

SALE NO. AU20220915001

LOT NO.

DESCRIPTION

1	QTY - 1	12 Chevrolet Express Van WH 8 cyl VIN: 1GCZGTCA2C1154362; Defects: Emissions, Frame Rusted, Missing Parts	ID 125386 OD 63359
2	QTY - 1	03 Chevrolet G30 Van BL 8 cyl AT PB R AC VIN: 1GBJG31U331191645; Defects: Body Damage, Engine	ID 035444 OD 73208
3	QTY - 1	16 Chevrolet Impala 4DSD WH 6 cyl (Flex Fuel) VIN: 2G1WD5E34G1146083; Defects: Body Damage, Catalytic Converter, Control Arms, Steering, Structural, Transmission	ID 161669 OD 106148
4	QTY - 1	14 Chevrolet Impala 4DSD WH 6 cyl (Flex Fuel) VIN: 2G1WD5E34E1187178; Defects: Control Arms, Exhaust, Steering, Structural	ID 143315 OD 100113
5	QTY - 1	95 Ford Ranger Pickup GR 4 cyl VIN: 1FTRC10AXSTA31002; Defects: Body Damage, Brakes, Cab Mounts, Clutch, Exhaust, Missing Parts	ID 954064 OD UNKN
6	QTY - 1	93 Ford Ranger Pickup PU 4 cyl VIN: 1FTRC10A1PTA93248; Defects: Battery, Engine, Frame Rotted Out, Interior Damage, Missing Parts, Tires/Wheels, Transmission	ID 934421 OD UNKN
7	QTY - 1	17 Ford Transit Subn WH 6 cyl VIN: 1FMZK1CM6HKB32312; Defects: Accident Damage, MV907A TO BE MAILED	ID AZ7805 OD 15315
8	QTY - 1	05 Ford Freestyle Subn GY 6 cyl AWD VIN: 1FMZK05115GA59975; Defects: **OPEN RECALL**, Frame Rotted Out, MV907A TO BE GIVEN	ID L92091 OD 116615
9	QTY - 1	15 Ford Focus 4DSD BL 4 cyl VIN: 1FADP3K20FL376434; Defects: Accident Damage, MV907A TO BE MAILED	ID AW9390 OD 80688
10	QTY - 1	96 Dodge Ram 2500 Pickup BL 8 cyl VIN: 1B7KF26Z5TJ176503; Defects: **OPEN RECALL**, Battery, Cab Mounts, Engine, Front End, Interior Damage, Rust Holes in Floor, Transmission	ID 965571 OD UNKN
11	QTY - 1	08 Dodge Dump YW 6 cyl Diesel VIN: 3D6WD66AX8G204081; Defects: Rust Holes in Floor, Transmission	ID 22300554V OD 106191
12	QTY - 1	11 Dodge Ram Utility YW 8 cyl VIN: 3D6WF4ET7BG574039; Defects: Engine, Frame Rusted	ID 22300155V OD 122138

SALE NO. AU20220915001

LOT NO.

DESCRIPTION

13	QTY - 1	07 Jeep Liberty Subn BL 6 cyl 4X4 VIN: 1J4GL48K97W685054; Defects: Body Damage, Engine, TITLE TO BE MAILED	ID 073546 OD 181646
14	QTY - 1	06 Sterling LT9 Tandem Dump YW 6 cyl Diesel, with Lot 40 VIN: 2FZHYZCV26AW91446; Defects: Engine, Exhaust, Frame Broken, Frame Cracked	ID 22300280V OD TMU
15	QTY - 1	13 International 760 Dump YW 6 cyl Diesel VIN: 1HTGRSJT6DJ183352; Defects: Body Damage, Fuel Leak	ID 22300238V OD 128497
16	QTY - 1	10 International 760 Dump YW 6 cyl Diesel VIN: 1HTWXSHT9AJ275283;	ID 22300272V OD 166194
17	QTY - 1	10 International 760 Dump YW 6 cyl Diesel VIN: 1HTWXAHT7AJ177671;	ID 22300277V OD 176321
18	QTY - 1	08 International 760 Dump YW 6 cyl Diesel VIN: 1HTWXAHTX8J645984;	ID 22300234V OD 189038
19	QTY - 1	08 International 760 Dump YW 6 cyl Diesel VIN: 1HTWXAHT48J645995; Defects: Body Damage, Interior Damage, Rust	ID 22300274V OD 184507
20	QTY - 1	06 International 760 Dump YW 6 cyl Diesel, ELP Hoist Cylinder Leaks VIN: 1HTWXAHT46J253841; Defects: Rust	ID 22300228V OD 186489
21	QTY - 1	06 International Stake Body YW 6 cyl Diesel VIN: 1HTWAAAN86J253824; Defects: Rust	ID 22300232V OD 173262
22	QTY - 1	08 Chevrolet Uplander GY 6 cyl VIN: 1GN DV23W78D182452; Defects: Brakes, Frame Rotted Out, Missing Parts, Transmission	ID 081651 OD 46005
23	QTY - 1	08 Chevrolet Uplander GY 6 cyl VIN: 1GN DV23W18D182690; Defects: Frame Rotted Out, Missing Parts, Structural	ID 081647 OD 48958
24	QTY - 1	04 Dodge Ram 2500 Pickup BL 8 cyl 4X4 VIN: 3D7KU26D24G256750; Defects: Body Damage, Engine, TITLE TO BE MAILED	ID 045236 OD 25287

SALE NO. AU20220915001

LOT NO.		DESCRIPTION	
25	QTY - 1	Miller Challenger 172 MIG Welder Defects: Needs Repair	
26	QTY - 1	Marathon Tack Coat Sprayer S/N NYS47	ID 009288
27	QTY - 1	Lot of (1) 98 Stihl 026 18" Chainsaw Defects: Low Compression 22-30-0394E (1) 19 MS 251 18" Chainsaw Defects: Burnt Hole in Piston 22-30-0395E (1) 08 Stihl KM130R Pole Saw Defects: Low Compression 22-30-0541E	
28	QTY - 1	Lot of (9) Pelican Cases	ID 21300269X
29	QTY - 1	Lot of (2) Driver Heavy Duty Post with 4 1/2" Master Chuck Rhino PD-140	ID 20300034X
30	QTY - 1	OTC 10 Ton Floor Jack Defects: Needs Repair	
31	QTY - 1	Approximately 12-15 Miscellaneous "D" Blocks	ID 3254
32	QTY - 1	06 JD JS20 Push Mower Defects: Needs Deck Replaced	ID 22300396E
33	QTY - 1	01 Honda Harmony II 21" Mower Defects: Engine Vibrates, Bent Crank	ID 22300397E
34	QTY - 1	I/R Portable Compressor	ID 129108
35	QTY - 1	Tool for Removing and Replacing Brake Drums and Hubs	ID 22300180R
36	QTY - 1	Diesel Injection Cleaner	
37	QTY - 1	3 Daytona Torpedo Heater, 175,000 BTU	ID 3253
38	QTY - 1	04 Craftsman Snow Blower S/N 536885202	ID 22300427E

SALE NO. AU20220915001

LOT NO.		DESCRIPTION	ID
39	QTY - 1	Garmin GPS Unit Auto Routing, Color GPS and Sensors with Navigation Kit	20300035X
40	QTY - 1	1995 Henderson NYTW94-9-9Y Spreader Defects: Unit is Siezed to Truck, can not be Removed 22-30-0280-V Sold With Lot14	22300281E
41	QTY - 1	Buyers SPE2000X Spreader	109000
42	QTY - 1	Lot of Used Parts	
43	QTY - 1	Lot of Approximately (56) Various Wiper Blades	22300181R
44	QTY - 1	4 Navistar Radiators Fit 7600	
45	QTY - 1	Miscellaneous Hydraulic Tools	
46	QTY - 1	Terex Arrow Board S/N EKD07135	048546
47	QTY - 1	Amida Arrow Board S/N EKD07140	068539
48	QTY - 1	John Deere TRS32 Snowblower	3251
49	QTY - 1	Bobcat Bucket	3252
50	QTY - 1	04 Viking PRRL1148FE 11" Rev	22300231E
51	QTY - 1	22/35 Ton Truck Jack LP-SY17-1851 Defects: Rust	19301407X
52	QTY - 1	2001 JD 6410 Tractor, Diesel/Biodiesel, HR: 4146 Defects: Rail Cutting Head has Cracks, Jib Boom is Bent S/N LO6410P305787	22300283E

SALE NO. AU20220915001

LOT NO.	DESCRIPTION	ID
53	QTY - 1 99 WAP WAAW15SB Arrowboard	22300558E
54	QTY - 1 01 VERMAC ST-4815 Solar Arrowboard	22300557E
55	QTY - 1 01 Vermac ST-4815 Solar Arrowboard	22300556E
56	QTY - 1 06 Viking 144WHD 12" RH Wing	22300282E
57	QTY - 1 2010 Viking 144WHD 12" Righthand Wing Plow	22300278E
58	QTY - 1 08 Viking 144WHD 12" LH Wing	22300276E
59	QTY - 1 08 Viking 144 WHD 12" RH Wing	22300275E
60	QTY - 1 2010 Viking 144WHD 12" Righthand Wing Plow	22300273E
61	QTY - 1 95 Henderson NYTW94-9 10Y Spreader	22300271E
62	QTY - 1 08 Viking 144WHD 12" LH Wing	22300237E
63	QTY - 1 2010 Viking 144 WHD 12" Righthand Wing Plow	22300236E
64	QTY - 1 04 Viking PRRL1148FE 11" REV	22300235E
65	QTY - 1 2018 Viking PRRL1148FE 11" REV Defects: Push Frame Twisted, Mold Board Bent	22300233E
66	QTY - 1 03 Viking PRRL1148FE 11" REV	22300230E
67	QTY - 1 00 Viking 144WHD 12" RH Wing	22300229E

SALE NO. AU20220915001

LOT NO.		DESCRIPTION	
68	QTY - 1	06 Viking 144WHD 12' LH Wing	ID 22300196E
69	QTY - 1	2007 Pequea Dump Trailer, BK S/N 4JADT50857G114689	ID 078923
70	QTY - 1	2005 BRI-MAR Dump Trailer, BK S/N 43YDC102X5C042016	ID 058001
71	QTY - 1	Lot of Approximately (1235) Mower Parts S/N 22300157R	
72	QTY - 1	Lot of approx. (6) Horizontal and Vertical CNG Tanks with Valves, Piping, Storage Tanks, Filter Assembly, Plumbing, Scaffolding, Compressor, Enclosure, and Fuel Dispenser *INSURANCE REQUIREMENTS NEED TO BE MET*	

LEGEND

AT = AUTOMATIC TRANSMISSION

ST = STANDARD TRANSMISSION

PB = POWER BRAKES

PS = POWER STEERING

TMU = TRUE MILEAGE UNKNOWN

OD = MILEAGE INDICATED ON ODOMETER, INCLUDING EXCESS OF 100,000 IF KNOWN

PW = POWER WINDOWS

AC = AIR CONDITIONING

CC = CRUISE CONTROL

R = RADIO