

SALE NO. AU20220518001

LOT NO.

DESCRIPTION

1	QTY - 1	01 Chevrolet G3500 Express Van WH 8 cyl VIN: 1GCHG39R511213426; Defects: Body Damage, Engine, Exhaust, Rust, Structural	ID AW5600 OD 52560
2	QTY - 1	07 Ford F650 Stake Body YW 6 cyl Diesel VIN: 3FRNW66A77V486849; Defects: Exhaust, FOR PARTS VALUE ONLY, Fuel Tank, Hole Cut in Engine Block, MV907A TO BE GIVEN, Oil Pan, Rust, Transmission Leak	ID 075281 OD 194853
3	QTY - 1	02 GEM E825 Lsv GY (Electric) VIN: 5ASAG47432F030525; Defects: **OD DISCREPANCY**, **OPEN RECALL**, Batteries, Body Damage, Missing Parts, Rust, Structural, Tires/Wheels	ID 10068LS OD UNKN
4	QTY - 1	02 GEM LSV Lsv RD (Electric) VIN: 5ASAG27422F030181; Defects: **OD DISCREPANCY**, **OPEN RECALL**, Batteries, Body Damage, Missing Parts, Rust, Structural, Tires/Wheels	ID 13352LU OD UNKN
5	QTY - 1	02 GEM LSV Lsv RD (Electric) VIN: 5ASAG274X2F027352; Defects: **OD DISCREPANCY**, **OPEN RECALL**, Batteries, Body Damage, Brakes, Missing Parts, Rust, Structural, Tires/Wheels	ID 13354U OD UNKN
6	QTY - 1	02 GEM LSV Lsv GY (Electric) VIN: 5ASAG47462F029899; Defects: **OD DISCREPANCY**, **OPEN RECALL**, Batteries, Body Damage, Missing Parts, Rust, Structural, Tires/Wheels	ID 13357LU OD UNKN
7	QTY - 1	02 GEM E825 Lsv RD (Electric) VIN: 5ASAG27442F030425; Defects: **OD DISCREPANCY**, **OPEN RECALL**, Batteries, Body Damage, Brakes, Missing Parts, Rust, Structural, Tires/Wheels	ID 13360LU OD UNKN
8	QTY - 1	02 GEM E825 Lsv GY (Electric) VIN: 5ASAG47492F029850; Defects: **OD DISCREPANCY**, **OPEN RECALL**, Batteries, Body Damage, Missing Parts, Rust, Structural, Tires/Wheels	ID 13351LU OD UNKN
9	QTY - 1	02 GEM E825 Lsv GY (Electric) VIN: 5ASAG47472F030088; Defects: **OD DISCREPANCY**, Batteries, Body Damage, Brakes, Missing Parts, Rust, Structural, Tires/Wheels	ID 18702LU OD UNKN
10	QTY - 1	08 Chevrolet Uplander Subn WH 6 cyl VIN: 1GN DV23128D146995; Defects: Body Damage, Rust	ID 083253 OD 87759

SALE NO. AU20220518001

LOT NO.		DESCRIPTION		
11	QTY - 1	12 Dodge Ram Van WH 6 cyl VIN: 2C4JDGAG0CR317851; Defects: Transmission	ID 125529 OD 140917	
12	QTY - 1	11 Chevrolet Silverado Pickup YW 8 cyl VIN: 1GC4CZCG1BF252412; Defects: Brakes, Engine, Missing Parts, Rust, Tires/Wheels	ID 115659 OD 252651	
13	QTY - 1	07 Ford F650 Dump YW 6 cyl Diesel VIN: 3FRNW65AX7V486832; Defects: FOR PARTS VALUE ONLY, Hole Cut in Engine Block, Missing Parts, MV907A TO BE GIVEN, Rust	ID 075239 OD 136049	
14	QTY - 1	07 Ford F650 Dump YW 6 cyl Diesel VIN: 3FRNW65A37V488664; Defects: FOR PARTS VALUE ONLY, Hole Cut in Engine Block, MV907A TO BE GIVEN, Rust	ID 075243 OD 125884	
15	QTY - 1	07 Ford F650 Dump YW 6 cyl Diesel VIN: 3FRPW65A97V488676; Defects: FOR PARTS VALUE ONLY, Hole Cut in Engine Block, MV907A TO BE GIVEN, Oil Pressure, Rust	ID 075246 OD 199178	
16	QTY - 1	11 Mack GU713 Dump YW 6 cyl Diesel Steer Gear Box Leak VIN: 1M2AX04CXBM009039; Defects: Body Rust, Brakes, Engine, Hydraulics	ID 115095 OD 117050	
17	QTY - 1	09 Mack GU713 Dump YW 6 cyl Diesel VIN: 1M2AX04C99M004182; Defects: A/C Not Working, Body Rust, Conveyor, Electrical, Hydraulics, Lights, Rust, Tires/Wheels, Transaxle/Diffmtl	ID 095104 OD 144850	
18	QTY - 1	09 Mack GU713 Dump YW 6 cyl Diesel VIN: 1M2AX04C29M004184; Defects: Body Rust, Engine Light, Exhaust, Lights	ID 095105 OD 126457	
19	QTY - 1	03 International 4200 Van RD 8 cyl VIN: 1HTMPAFM83H585464; Defects: Frame Rusted	ID 035119 OD 21808	
20	QTY - 1	08 Ford F350 Stake Body YW 8 cyl Diesel VIN: 1FDWF37R78EC71680; Defects: Body Rust, Front End, Rust	ID 085332 OD 131850	
21	QTY - 1	08 Ford F350 Pickup YW 8 cyl Diesel VIN: 1FDWF34R58EC71648; Defects: Body Rust, Fuel Tank, Heater Core, Missing Parts, Pinion Seal	ID 085319 OD 101400	

SALE NO. AU20220518001

LOT NO.		DESCRIPTION	
22	QTY - 1	11 Chevrolet Silverado Pickup YW 8 cyl VIN: 1GC4CZCG9BF252433; Defects: Accident Damage, Front End, Steering	ID 115665 OD 204321
23	QTY - 1	13 Ford F250 Pickup YW 8 cyl VIN: 1FTBF2A6XDEB37817; Defects: Engine, Rust	ID 135400 OD 181089
24	QTY - 1	11 Ford F250 Pickup YW 8 cyl Box supports rotted off VIN: 1FTBF2A65BEB48446; Defects: Exhaust, Rust	ID 115372 OD 158117
25	QTY - 1	08 Dodge Durango WH 8 cyl VIN: 1D8HB38N88F152035; Defects: Battery, Body Damage, Brakes, Engine, Frame Rotted Out, Rust	ID AY6152 OD 136541
26	QTY - 1	11 Mack GU713 Dump YW 6 cyl Diesel Dump Box Issue VIN: 1M2AX04C5BM008980; Defects: Body Rust, Engine Light, Hydraulics, Lights, Oil Leak, Structural	ID 115089 OD 160301
27	QTY - 1	11 Mack GU713 Dump YW 6 cyl Diesel Pivot Pin Siezed VIN: 1M2AX04C6BM009037; Defects: Body Rust, Transmission, Transmission Leak	ID 115093 OD 125641
28	QTY - 1	11 Mack GU713 Dump YW 6 cyl Diesel Broken Rear Spring VIN: 1M2AX04C8BM009038; Defects: Body Rust, Crank Seal, Engine, Oil Leak, Oil Pan, Radiator	ID 115094 OD 168996
29	QTY - 1	11 Mack GU713 Dump YW 6 cyl Diesel Rear Axles Leaking VIN: 1M2AX04C8M009041; Defects: A/C Not Working, Axle, Body Rust, Exhaust, Windshield	ID 115097 OD 137037
30	QTY - 1	11 Mack GU713 Dump YW 6 cyl Diesel VIN: 1M2AX04CXBM009042; Defects: A/C Not Working, Body Rust, Emissions, Injectors, Missing Door, Suspension	ID 115098 OD 115409
31	QTY - 1	11 Mack GU713 Dump YW 6 cyl Diesel VIN: 1M2AX04C9BM009016; Defects: Air Bags, Brakes, Frame Rotted Out, Radiator, Suspension, Transfer Case	ID 115131 OD 146726
32	QTY - 1	09 Mack GU713 Dump YW 6 cyl Diesel VIN: 1M2AX04C29M006968; Defects: ABS Light, Body Rust, Exhaust, Steering, Transmission	ID 095287 OD 197188

SALE NO. AU20220518001

LOT NO.

DESCRIPTION

33	QTY - 1	01 International 470 Stake Body YW 8 cyl Diesel VIN: 1HTSCABM11H332881; Defects: Body Damage, Brakes, FOR PARTS VALUE ONLY, Hole Cut in Engine Block, MV907A TO BE GIVEN, Rust	ID 005673 OD 55417
34	QTY - 1	86 International S1654 YW 8 cyl No Bed, Diesel VIN: 1HTLAHEL3GHA30350; Defects: FOR PARTS VALUE ONLY, Hole Cut in Engine Block, NO REG. DOCUMENTS, NO TITLE, Rust	ID 865306 OD 73739
35	QTY - 1	86 International Chassis YW 8 cyl VIN: 1HTLAHEL3GHA30350; Defects: NO REG. DOCUMENTS, NO TITLE, Rust	ID 865306 ** CANCELLED **
36	QTY - 1	Hein-Warner Wheel Dolly Defects: missing jack	
37	QTY - 1	Worm Drive Skill Saw in Metal Box	
38	QTY - 1	(2) Pallets of Hydraulic Fittings, Hose and Crimp Tools	
39	QTY - 1	Weaver, Model W-937 Tire Balancer S/N 912050836	
40	QTY - 1	Onan Generator, Model 7NHMFA26105F S/N 953463232	** CANCELLED **
41	QTY - 1	Rockwell Circular Saw in metal Box	
42	QTY - 1	Porter Cable Jig Saw in Metal Box	
43	QTY - 1	Rockwell 3/4inch Electric Drill	
44	QTY - 1	Lot of (2) 55 Gallon Drums of 5W20 Motor Oil	
45	QTY - 1	Homelite HMLTE, Model EH4400HD Gen AC 30/40 K S/N HN1570567	
46	QTY - 1	Champion, Model BD362961 60 gallon Air Compressor	

SALE NO. AU20220518001

LOT NO.	DESCRIPTION
47	QTY - 1 Military 60 gallon Air Compressor S/N 156732
48	QTY - 1 Curtis 60 Gallon Air Compressor S/N 8529897
49	QTY - 1 Arbor Press
50	QTY - 1 Leroi, Model Q175 Comp 161/185CFM S/N 3271X102
51	QTY - 1 Miscellaneous Box of Sweeper Broom Refills
52	QTY - 1 Airflomfg, Model PSV8ESS Spreader Material Small; Defects: Engine S/N 18423
53	QTY - 1 Buyers Material, Model SHPE2000 Spreader 2CUYD S/N 1652
54	QTY - 1 Buyers Material Spreader, Model SHPE2000 2CUYD S/N 1655
55	QTY - 1 John Deere, Model X475 Mower SM Trac To 30; Defects: Engine S/N MOX475A012554
56	QTY - 1 Hydraulic Tank with Electric Pump
57	QTY - 1 (2) Pallets of Miscellaneous used Older Parts
58	QTY - 1 Toro 30789 Mower RD 4 cyl. Gas Defects: Unknown Hours, Rust, Body Damage, Engine, Brakes, Battery S/N 80344
59	QTY - 1 Toro Wheel Horse Riding Mower RD 2 cyl. Gas Defects: Unknown Hours, Body Damage, Engine, Tires
60	QTY - 1 13 Jacobsen GKIV Riding Greens Mower OR Gas (Hours: ID C13002 797) Defects: Accident Damage, Engine, Hydraulics, Frame, Electrical System, Missing Mowing Reels S/N 6230602248

SALE NO. AU20220518001

LOT NO.		DESCRIPTION	ID
61	QTY - 1	05 Toro GM 3100 Riding Greens Mower RD 18HP Gas (Hours: 3950) Defects: Electrical, Frame, Hydraulics, Missing Mowing Reels S/N 250000397	C05008
62	QTY - 1	02 Jacobsen GKIV Riding Greens Mower OR 2 cyl. Gas (Hours:1794) Defects: Seat Body Panels, Hydraulics, Electrical, Engine, Missing Reels S/N 94671400406	C02013
63	QTY - 1	02 Tuff Pressure Washer RD Electric/Diesel Defects: Electrical, Burner	
64	QTY - 1	09 Eride LSVT Cart WH 0 cyl. Electric Defects: Unknown Hours, Batteries, Tires, Brakes, Body Damage, Rust S/N 1E9EA15S79P363354	AY3688
65	QTY - 1	Onan 6.8KW Marquis 7000 Generator Model 7NHMFA26105F Skid Mounted S/N L953463232	
66	QTY - 1	Tarp System For Medium Duty Dump Truck	** CANCELLED **
67	QTY - 1	09 Lely H Spreader RD S/N 2320115056241	F09016
68	QTY - 1	97 Turfco MeterMatic Spreader Top Dresser BR Defects: Drive Chain, Wheels S/N 298860	F17181
69	QTY - 1	Fisher 8ft. Snow Plow Minute Mount No truck mount/controls	
70	QTY - 1	Truck Cap Manuf. ARE Fiberglass off of Ford Pickup	
71	QTY - 1	Repaired 90 Gallon Mack Fuel Tank	
72	QTY - 1	Lot of (2) Fisher 10Ft. Snow Plows Minute Mount No truck mount/controls	
73	QTY - 1	Case, Model MK2K TRK Forklift 5M/6M L Defects; No Title, No Reg. S/N 16960	
74	QTY - 1	HIVU, Model TM4815SD Arrowboard Trail; Defects: Engine S/N 58223000363	

SALE NO. AU20220518001

LOT NO.	DESCRIPTION	
75	QTY - 1 Case, Model 4210 Trac Right/Rear MTD; No Reg, No Docs.Defects: Steering, Missing Parts S/N JJE0909323	
76	QTY - 1 Safestop TRK MTD Attn Safe Stop, Model 8291, Defects: Parts Only S/N 2853280011	
77	QTY - 1 Brush Hog, Model 406 S/N 1211056	
78	QTY - 1 84 John Deere 950 Tractor GR 3 cyl. Gas Plow, Bush Hog (Hours: 2704.9) (No Reg Docs) Defects: Battery, Brakes, Rust, Rot Body Damage, Broken Window S/N CH0950S020305	ID AK1314
79	QTY - 1 Bobcat 811 Backhoe Attachment WH/GY Defects: Rust, Body Damage S/N 630002291	
80	QTY - 1 02 New Holland Backhoe/Load Tractor Attachment BL Defects: Hydraulics, Pins, Bucket S/N 751481	ID C02012
81	QTY - 1 Toro Groundsmaster 345 Unit RD 3 cyl. (Hours: 2110.6) Gas Defects: Body Damage, Engine, Battery, Tires, Missing Front Attachment S/N 230000145	
82	QTY - 1 Toro Groundsmaster 345 Mower with Snow Brush RD 3 cyl. Gas (Hours: 2869.5) Defects: Body Damage, Engine, Battery, Tires S/N 60367	
83	QTY - 1 Melroe Sweeper 72 Sweeper Attachment GY Defects: Rust, Body Damage, Hydraulic Lines S/N 783701968	
84	QTY - 1 2019 Gregory, Model TTMA200 Attenuator Trailer S/N 4S93A241XKH089045	
85	QTY - 1 Lot of Approximately (2000) 5/8x4 inch Plow Bolts	
86	QTY - 1 2010 Wanco Arrow Board, Model WTSP55LSA Defects: Accident Damage, Frame and Arrow Boards are Damaged, Missing all Lights S/N 5F11S1013A1000730	ID 108506
87	QTY - 1 Safstop, Model 8290LC Impact Attenuator Defects: Parts Only S/N SSII830	

SALE NO. AU20220518001

LOT NO.

DESCRIPTION

88	QTY - 1	Grove Model IND36 Crane wheel MTD 3T Defects; No Title, No Reg. S/N 33907	
89	QTY - 1	Weaver, Model W-893 Tire Machine S/N 812051631	
90	QTY - 1	05 Chevrolet Express Van WH 6 cyl VIN: 1GCFG15X951150515; Defects: Body Damage, Frame Rotted Out, Rust, Structural	ID AZ8046 OD 187213
91	QTY - 1	07 GEM G82 Lsv GR (Electric) VIN: 5ASAG47447F043128; Defects: **OD DISCREPANCY**, **OPEN RECALL**, Battery, Body Damage, Brakes, Missing Parts, Rust, Structural, Tires/Wheels	ID 21865LU OD UNKN
92	QTY - 1	06 GEM G82 Lsv WH (Electric) VIN: 5ASAK274X6F039683; Defects: **OD DISCREPANCY**, **OPEN RECALL**, Batteries, Body Damage, Missing Parts, Rust, Structural	ID 21877LU OD UNKN
93	QTY - 1	06 GEM G82 Lsv WH (Electric) VIN: 5ASAK27456F039686; Defects: **OD DISCREPANCY**, **OPEN RECALL**, Batteries, Body Damage, Missing Parts, Structural, Tires/Wheels	ID 21879LU OD UNKN
94	QTY - 1	06 GEM G82 Lsv WH (Electric) VIN: 5ASAK27416F039703; Defects: **OD DISCREPANCY**, **OPEN RECALL**, Batteries, Body Damage, Missing Parts, Rust, Structural, Tires/Wheels	ID 21882LU OD UNKN
95	QTY - 1	06 GEM G82 Lsv WH (Electric) VIN: 5ASAK27456F039705; Defects: **OD DISCREPANCY**, **OPEN RECALL**, Batteries, Body Damage, Missing Parts, Structural, Tires/Wheels	ID 21883LU OD UNKN
96	QTY - 1	06 GEM G82 Lsv WH (Electric) VIN: 5ASAK27426F039709; Defects: **OD DISCREPANCY**, **OPEN RECALL**, Batteries, Body Damage, Brakes, Missing Parts, Rust, Structural, Tires/Wheels	ID 21885LU OD UNKN
97	QTY - 1	98 New Holland CA6 Tractor BL 3 cyl. Diesel No Reg Docs Defects: Hours Meter, Rust, Rot, Body Damage, Brakes, Tires, Engine, Transmission S/N 102972B	ID AK1337

SALE NO. AU20220518001

LOT NO.

DESCRIPTION

98	QTY - 1	98 New Holland CA6 Tractor BL 3 cyl. Diesel Front Mount Brush (Hours: 1764.5) No Reg Docs Defects: Rust, Rot, Body Damage, Brakes, Tires, Engine, Transmission S/N 102452B	
99	QTY - 1	04 International 4200 Van WH 8 cyl (Diesel) VIN: 1HTMPAFM14H656554; Defects: Body Rust, Electrical, Engine, FOR PARTS VALUE ONLY, Hole Cut in Engine Block, MV907A TO BE GIVEN	ID AB9865 OD 10364
100	QTY - 1	Lot of (2) Fifth Wheel Risers	
101	QTY - 1	2000 Dakota TurfTender 410 Spreader Top Dresser Defects: Engine, Hydraulics, Conveyor Belt	ID C00016
102	QTY - 1	Military Surplus A/C Unit KECO F9000H-1SA	ID 901068
103	QTY - 1	Military Surplus A/C Unit KECO F9000H-1SA	ID 90746

LEGEND

AT = AUTOMATIC TRANSMISSION

ST = STANDARD TRANSMISSION

PB = POWER BRAKES

PS = POWER STEERING

TMU = TRUE MILEAGE UNKNOWN

OD = MILEAGE INDICATED ON ODOMETER, INCLUDING EXCESS OF 100,000 IF KNOWN

PW = POWER WINDOWS

AC = AIR CONDITIONING

CC = CRUISE CONTROL

R = RADIO