

SALE NO. AU20220318001

LOT NO.

DESCRIPTION

|   |         |   |                        |
|---|---------|---|------------------------|
| 1 | QTY - 1 | 13 Chevrolet G1500 Express Van BL 8 cyl Whlchr AT PB PS R AC PW<br>VIN: 1GBZG1FA9D1187221; Defects: **OPEN RECALL**, Accident Damage, Exterior and Interior DMG, Frame Rusted, Missing Parts                | ID 131174<br>OD UNKN   |
| 2 | QTY - 1 | 11 Chevrolet G3500 Express Van GY 8 cyl AT PB PS R AC PW<br>VIN: 1GCZGUCAXB1166912; Defects: **OPEN RECALL**, Accident Damage, Exterior and Interior DMG, Frame, Frame Rusted, Missing Parts                | ID 115839<br>OD UNKN   |
| 3 | QTY - 1 | 06 Chevrolet Express Van RD 8 cyl Wheelchair Conversion AT PB PS R AC PW<br>VIN: 1GBHG39U661205609; Defects: Accident Damage, Exterior and Interior DMG, Frame Rusted, Missing Parts, Open Recall           | ID 061167<br>OD 102359 |
| 4 | QTY - 1 | 05 Chevrolet Express Van BL 8 cyl Wheelchair Conversion AT PB PS R AC PW<br>VIN: 1GBHG39U551217247; Defects: Exterior and Interior DMG, Frame Rusted, Missing Parts   | ID 051339<br>OD 107639 |
| 5 | QTY - 1 | 04 Chevrolet Express Van RD 8 cyl Wheelchair Conversion AT PB PS R AC PW<br>VIN: 1GBHG39U241247885; Defects: Exterior and Interior DMG, Frame Rotted Out, Missing Catalytic Convert, Missing Parts          | ID 041329<br>OD 119950 |
| 6 | QTY - 1 | 04 Chevrolet G3500 Express Van GR 8 cyl AT PB PS R AC PW<br>VIN: 1GBHG39U441234748; Defects: Exterior and Interior DMG, Frame Rusted, Missing Catalytic Convert, Missing Parts                              | ID 041316<br>OD 183726 |
| 7 | QTY - 1 | 03 Chevrolet G3500 Express Van WH 8 cyl Whlchr AT PB PS R AC PW<br>VIN: 1GBJG31UX31219070; Defects: Exterior and Interior DMG, Frame Rusted, Glass Damage, Lights, Missing Catalytic Convert, Missing Parts | ID 035228<br>OD 59808  |
| 8 | QTY - 1 | 09 Chevrolet Express Subn BL 8 cyl No Start AT PB PS R AC PW<br>VIN: 1GAGG25K791165303; Defects: Engine, Exterior and Interior DMG, Frame Rusted, Glass Damage, Lights, Missing Parts                       | ID 091154<br>OD 168698 |
| 9 | QTY - 1 | 08 Chevrolet Express Subn GY 8 cyl AT PB PS R AC PW<br>VIN: 1GBHG39K681230429; Defects: Accident Damage, Exterior and Interior DMG, Frame Rusted, Missing Doors, Missing Parts                              | ID 081499<br>OD 93129  |

SALE NO. AU20220318001

LOT NO.

DESCRIPTION

|    |         |   |                              |
|----|---------|---|------------------------------|
| 10 | QTY - 1 | 08 Chevrolet Uplander Subn GY 6 cyl AT PB PS R AC PW<br>VIN: 1GNDV23W58D184670; Defects: Exterior and Interior<br>DMG, Frame Rusted, Missing Parts  | ID 081431<br>OD 200533       |
| 11 | QTY - 1 | 08 Chevrolet Uplander Subn RD 6 cyl AT PB AC PW<br>VIN: 1GNDV23W68D184516; Defects: Body Damage,<br>Frame Rotted Out, Missing Parts, Undercarriage Rust   | ID 081428<br>** CANCELLED ** |
| 12 | QTY - 1 | 08 Chevrolet Uplander Subn RD 6 cyl AT PB PS R AC PW<br>VIN: 1GNDV23W68D184516; Defects: Body Damage,<br>Frame Rotted Out, Missing Parts, Undercarriage Rust  | ID 081428<br>OD 151718       |
| 13 | QTY - 1 | 07 Chevrolet Express Subn GY 8 cyl AT PB PS R AC PW<br>VIN: 1GAGG25U071205509; Defects: Exterior and Interior<br>DMG, Frame Rusted, Glass Damage, Lights, Missing<br>Catalytic Convert, Missing Parts           | ID 071540<br>OD 116130       |
| 14 | QTY - 1 | 07 Chevrolet Uplander Subn BL 6 cyl AT PB PS R AC PW<br>VIN: 1GNDV23W77D180960; Defects: Exterior and Interior<br>DMG, Frame Rusted, Missing Catalytic Convert, Missing<br>Parts                                | ID 071739<br>OD 123902       |
| 15 | QTY - 1 | 06 Chevrolet Express Subn BL 8 cyl AT PB PS R AC PW<br>VIN: 1GAGG25UX61210277; Defects: Body Damage, Frame<br>Rotted Out, Glass Damage, Lights, Missing Catalytic Convert,<br>Missing Parts                     | ID 061529<br>OD 225331       |
| 16 | QTY - 1 | 06 Chevrolet Express Subn RD 8 cyl AT PB PS R AC PW<br>VIN: 1GAGG25U761207577; Defects: Body Damage, Frame<br>Rotted Out, Missing Doors, Missing Parts, Missing Seat  | ID 061061<br>OD 113277       |
| 17 | QTY - 1 | 06 Chevrolet Express Subn BL 8 cyl AT PB PS R AC PW<br>VIN: 1GAGG25U161208000; Defects: Body Damage, Frame<br>Rotted Out, Glass Damage, Lights, Missing Catalytic Convert,<br>Missing Parts                     | ID 061063<br>OD 197428       |
| 18 | QTY - 1 | 06 Chevrolet Express Subn RD 8 cyl AT PB PS R AC PW<br>VIN: 1GAHG39U061208509; Defects: Body Damage, Brake<br>Lines, Brakes, Catalytic Converter, Frame Rotted Out,<br>Missing Parts, Undercarriage Rust        | ID 061097<br>OD 171301       |
| 19 | QTY - 1 | 05 Chevrolet Express Subn GY 8 cyl AT PB PS R AC PW<br>VIN: 1GAGG25U151198289; Defects: Body Damage, Frame<br>Rotted Out, Glass Damage, Lights, Missing Catalytic Convert,<br>Missing Parts, Undercarriage Rust | ID 051285<br>OD 111604       |
| 20 | QTY - 1 | 05 Chevrolet Express Subn GR 8 cyl AT PB PS R AC PW<br>VIN: 1GAGG25U751199639; Defects: Body Damage, Frame<br>Rotted Out, Glass Damage, Lights, Missing Parts   | ID 051289<br>OD 122002       |

SALE NO. AU20220318001

| LOT NO. |         | DESCRIPTION   |                        |  |
|---------|---------|---|------------------------|--|
| 21      | QTY - 1 | 05 Chevrolet Express Subn GY 8 cyl AT PB PS R AC PW<br>VIN: 1GAGG25U051199756; Defects: Body Damage, Frame Rotted Out, Glass Damage, Lights, Missing Keys, Missing Parts                                  | ID 051294<br>OD 224800 |  |
| 22      | QTY - 1 | 05 Chevrolet Express Subn GY 6 cyl AT PB PS R AC PW<br>VIN: 1GNFG15X251210142; Defects: Body Damage, Frame Rusted, Glass Damage, Missing Parts  | ID 051224<br>OD 217739 |  |
| 23      | QTY - 1 | 05 Chevrolet Express Subn GY 8 cyl AT PB PS R AC PW<br>VIN: 1GNFG15X251209749; Defects: Body Damage, Frame Rusted, Missing Keys, Missing Parts  | ID 051226<br>OD 252965 |  |
| 24      | QTY - 1 | 05 Chevrolet Express Subn BL 8 cyl AT PB PS R AC PW<br>VIN: 1GAHG39U251205433; Defects: Body Damage, Frame Rotted Out, Glass Damage, Lights, Missing Catalytic Convert, Missing Parts, Undercarriage Rust | ID 051244<br>OD 142907 |  |
| 25      | QTY - 1 | 05 Chevrolet Express Subn GY 8 cyl AT PB PS R AC PW<br>VIN: 1GAGG25U151204639; Defects: Body Damage, Frame Rotted Out, Glass Damage, Lights, Missing Parts, Undercarriage Rust                            | ID 051295<br>OD 179559 |  |
| 26      | QTY - 1 | 05 Chevrolet Express Subn BL 8 cyl Wheelchair Conversion AT PB PS R AC PW<br>VIN: 1GBHG39U851216402; Defects: Body Damage, Frame Rotted Out, Missing Keys, Missing Parts, Undercarriage Rust              | ID 051340<br>OD 120208 |  |
| 27      | QTY - 1 | 05 Chevrolet Astro Subn GY 6 cyl AT PB PS R AC PW<br>VIN: 1GNEL19X45B129445; Defects: Body Damage, Engine, Frame Rotted Out, Glass Damage, Lights, Missing Parts, Undercarriage Rust                      | ID 051383<br>OD 150844 |  |
| 28      | QTY - 1 | 05 Chevrolet Astro Subn WH 6 cyl AT PB PS R AC PW<br>VIN: 1GNEL19X75B129567; Defects: Body Damage, Frame Rotted Out, Missing Parts, Undercarriage Rust  | ID 051387<br>OD 143878 |  |
| 29      | QTY - 1 | 05 Chevrolet Astro Subn WH 6 cyl AT PB PS R AC PW<br>VIN: 1GNEL19X85B129383; Defects: Body Damage, Frame Rotted Out, Glass Damage, Missing Parts, Undercarriage Rust                                      | ID 051388<br>OD 158729 |  |
| 30      | QTY - 1 | 04 Chevrolet G3500 Express Subn RD 8 cyl AT PB PS R AC PW<br>VIN: 1GAHG39U141247705; Defects: Body Damage, Frame Rusted, Glass Damage, Lights, Missing Catalytic Convert, Missing Parts                   | ID 041117<br>OD 157981 |  |

SALE NO. AU20220318001

| LOT NO. |         | DESCRIPTION  |                              |  |
|---------|---------|--|------------------------------|--|
| 31      | QTY - 1 | 04 Chevrolet Astro Subn TN 6 cyl AT PB PS R AC PW<br>VIN: 1GNEL19X04B129070; Defects: Body Damage, Frame Rusted, Missing Parts   | ID 041181<br>OD 165079       |  |
| 32      | QTY - 1 | 04 Chevrolet Astro Subn TN 6 cyl AT PB PS R AC PW<br>VIN: 1GNEL19X14B129403; Defects: Body Damage, Frame Rusted, Missing Parts   | ID 041184<br>OD 151954       |  |
| 33      | QTY - 1 | 04 Chevrolet Astro Subn RD 6 cyl AT PB PS R AC PW<br>VIN: 1GNEL19X94B129794; Defects: Body Damage, Frame Rusted, Missing Parts, Undercarriage Rust                               | ID 041187<br>OD 134370       |  |
| 34      | QTY - 1 | 04 Chevrolet G3500 Express Subn BL 8 cyl AT PB PS R AC PW<br>VIN: 1GAHG39U441236911; Defects: Body Damage, Frame Rusted, Glass Damage, Lights, Missing Parts, Undercarriage Rust | ID 0441114<br>OD 184676      |  |
| 35      | QTY - 1 | 04 Chevrolet Astro Subn RD 8 cyl AT PB PS R AC PW<br>VIN: 1GNEL19X84B129088; Defects: Body Damage, Frame Rusted, Missing Parts, Undercarriage Rust                               | ID 041176<br>OD 137734       |  |
| 36      | QTY - 1 | 04 Chevrolet Astro Subn TN 6 cyl AT PB PS R AC PW<br>VIN: 1GNEL19X84B129060; Defects: Body Damage, Body Rust, Frame Rusted, Missing Parts, Undercarriage Rust                    | ID 041177<br>OD 153947       |  |
| 37      | QTY - 1 | 04 Chevrolet Astro Subn RD 6 cyl AT PB PS R AC PW<br>VIN: 1GNEL19X94B129097; Defects: Body Damage, Frame Rusted, Missing Parts, Transfer Case, Undercarriage Rust                | ID 041180<br>OD 110194       |  |
| 38      | QTY - 1 | 04 Chevrolet Astro Subn RD 6 cyl AT PB PS R AC PW<br>VIN: 1GNEL19X94B129620; Defects: Body Damage, Frame Rusted, Glass Damage, Missing Parts, Undercarriage Rust                 | ID 041191<br>OD 175656       |  |
| 39      | QTY - 1 | 04 Chevrolet Astro Subn RD 6 cyl MOVE TO ROCHESTER 6/15/22 AT PB PS R AC PW<br>VIN: 1GNEL19X04B129277;   | ID 041198<br>** CANCELLED ** |  |
| 40      | QTY - 1 | 04 Chevrolet Astro Subn RD 6 cyl AT PB PS R AC PW<br>VIN: 1GNEL19XX4B129206; Defects: Body Damage, Frame Rusted, Missing Parts, Undercarriage Rust                               | ID 041200<br>OD 170896       |  |
| 41      | QTY - 1 | 04 Chevrolet Astro Subn TN 6 cyl AT PB PS R AC PW<br>VIN: 1GNEL19X84B129169; Defects: Body Damage, Frame, Frame Rotted Out, Missing Parts, Undercarriage Rust                    | ID 041194<br>OD 177224       |  |

SALE NO. AU20220318001

LOT NO.

DESCRIPTION

|    |         |   |                        |
|----|---------|---|------------------------|
| 42 | QTY - 1 | 03 Chevrolet Astro Subn GY 6 cyl AT PB PS R AC PW<br>VIN: 1GNEL19X63B143067; Defects: Body Damage, Frame Rusted, Glass Damage, Lights, Missing Parts, Undercarriage Rust                            | ID 031542<br>OD UNKN   |
| 43 | QTY - 1 | 03 Chevrolet Astro Subn WH 6 cyl AT PB PS R AC PW<br>VIN: 1GNEL19X33B143186; Defects: Body Damage, Frame Rusted, Glass Damage, Lights, Missing Catalytic Convert, Missing Parts, Undercarriage Rust | ID 031538<br>OD 168706 |
| 44 | QTY - 1 | 03 Chevrolet G3500 Express Subn GR 8 cyl AT PB PS R AC PW<br>VIN: 1GAHG39U431219959; Defects: Body Damage, Frame Rusted, Missing Parts, Undercarriage Rust  | ID 031472<br>OD 189168 |
| 45 | QTY - 1 | 03 Chevrolet Astro Subn WH 6 cyl AT PB PS R AC PW<br>VIN: 1GNEL19X73B142929; Defects: Body Damage, Frame Rusted, Glass Damage, Lights, Missing Parts, Undercarriage Rust                            | ID 031536<br>OD 142086 |
| 46 | QTY - 1 | 03 Chevrolet G3500 Express Subn GY 8 cyl AT PB PS R AC PW<br>VIN: 1GAHG35U731226023; Defects: Body Damage, Frame Rusted, Glass Damage, Lights, Missing Keys, Missing Parts, Undercarriage Rust      | ID 031196<br>OD UNKN   |
| 47 | QTY - 1 | 03 Chevrolet G2500 Express Subn BL 8 cyl AT PB PS R AC PW<br>VIN: 1GNGG25U331226041; Defects: Body Damage, Frame Rusted, Glass Damage, Lights, Missing Parts, Undercarriage Rust                    | ID 031200<br>OD 146856 |
| 48 | QTY - 1 | 03 Chevrolet G3500 Express Subn RD 8 cyl AT PB PS R AC PW<br>VIN: 1GAHG35U731226118; Defects: Body Damage, Frame Rusted, Missing Keys, Missing Parts, Undercarriage Rust                            | ID 031281<br>OD 106246 |
| 49 | QTY - 1 | 03 Chevrolet G3500 Express Subn GR 8 cyl AT PB PS R AC PW<br>VIN: 1GAHG35U331226147; Defects: Body Damage, Frame Rusted, Glass Damage, Lights, Missing Keys, Missing Parts, Undercarriage Rust      | ID 031284<br>OD UNKN   |
| 50 | QTY - 1 | 02 Chevrolet Express Subn WH 8 cyl AT PB PS R AC PW<br>VIN: 1GAHG39U351205389; Defects: Body Damage, Catalytic Converter, Frame Rotted Out, Missing Parts, Undercarriage Rust                       | ID 051245<br>OD 171607 |

SALE NO. AU20220318001

| LOT NO. |         | DESCRIPTION   |                        |  |
|---------|---------|---|------------------------|--|
| 51      | QTY - 1 | 01 Chevrolet G3500 Express Subn TN 8 cyl Whchr AT PB PS R AC PW<br>VIN: 1GBHG39R811195881; Defects: Body Damage, Frame Rusted, Missing Parts, Undercarriage Rust  | ID 011280<br>OD UNKN   |  |
| 52      | QTY - 1 | 01 Chevrolet G3500 Express Subn TN 8 cyl Whchr AT PB PS R AC PW<br>VIN: 1GBHG39R011197057; Defects: Body Damage, Frame Rusted, Glass Damage, Lights, Missing Catalytic Convert, Missing Parts, Undercarriage Rust | ID 011282<br>OD 64162  |  |
| 53      | QTY - 1 | 01 Chevrolet G3500 Express Subn BL 8 cyl Whchr AT PB PS R AC PW<br>VIN: 1GAHG39R711224307; Defects: Body Damage, Frame Rusted, Glass Damage, Lights, Missing Keys, Missing Parts, Undercarriage Rust              | ID 011385<br>OD UNKN   |  |
| 54      | QTY - 1 | 18 Chevrolet Malibu 4DSD BK 4 cyl AT PB PS R AC PW<br>VIN: 1G1ZC5ST2JF205443; Defects: **OPEN RECALL**, Accident Damage, Missing Parts  | ID 181660<br>OD 1530   |  |
| 55      | QTY - 1 | 05 Chrysler Town & Country Subn BL 6 cyl AT PB PS R AC PW<br>VIN: 1C4GP45R85B378460; Defects: Body Damage, Frame Rotted Out, Missing Parts, Undercarriage Rust  | ID 051476<br>OD 168599 |  |
| 56      | QTY - 1 | 05 Chrysler Town & Country Subn BL 6 cyl AT PB PS R AC PW<br>VIN: 1C4GP45R05B378453; Defects: Body Damage, Frame Rusted, Glass Damage, Missing Parts, Undercarriage Rust  | ID 051481<br>OD 222113 |  |
| 57      | QTY - 1 | 05 Chrysler Town & Country Subn BL 6 cyl AT PB PS R AC PW<br>VIN: 1C4GP45RX5B388116; Defects: Body Damage, Frame Rotted Out, Glass Damage, Missing Keys, Missing Parts, Undercarriage Rust                        | ID 051490<br>OD 133639 |  |
| 58      | QTY - 1 | 08 Ford E350 Van WH 8 cyl AT PB PS R AC PW<br>VIN: 1FTSE34L18DB04100; Defects: Accident Damage, Body Damage, Frame Rotted Out, Missing Parts, Undercarriage Rust  | ID 085660<br>OD 148202 |  |
| 59      | QTY - 1 | 18 Ford Transit Subn GY 6 cyl AT PB PS R AC PW<br>VIN: 1FBZX2XM9JKA72414; Defects: Accident Damage, Body Damage, Frame, Frame Rusted  | ID 181997<br>OD 8180   |  |
| 60      | QTY - 1 | 11 Ford Expedition Subn WH 8 cyl AT PB PS R AC PW<br>VIN: 1FMJU1G5XBEF52381; Defects: Accident Damage, Body Damage, Frame Rusted, Missing Parts, Undercarriage Rust   | ID 113543<br>OD UNKN   |  |

SALE NO. AU20220318001

LOT NO.

DESCRIPTION

|    |       |   |  |                        |
|----|-------|---|--|------------------------|
| 61 | QTY - | 1 | 08 Ford E350 Subn WH 10 cyl AT PB PS R AC PW<br>VIN: 1FD3E35S88DA15761; Defects: Body Damage,<br>Engine, Frame Rotted Out, Missing Parts, Undercarriage Rust   | ID 085522<br>OD 121611 |
| 62 | QTY - | 1 | 08 Ford E350 Subn WH 10 cyl Wheelchair Conversion AT<br>PB PS R AC PW<br>VIN: 1FD3E35S18DA15763; Defects: Body Damage, Frame<br>Rotted Out, Glass Damage, Lights, Missing Keys, Missing<br>Parts, Undercarriage Rust                       | ID 085524<br>OD 168425 |
| 63 | QTY - | 1 | 08 Ford E350 Subn WH 10 cyl AT PB PS R AC PW<br>VIN: 1FD3E35S38DA15764; Defects: Body Damage,<br>Engine, Frame Rotted Out, Missing Parts, Rust Holes in<br>Floor, Undercarriage Rust   | ID 085525<br>OD 129784 |
| 64 | QTY - | 1 | 07 Ford E350 Subn WH 8 cyl AT PB PS R AC PW<br>VIN: 1FDWE35L57DA58653; Defects: Accident Damage,<br>Body Damage, Frame Rotted Out, Missing Parts,<br>Undercarriage Rust  | ID 075309<br>OD 63382  |
| 65 | QTY - | 1 | 06 Ford E350 Subn WH 8 cyl Wheelchair Lift AT PB PS R<br>AC PW<br>VIN: 1FDWE35L56HA20007; Defects: Body Damage, Frame<br>Rotted Out, Glass Damage, Lights, Missing Parts,<br>Undercarriage Rust  | ID 065202<br>OD 104445 |
| 66 | QTY - | 1 | 06 Ford E350 Subn WH 8 cyl Wheelchair Lift AT PB PS R<br>AC PW<br>VIN: 1FDWE35L16HA20005; Defects: Body Damage, Frame<br>Rotted Out, Glass Damage, Lights, Missing Catalytic Convert,<br>Missing Door, Missing Parts, Wheelchair Lift      | ID 065201<br>OD 63155  |
| 67 | QTY - | 1 | 05 Ford E350 Subn WH 8 cyl Wheelchair Conversion AT<br>PB PS R AC PW<br>VIN: 1FDWE35L45HB26480; Defects: Body Damage,<br>Catalytic Converter, Frame Rotted Out, Glass Damage,<br>Lights, Missing Parts, Undercarriage Rust                 | ID 055143<br>OD 120845 |
| 68 | QTY - | 1 | 05 Ford E350 Subn WH 8 cyl Wheelchair Conversion AT<br>PB PS R AC PW<br>VIN: 1FDWE35L65HB26481; Defects: Body Damage, Frame<br>Rotted Out, Glass Damage, Lights, Missing Catalytic Convert,<br>Missing Parts, Undercarriage Rust           | ID 055144<br>OD 71380  |
| 69 | QTY - | 1 | 05 Ford E350 Subn WH 8 cyl Wheelchair Conversion AT<br>PB PS R AC PW<br>VIN: 1FDWE35L35HA87848; Defects: Body Damage,<br>Catalytic Converter, Frame Rotted Out, Glass Damage,<br>Lights, Missing Engine, Missing Parts, Undercarriage Rust | ID 055140<br>OD 94219  |

SALE NO. AU20220318001

| LOT NO. |         | DESCRIPTION  |                        |
|---------|---------|--|------------------------|
| 70      | QTY - 1 | 05 Ford E350 Subn WH 8 cyl Wheelchair Conversion AT<br>PB PS R AC PW<br>VIN: 1FDWE35L15HA87847; Defects: Accident Damage,<br>Body Damage, Frame Rotted Out, Glass Damage, Lights, Rust<br>Holes in Floor, Undercarriage Rust     | ID 055139<br>OD 96647  |
| 71      | QTY - 1 | 05 Ford E350 Subn WH 8 cyl Wheelchair Conversion AT<br>PB PS R AC PW<br>VIN: 1FDWE35L85HB26482; Defects: Body Damage, Frame<br>Rotted Out, Glass Damage, Lights, Missing Catalytic Convert,<br>Missing Parts, Undercarriage Rust | ID 055145<br>OD 149249 |
| 72      | QTY - 1 | 05 Ford E350 Subn WH 8 cyl Wheelchair Conversion AT<br>PB PS R AC PW<br>VIN: 1FDWE35LX5HB26483; Defects: Body Damage,<br>Catalytic Converter, Frame Rotted Out, Glass Damage,<br>Lights, Missing Parts, Undercarriage Rust       | ID 055146<br>OD 127879 |
| 73      | QTY - 1 | 05 Ford E350 Subn WH 8 cyl Wheelchair Conversion AT<br>PB PS R AC PW<br>VIN: 1FDWE35L55HA87849; Defects: Body Damage, Frame<br>Rotted Out, Glass Damage, Lights, Missing Catalytic Convert,<br>Missing Parts, Undercarriage Rust | ID 055141<br>OD 81881  |
| 74      | QTY - 1 | 07 Ford Taurus 4DSD BL 6 cyl AT PB PS R AC PW<br>VIN: 1FAFP53U37A116692; Defects: Body Damage, Frame<br>Rotted Out, Missing Parts, Undercarriage Rust  | ID 071034<br>OD 126024 |
| 75      | QTY - 1 | 07 Ford Taurus 4DSD BL 6 cyl AT PB PS R AC PW<br>VIN: 1FAFP53U97A116695; Defects: Body Damage, Frame<br>Rotted Out, Missing Parts, Undercarriage Rust  | ID 071036<br>OD 124312 |
| 76      | QTY - 1 | 07 Ford Taurus 4DSD BL 6 cyl AT PB PS R AC PW<br>VIN: 1FAFP53U87A116705; Defects: Body Damage, Frame<br>Rotted Out, Glass Damage, Lights, Missing Parts,<br>Undercarriage Rust   | ID 071041<br>OD 195115 |
| 77      | QTY - 1 | 07 Ford Taurus 4DSD BL 6 cyl AT PB PS R AC PW<br>VIN: 1FAFP53U97A116700; Defects: Body Damage, Frame<br>Rotted Out, Glass Damage, Lights, Missing Parts,<br>Undercarriage Rust   | ID 071035<br>OD 103206 |
| 78      | QTY - 1 | 05 Ford Taurus 4DSD GY 6 cyl AT PB PS R AC PW<br>VIN: 1FAFP53245A301653; Defects: Body Damage, Frame<br>Rotted Out, Glass Damage, Lights, Missing Parts,<br>Undercarriage Rust   | ID 051976<br>OD 79337  |



SALE NO. AU20220318001

LOT NO.

DESCRIPTION

|    |         |   |                        |
|----|---------|---|------------------------|
| 79 | QTY - 1 | 12 Dodge Grand Caravan Subn GY 6 cyl AT PB PS R AC PW<br>VIN: 2C4RDGBGXCR168401; Defects: Body Damage, Frame Rusted, Glass Damage, Lights, Missing Parts, Undercarriage Rust                        | ID 121075<br>OD 161550 |
| 80 | QTY - 1 | 12 Dodge Grand Caravan Subn BL 6 cyl AT PB PS R AC PW<br>VIN: 2C4RDGBG2CR366678; Defects: **OPEN RECALL**, Accident Damage, Frame Rusted, Missing Parts, Undercarriage Rust                         | ID 121212<br>OD UNKN   |
| 81 | QTY - 1 | 10 Dodge Caravan Subn BK 6 cyl AT PB PS R AC PW<br>VIN: 2D4RN4DE7AR303762; Defects: **OPEN RECALL**, Body Damage, Frame Rotted Out, Missing Parts, Undercarriage Rust                               | ID 101300<br>OD 261386 |
| 82 | QTY - 1 | 09 Dodge Caravan Subn GR 6 cyl AT PB PS R AC PW<br>VIN: 2D8HN44E79R653382; Defects: **OPEN RECALL**, Body Damage, Exhaust, Frame Rotted Out, Missing Parts  | ID 091117<br>OD 136660 |
| 83 | QTY - 1 | 03 Toyota Prius 4DSD BL 4 cyl Hybrid AT PB PS R AC PW<br>VIN: JT2BK12U830082470; Defects: Body Damage, Exhaust, Frame Rusted, Glass Damage, Lights, Missing Parts, Transmission, Undercarriage Rust | ID 031190<br>OD UNKN   |
| 84 | QTY - 1 | 03 GMC G3500 Savana Subn GR 8 cyl whlchr AT PB PS R AC PW<br>VIN: 1GDHG39U031226331; Defects: Body Damage, Frame Rusted, Glass Damage, Lights, Missing Keys, Missing Parts, Undercarriage Rust      | ID 031412<br>OD UNKN   |
| 85 | QTY - 1 | 03 GMC G3500 Savana Subn BL 8 cyl Whlchr AT PB PS R AC PW<br>VIN: 1GDHG39U731227542; Defects: Body Damage, Frame Rusted, Glass Damage, Lights, Missing Parts, Undercarriage Rust                    | ID 031413<br>OD 74661  |
| 86 | QTY - 1 | 03 GMC G3500 Savana Subn GR 8 cyl whlchr AT PB PS R AC PW<br>VIN: 1GDHG39U231217484; Defects: Body Damage, Frame Rusted, Glass Damage, Lights, Missing Keys, Missing Parts, Undercarriage Rust      | ID 031414<br>OD UNKN   |
| 87 | QTY - 1 | 03 GMC G3500 Savana Subn RD 8 cyl whlchr AT PB PS R AC PW<br>VIN: 1GDHG39U231233278; Defects: Body Damage, Frame Rusted, Missing Parts, Undercarriage Rust  | ID 031416<br>OD 82319  |

SALE NO. AU20220318001

LOT NO.

DESCRIPTION

|    |         |   |                        |
|----|---------|---|------------------------|
| 88 | QTY - 1 | 03 GMC G3500 Savana Subn BL 8 cyl whlchr AT PB PS R AC PW<br>VIN: 1GDHG39U631228648; Defects: Body Damage, Frame Rusted, Glass Damage, Lights, Missing Catalytic Convert, Missing Parts, Undercarriage Rust | ID 031418<br>OD 101109 |
| 89 | QTY - 1 | 02 GMC G3500 Savana Subn BL 8 cyl Whchr AT PB PS R AC PW<br>VIN: 1GDHG39RX21168867; Defects: Body Damage, Frame Rusted, Glass Damage, Lights, Missing Parts, Undercarriage Rust                             | ID 021114<br>OD 85109  |
| 90 | QTY - 1 | 03 GMC Van RD 8 cyl Whlchr AT PB PS R AC PW<br>VIN: 1GDHG39U231217386; Defects: Body Damage, Frame Rusted, Missing Parts, Undercarriage Rust  | ID 031407<br>OD 136078 |
| 91 | QTY - 1 | 98 Chevrolet Cheyenne Pickup GR 8 cyl AT PB PS R AC PW<br>VIN: 1GCGC24R8WE205958; Defects: Body Damage, Frame Rusted, Missing Parts, Rust Holes in Floor, Undercarriage Rust                                | ID 985183<br>OD 159366 |
| 92 | QTY - 1 | 03 Chevrolet K2500 Pickup WH 8 cyl 4X4 AT PB PS R AC PW<br>VIN: 1GCHK29U33E368534; Defects: Body Damage, Frame Rusted, Glass Damage, Lights, Missing Keys, Missing Parts, Undercarriage Rust                | ID 035210<br>OD UNKN   |
| 93 | QTY - 1 | 03 Chevrolet K2500 Pickup WH 8 cyl 4X4 AT PB PS R AC PW<br>VIN: 1GCHK29U73E365510; Defects: Body Damage, Frame Rusted, Missing Parts, Undercarriage Rust  | ID 035211<br>OD UNKN   |
| 94 | QTY - 1 | 04 Ford F550 Van WH 8 cyl Diesel AT PB PS R PW<br>VIN: 1FDAF57P64EC26177; Defects: Body Damage, Brake Lines, Brakes, Frame Rotted Out, Missing Parts, Undercarriage Rust                                    | ID 045110<br>OD 94089  |

LEGEND

AT = AUTOMATIC TRANSMISSION

ST = STANDARD TRANSMISSION

PB = POWER BRAKES

PS = POWER STEERING

TMU = TRUE MILEAGE UNKNOWN

OD = MILEAGE INDICATED ON ODOMETER, INCLUDING EXCESS OF 100,000 IF KNOWN

PW = POWER WINDOWS

AC = AIR CONDITIONING

CC = CRUISE CONTROL

R = RADIO