

May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending today's auction, please visit our website for the most up to date conversation!

LOT

7272 Used 2010 Yamaha Grizzly Null Four Wheeler

****bos Only**** Used 2010 Yamaha Grizzly Null Four Wheeler, Vin# 5y4amc9y0ja103313, 1,299 Miles, 700cc, Gray In Color. Power Steering, Reverse, Backrest For Passenger.



7223 REPO 2016 Ford Escape 1FMCU9GX8GUA18916

Miles: 103,599
Color: Black
Engine: I4, 1.6 T



Automatic transmission, automatic headlights, power mirrors, power windows, power locks, tilt steering wheel, steering wheel monitor controls, cruise control, AM/FM radio with CD player, Bluetooth and SiriusXM available, gray black cloth interior, aluminum rims,

Condition report: minor scratches on hood, multiple scratches paint and protections on front bumper, light scratches on driver side fender, minor scratches on driver side doors, heavy corrosion on driver side, front door, and driver side rear door, scuffs, paint, imperfections, large scrapes on rear bumper and liftgate, minor scratches on passenger quarter panel, minor scratches on passenger side, rear door, and front door, heavy corrosion on passenger side doors.

DO NOT BID ON THIS VEHICLE FROM THE PICTURES

YOU MUST INSPECT THE VEHICLE IN PERSON ON Saturday, MAY 9TH, 2026.

Beginning at 8am Eastern Time

This Unit Is A Repossessed Vehicle!

Repossessed Vehicles can offer a Best Value, however they can bear The Greatest Risk!

Each reposessed vehicle will have New York State REPO papers you can ONLY register this unit in New York State, You Can "NOT???"

Register It Out Of New York State

A Repossessed Vehicle often has condition or mechanical issues. There are NO WARRANTIES or GUARANTEES. This

LOT

vehicle came from someone who couldn't pay for it, so maintenance and upkeep was not the prior owner priority
YOU MUST INSPECT THE VEHICLE in person and determine if this is the right vehicle for you.

THIS VEHICLE IS SOLD "AS-IS.....YOU BUY IT YOU OWN IT!YOU MADE A MISTAKE YOU OWN IT! LET THE BUYER BEWARE..... THERE IS NO RETURN POLICY.

GOOD LUCK! AND REMEMBER AN EDUCATED CONSUMER IS OUR BEST CUSTOMER.

****BIDDING IS OPEN TO THE GENERAL PUBLIC****

7225 REPO 2019 Chevrolet Equinox 2GNAXUEV1K6141642

Miles: 165,599
Color: Black
Engine: I4, 1.5 T



Automatic transmission, all-wheel-drive, black cloth interior, AM/FM radio with CD, dual climb control, push start, steering wheel monitor control, cruise control, tilt wheel, automatic headlight, power driver seat, power window power lock, aluminum rims,

Condition report: put a small scratch out from Bumper head flat scrapes scratches and neck driver side front fender scrape small dense driver door has small scratch to scrape rough starting to form on bottom like paint chips on edge have a rear door has heavy scratches around door handle small rack chips and paint chip driver side rear quarter panel scratches around field cap bumper heavy scrape scratches small that's your trunk that has large scratches out passenger side rear as small dents around Wiil well heavy scratches throughout passenger side rear door has small dent scratches on bottom of rocker side front door has multiple small paint chipped

May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending todays auction, please visit our website for the most up to date conversation!

LOT #

active side front fender has a small dent with paint imperfections

DO NOT BID ON THIS VECHICLE FROM THE PICTURES
YOU MUST INSPECT THE VEHICLE IN PERSON ON Saturday, MAY 9TH, 2026.
Beginning at 8am Eastern Time
This Unit Is A Repossessed Vehicle!
Repossessed Vehicles can offer a Best Value, however they can bear The Greatest Risk!
Each repossessed vehicle will have New York State REPO papers you can ONLY register this unit in New York State, You Can "NOT???"
Register It Out Of New York State
A Repossessed Vehicle often has condition or mechanical issues. There are NO WARRANTIES or GUARANTEES. This vehicle came from someone who couldn't pay for it, so maintenance and upkeep was not the prior owner priority
YOU MUST INSPECT THE VEHICLE in person and determine if this is the right vehicle for you.
THIS VEHICLE IS SOLD "AS-IS.....YOU BUY IT YOU OWN IT!YOU MADE A MISTAKE YOU OWN IT! LET THE BUYER BEWARE..... THERE IS NO RETURN POLICY.
GOOD LUCK! AND REMEMBER AN EDUCATED CONSUMER IS OUR BEST CUSTOMER.

****BIDDING IS OPEN TO THE GENERAL PUBLIC****

LOT #

Driver door has multiple large attractive paint tips large scrape scratches and dense driver rear door scrapes paint and perfection over Will has small scrap scratches that rough starting the Farm rear bumper hits heavy scratches and scrapes your trunk that has heavy scratches that rear bumper has small soft Mark rock forming and passenger rocker or small done side rear door has large door scratches and scrapes at the front door and small scraped tractor done Driver Patty front finder has excellent damage great scratches damage paint peeling dents

DO NOT BID ON THIS VECHICLE FROM THE PICTURES
YOU MUST INSPECT THE VEHICLE IN PERSON ON Saturday, MAY 9TH, 2026.
Beginning at 8am Eastern Time
This Unit Is A Repossessed Vehicle!
Repossessed Vehicles can offer a Best Value, however they can bear The Greatest Risk!
Each repossessed vehicle will have New York State REPO papers you can ONLY register this unit in New York State, You Can "NOT???"
Register It Out Of New York State
A Repossessed Vehicle often has condition or mechanical issues. There are NO WARRANTIES or GUARANTEES. This vehicle came from someone who couldn't pay for it, so maintenance and upkeep was not the prior owner priority
YOU MUST INSPECT THE VEHICLE in person and determine if this is the right vehicle for you.
THIS VEHICLE IS SOLD "AS-IS.....YOU BUY IT YOU OWN IT!YOU MADE A MISTAKE YOU OWN IT! LET THE BUYER BEWARE..... THERE IS NO RETURN POLICY.
GOOD LUCK! AND REMEMBER AN EDUCATED CONSUMER IS OUR BEST CUSTOMER.

****BIDDING IS OPEN TO THE GENERAL PUBLIC****

7228 Repo 2015 Buick Regal 2g4gk5ex3f9126049

Miles: 123,956
Color: Silver
Engine: I4, 2 T
Automatic transmission, black leather interior, dual climate control, heated seats, cap capabilities, steering wheel monitor controls, cruise control,, power relax aluminum rims



Condition report: Friday of the actual damage large pieces of bumper are missing crack damaged large stretches driver side front fender large set multiple smaller rough slots large dents

May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending todays auction, please visit our website for the most up to date conversation!

LOT #

7230 REPO 2017 Chevrolet Malibu 1G1ZB5ST2HF128912

Miles: 148,834
 Color: Gray
 Engine: I4, 1.5 T



Automatic transmission, black cloth and interior, AM/FM radio, steering wheel monitor controls, cruise control, push the start, automatic headlights, power windows power locked, aluminum rims,

Condition report put a small paint chips and scratches throughout small paint blemishes on hood from bumper and small straight scratches throughout territory front fender has multiple art dents and scratches Driver door has small scratches scrapes and blue light top on door heavy scratches around door handle large paint chips on edge of door driver side rear door has scratches straight small rack tips throughout phair tire quarter panel has small scrape scratches rear bumper has has paint and perfections throughout rear trunk has clear coat fading side quarter panel has multiple small dents and scratches your door has large paint and perfection and scratches side front door and small under door handle small scrapes passenger side front Binder has multiple small dents and and perfect.

DO NOT BID ON THIS VECHICLE FROM THE PICTURES
 YOU MUST INSPECT THE VEHICLE IN PERSON ON Saturday, MAY 9TH, 2026.
 Beginning at 8am Eastern Time
 This Unit Is A Repossessed Vehicle!
 Repossessed Vehicles can offer a Best Value, however they can bear The Greatest Risk!
 Each repossessed vehicle will have New York State REPO papers you can ONLY register this unit in New York State, You Can "NOT???" Register It Out Of New York State
 A Repossessed Vehicle often has condition or mechanical issues. There are NO WARRANTIES or GUARANTEES. This vehicle came from someone who couldn't pay for it, so maintenance and upkeep was not the prior owner priority
 YOU MUST INSPECT THE VEHICLE in person and determine if this is the right vehicle for you.
 THIS VEHICLE IS SOLD "AS-IS.....YOU BUY IT YOU OWN IT!YOU MADE A

LOT #

MISTAKE YOU OWN IT! LET THE BUYER BEWARE..... THERE IS NO RETURN POLICY.
 GOOD LUCK! AND REMEMBER AN EDUCATED CONSUMER IS OUR BEST CUSTOMER.

****BIDDING IS OPEN TO THE GENERAL PUBLIC****

7232 REPO 2017 Honda Pilot 5FNYP6H16HB079219

Miles: 137,489
 Color: White
 Engine: V6, 3.5



This vehicle runs but does not moveAutomatic transmission, black cloth interior, dual climber control, AM/FM radio CD, steering wheel monitor controls, cruise control, tilt wheel, cruise control, power Windows power lock down aluminum rims third row seating,

Additional report: put multiple small paint chips and scratches they're out small paint blemishes on front bumper with rack chips scratches driver side front fender has small scratches along ad Driver door scratches our own door handle multiple small rock tips at bottom driver rear door has small particles throughout their side rear quarter panel small heavy vents multiple small large paint and perfection Bumper stuff Martin stripes for trunk has accent damage paint large stunts rear bumper has small spaced scratches faster side rear quarter panel has small paint and perfection small dent with starting to form Patty rear door has small scratches and stripes after side front door small imperfections front fender has scraped and scratches side front axle is broken and Tirer is moved forward

DO NOT BID ON THIS VECHICLE FROM THE PICTURES
 YOU MUST INSPECT THE VEHICLE IN PERSON ON Saturday, MAY 9TH, 2026.
 Beginning at 8am Eastern Time
 This Unit Is A Repossessed Vehicle!
 Repossessed Vehicles can offer a Best Value, however they can bear The Greatest Risk!
 Each repossessed vehicle will have New York State REPO papers you can ONLY register this

May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending todays auction, please visit our website for the most up to date conversation!

LOT #

unit in New York State, You Can "NOT???" Register It Out Of New York State
 A Repossessed Vehicle often has condition or mechanical issues. There are NO WARRANTIES or GUARANTEES. This vehicle came from someone who couldn't pay for it, so maintenance and upkeep was not the prior owner priority
 YOU MUST INSPECT THE VEHICLE in person and determine if this is the right vehicle for you.
 THIS VEHICLE IS SOLD "AS-IS.....YOU BUY IT YOU OWN IT!YOU MADE A MISTAKE YOU OWN IT! LET THE BUYER BEWARE..... THERE IS NO RETURN POLICY.
 GOOD LUCK! AND REMEMBER AN EDUCATED CONSUMER IS OUR BEST CUSTOMER.

BIDDING IS OPEN TO THE GENERAL PUBLIC

7233 Repo 2017 Ford Fusion 3fa6p0h73hr375342

Miles: 137,353
 Color: White
 Engine: I4, 2.5

Automatic transmission, black cloth interior, AM/FM radio with CD, steering wheel motor control, cruise control, Wiil,, aluminum rims



Multiple scratches throughout from Bumper has higher chances and scrapes Adelaide is very fogged multiple small scratches scrapes and front fender with paint missing Driver door hit small scratches scrape heavy scratches around door handle large paint tip small paint crafts on tree rear door small scratches and scrapes have rough large stuff marks throughout your bumper heads heavy scrap and scratches with large cracks tail light broken and rear bumper heads particles brake particles brakes throughout small scratches side rear tipping and peeling shelf marks and their ad has small pink imperfection throughout driver side front door front mirror is missing top plastic large stand large scratches throughout black tar like substance around front fenders.

LOT #

DO NOT BID ON THIS VECHICLE FROM THE PICTURES
 YOU MUST INSPECT THE VEHICLE IN PERSON ON Saturday, MAY 9TH, 2026.
 Beginning at 8am Eastern Time
 This Unit Is A Repossessed Vehicle!
 Repossessed Vehicles can offer a Best Value, however they can bear The Greatest Risk!
 Each repossessed vehicle will have New York State REPO papers you can ONLY register this unit in New York State, You Can "NOT???" Register It Out Of New York State
 A Repossessed Vehicle often has condition or mechanical issues. There are NO WARRANTIES or GUARANTEES. This vehicle came from someone who couldn't pay for it, so maintenance and upkeep was not the prior owner priority
 YOU MUST INSPECT THE VEHICLE in person and determine if this is the right vehicle for you.
 THIS VEHICLE IS SOLD "AS-IS.....YOU BUY IT YOU OWN IT!YOU MADE A MISTAKE YOU OWN IT! LET THE BUYER BEWARE..... THERE IS NO RETURN POLICY.
 GOOD LUCK! AND REMEMBER AN EDUCATED CONSUMER IS OUR BEST CUSTOMER.

BIDDING IS OPEN TO THE GENERAL PUBLIC

7231 REPO 2016 Dodge Journey 3C4PDDEG5GT227777

Miles: 142,870
 Color: White
 Engine: V6, 3.6

Automatic transmission, black leather interior, dual climate control heated steering wheel, three door garage memory, steering wheel monitor controls, cruise control, push the start, automatic headlights, fog light, power Driver, power windows power lock, third row seat, aluminum rims, roof rack,
 Additional report: scratches out front bumper has small scratches and dents Driver front Binder has large rub mark and stuff marks break dust all along driver side a vehicle large center on bottom of thunder Driver window will not go



May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending todays auction, please visit our website for the most up to date conversation!

LOT #

up or down Driver door heads large straight scratches paint and perfections driver rear door has large stock Mark large stance scratches great paint imperfections tide rear quarter panel large black stripe starting a form over Wiil Wiil for Bumper heavy scrape scratches and then your trunk has scraped scratches passenger side rear bumper has small quarter panel small scrape scratch passenger rear door highlight substance on bottom words stuff marks and scrapes has black car like substance in the middle of door large scratches front fender small scrape scratch and dents


DO NOT BID ON THIS VECHICLE FROM THE PICTURES
 YOU MUST INSPECT THE VEHICLE IN PERSON ON Saturday, MAY 9TH, 2026.
 Beginning at 8am Eastern Time
 This Unit Is A Repossessed Vehicle!
 Repossessed Vehicles can offer a Best Value, however they can bear The Greatest Risk!
 Each repossessed vehicle will have New York State REPO papers you can ONLY register this unit in New York State, You Can "NOT???" Register It Out Of New York State
 A Repossessed Vehicle often has condition or mechanical issues. There are NO WARRANTIES or GUARANTEES. This vehicle came from someone who couldn't pay for it, so maintenance and upkeep was not the prior owner priority
 YOU MUST INSPECT THE VEHICLE in person and determine if this is the right vehicle for you.
 THIS VEHICLE IS SOLD "AS-IS.....YOU BUY IT YOU OWN IT!YOU MADE A MISTAKE YOU OWN IT! LET THE BUYER BEWARE..... THERE IS NO RETURN POLICY.
 GOOD LUCK! AND REMEMBER AN EDUCATED CONSUMER IS OUR BEST CUSTOMER.

BIDDING IS OPEN TO THE GENERAL PUBLIC

LOT #

7229 REPO 2017 Kia Optima 5XXGT4L30HG165463

Miles: 164,813
 Color: Blue
 Engine: I4, 2.4
 Automatic transmission, black cloth here, AM/FM radio with CV, steering wheel control, cruise control, tilt wheel, power windows power lock, aluminum,



Report: cut as multiple small scratches and scraped multiple large sense and hood large scratch front bumper plastic hanging down on front bumper bumper wire scratch scratches and scrapes with paint perfect and cyber door has multiple large stock marked scrapes large dents throughout missing classic antenna apart tide rear door has small scratches large dent small stripes steel cap door paint rear bumper has heavy scraped and scrapes rear bumper held down with a bungee cord large dent scratches throughout rear hood does not close passenger side rear quarter panel has small and large pesticide rear door has multiple attractive sense and things with multiple small large stunt exercise front door has small dent scrapes and scratches passenger side front fender small large scratches throughout.

DO NOT BID ON THIS VECHICLE FROM THE PICTURES
 YOU MUST INSPECT THE VEHICLE IN PERSON ON Saturday, MAY 9TH, 2026.
 Beginning at 8am Eastern Time
 This Unit Is A Repossessed Vehicle!
 Repossessed Vehicles can offer a Best Value, however they can bear The Greatest Risk!
 Each repossessed vehicle will have New York State REPO papers you can ONLY register this unit in New York State, You Can "NOT???" Register It Out Of New York State
 A Repossessed Vehicle often has condition or mechanical issues. There are NO WARRANTIES or GUARANTEES. This vehicle came from someone who couldn't pay for it, so maintenance and upkeep was not the prior owner priority
 YOU MUST INSPECT THE VEHICLE in person and determine if this is the right vehicle for you.
 THIS VEHICLE IS SOLD "AS-IS.....YOU BUY IT YOU OWN IT!YOU MADE A MISTAKE YOU OWN IT! LET THE BUYER

May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending todays auction, please visit our website for the most up to date conversation!

LOT #

BEWARE..... THERE IS NO RETURN POLICY.
GOOD LUCK! AND REMEMBER AN EDUCATED CONSUMER IS OUR BEST CUSTOMER.

****BIDDING IS OPEN TO THE GENERAL PUBLIC****

7227 Repo 2018 Dodge Grand Caravan 2c4rdgeg3jr328031

Miles: 119,789
Color: Silver
Engine: V6, 3.6



Automatic transmission, black leather interior, heated seats, heated steering wheel, dual climber control, backup camera, three door memory, steering wheel monitor controls, cruise control, tilt wheel, automatic headlights, fog lights, power windows power locks, stone no seating, third row seating, rear climate control, roof rack, aluminum,rims

Report a small smaller out from Bumper small distracted and things hit small scratches on edge Driver door has multiple small paint Tow Truck scratches through Driver slider has danced through throughout door dig through throughout scratches throughout rack the bottom Xavier quarter panel stretches around fuel cap small rack and paint chips your bumper heavy scrapes and scratches on edge small puncture holes in your plastic Bumper your truck has scratches and scrapes cyber corner panel scratches around edge heavy scratches on your door cyber slider has multiple small dents and dings faster side door heads large dent small dent heavy scratches throughout large plastic rub mark and passenger finder

DO NOT BID ON THIS VECHICLE FROM THE PICTURES

YOU MUST INSPECT THE VEHICLE IN PERSON ON Saturday, MAY 9TH, 2026.

Beginning at 8am Eastern Time

This Unit Is A Repossessed Vehicle!

Repossessed Vehicles can offer a Best Value, however they can bear The Greatest Risk!

Each repossessed vehicle will have New York State REPO papers you can ONLY register this

LOT #

unit in New York State, You Can "NOT???" Register It Out Of New York State
A Repossessed Vehicle often has condition or mechanical issues. There are NO WARRANTIES or GUARANTEES. This vehicle came from someone who couldn't pay for it, so maintenance and upkeep was not the prior owner priority
YOU MUST INSPECT THE VEHICLE in person and determine if this is the right vehicle for you.

THIS VEHICLE IS SOLD "AS-IS.....YOU BUY IT YOU OWN IT! ...YOU MADE A MISTAKE YOU OWN IT! LET THE BUYER BEWARE..... THERE IS NO RETURN POLICY.
GOOD LUCK! AND REMEMBER AN EDUCATED CONSUMER IS OUR BEST CUSTOMER.

****BIDDING IS OPEN TO THE GENERAL PUBLIC****

7224 REPO 2012 Honda Pilot 5FN9F4H49CB036128

Miles: 169,624
Color: Black
Engine: V6, 3.5



Automatic transmission, gray cloth interior, climate drill, M FM radio control, cruise control, four-wheel-drive, power driver seat, cruise control, power windows power, third seat, aluminum, hitch receiver

Report but it won't small to paint throughout from bumper heads crate scratches and scrapes rock chips large rock chips and paint chips on your driver side front driver door has scratches and scrapes with paint and perfections Driver stretches at bottom heavy scratches around door handle rear quarter panel has touchup paint done between fuel cap and heavy scratches and large stuff marks on rear bumper cover plastic trunk falling off rear trunk lid side rear quarter panel scratches and straight out side rear door small scratches scrapes rust forming on bottom passenger side front door doors scrapes hands scratch scratches Binder heads scrapes plastic piece on bumper falling off

May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending todays auction, please visit our website for the most up to date conversation!

LOT #

DO NOT BID ON THIS VECHICLE FROM THE PICTURES
 YOU MUST INSPECT THE VEHICLE IN PERSON ON Saturday, MAY 9TH, 2026.
 Beginning at 8am Eastern Time
 This Unit Is A Repossessed Vehicle!
 Repossessed Vehicles can offer a Best Value, however they can bear The Greatest Risk!
 Each repossessed vehicle will have New York State REPO papers you can ONLY register this unit in New York State, You Can "NOT???" Register It Out Of New York State
 A Repossessed Vehicle often has condition or mechanical issues. There are NO WARRANTIES or GUARANTEES. This vehicle came from someone who couldn't pay for it, so maintenance and upkeep was not the prior owner priority
 YOU MUST INSPECT THE VEHICLE in person and determine if this is the right vehicle for you.
 THIS VEHICLE IS SOLD "AS-IS.....YOU BUY IT YOU OWN IT!YOU MADE A MISTAKE YOU OWN IT! LET THE BUYER BEWARE..... THERE IS NO RETURN POLICY.
 GOOD LUCK! AND REMEMBER AN EDUCATED CONSUMER IS OUR BEST CUSTOMER.

****BIDDING IS OPEN TO THE GENERAL PUBLIC****

LOT #

bump quarter panel small scratches rear bumper has heavy scratches scrapes with cracking or scratches with scrapes passenger side rear bumper has large scratches under tail light multiple small stretches in recorder panel faster side door small Mark bottom rocker side front door and small paint chip rack tipped and scratched disaster side front thunder small scratches and scrapes tractor tight front bumper heads large chips in the Paint clear coat peeling

Do Not Bid From The Pictures
 You Must Inspect The Vehicle In Person On Saturday, May 9th, 2026. Beginning At 8am Est. This Unit Is Being Sold At Auction, Auction Units Can Offer The Best Value, However They Can Bear The Greatest Risk!
 An Auction Vehicle Often May Have Condition Or Mechanical Issues.
 There Are No Warranties Or Guarantees.
 You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You.
 This Vehicle Is Sold "as-is..... You Buy It You Own It! You Made A Mistake You Own It! Let The Buyer Beware..... There Is No Return Policy. Good Luck! And Remember An Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL PUBLIC****

7204 Used 2011 Ford Fusion 3fahp0ha0br192184

Miles: 170,559
 Color: Silver
 Engine: I4, 2.5
 Automatic transmission, black interior, FM radio CD, steering wheel monitor controls, cruise control, automatic headlights, fog light, power diverse, power windows power lock locks,



Condition report: multiple scratches; front bumper has small scratches and side front fender has small scratches, scrapes, small paint chips; front door has small scratches; middle door small rock chips, bottom side door multiple small paint imperfections, small scratches; rust forming on bottom of rocker driver side rear

7244 USED 2007 Suzuki Grand Vitara JS3TD941874201075

Miles: 159,284
 Color: Black
 Engine: V6, 2.7
 Automatic transmission, four-wheel-drive, black cloth interior, AM/FM radio with CD, steering wheel monitor controls, cruise control, tilt wheel, power windows power locks , full size Spare



Condition report : small paint imperfections with rust starting to form; front Bumper has paint imperfections and scratches; Bumper has smaller rock chips & paint chips with scratches; passenger door small paint imperfections in the middle of door & rock chips at bottom; quarter

May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending todays auction, please visit our website for the most up to date conversation!

LOT #

panel has small dents, scratches throughout; rust forming on bottom of rocker; rear quarter panel has scratches on wheel well; rear bumper has straight scratches heavy scuff marks; passenger side rear quarter panel scratched; scratches on fuel cap; scratches on body line; rear door has multiple small dents, scratches & scrapes; front door scratches around the door handle & scratches in middle of door; rock chipped bottom passenger side; front fender scratches on Wheel well.

Do Not Bid From The Pictures
 You Must Inspect The Vehicle In Person On Saturday,
 May 9th, 2026. Beginning At 8am Est. This Unit Is
 Being Sold At Auction,
 Auction Units Can Offer The Best Value,
 However They Can Bear The Greatest Risk!
 An Auction Vehicle Often May Have Condition Or Mechanical Issues.
 There Are No Warranties Or Guarantees.
 You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You.
 This Vehicle Is Sold "as-is..... You Buy It You Own It! You Made A Mistake You Own It! Let The Buyer Beware..... There Is No Return Policy. Good Luck! And Remember An Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL PUBLIC****

LOT #

steps through outer quarter panel pan multiple small done rear bumper has scratches great rear trunk has scratches on edge scratches around logo side rear bumper heavy scratches scrapes paint peeling chips and your quarter panel multiple small fence side rear door scratches around the door handle scratches in middle of door scratches scratches the middle door multiple racks on edge door beside a decimal that scratches throughout

Do Not Bid From The Pictures
 You Must Inspect The Vehicle In Person On Saturday,
 May 9th, 2026. Beginning At 8am Est. This Unit Is
 Being Sold At Auction,
 Auction Units Can Offer The Best Value,
 However They Can Bear The Greatest Risk!
 An Auction Vehicle Often May Have Condition Or Mechanical Issues.
 There Are No Warranties Or Guarantees.
 You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You.
 This Vehicle Is Sold "as-is..... You Buy It You Own It! You Made A Mistake You Own It! Let The Buyer Beware..... There Is No Return Policy. Good Luck! And Remember An Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL PUBLIC****

7203 USED 2015 Kia Optima 5XXGM4A78FG451495

Miles: 158,862
 Color: Silver
 Engine: I4, 2.4



Automatic transmission, gray cloth interior, AM/FM radio with CD, steering wheel monitor controls, cruise control, automatic headlights, power windows power locks aluminum rims

Condition report: but as a small pink tip and scratches throughout from Bumper has large scraping driver side front fender an and scratches out Driver door has scratches our own door handle paint and perfection in middle of door driver rear door has scratches and rack

7218 Ihi Excavator

Ihi Excavator 4336 Hours Diesel Rubber Cracks Push Blade, Hydraulic Thumb, Two Speed Transmission, Boom Side The Side



7202 Used 2010 Chevrolet Suburban 1gnukje38ar174245

Miles: 200,901
 Color: Blue
 Engine: V8, 5.3

Automatic transmission, four-wheel-drive, tan leather interior, dual climate control, heated seats, AM/FM radio with CD, on star capabilities, three door garage memory, steering wheel monitor control, cruise control, two seat



May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending todays auction, please visit our website for the most up to date conversation!

LOT #

memory, power driver seat, aftermarket Brake controller, rear captain chairs, third row seating, rear climate control, rear heated seats, aluminum rims, roof rack, hitch receiver,

Condition report: small blemishes throughout; front Bumper driver side has small scuff marks and scratches; driver side front fender has small dent with rock chips throughout; small scratches throughout; Driver front door has small dent; paint peeling throughout ; small scratches around door handle; multiple small dents; rust forming at the bottom of wheel well; small scratches and dents over Wheel well with paint imperfection; rear bumper has small scratches; trunk lid has paint starting to bubble; rear quarter panel has rust over Wheel Well with paint bubbling, small rust spot at bottom of quarter panel; door has multiple small scratches and scrapes; rust on rocker panels; passenger side front door has small rock chips and paint blemishes throughout; side front fender has small chips with a small dent

****OPEN RECALL**** Dealers will replace the passenger-side frontal airbag inflator.

Do Not Bid From The Pictures
You Must Inspect The Vehicle In Person On Saturday,
May 9th, 2026. Beginning At 8am Est. This Unit Is
Being Sold At Auction,
Auction Units Can Offer The Best Value,
However They Can Bear The Greatest Risk!
An Auction Vehicle Often May Have Condition Or Mechanical Issues.
There Are No Warranties Or Guarantees.
You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You.
This Vehicle Is Sold "as-is..... You Buy It You Own It! You Made A Mistake You Own It! Let The Buyer Beware..... There Is No Return Policy. Good Luck! And Remember An Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL PUBLIC****

LOT #

7200 Used 2013 Chevrolet Traverse 1gnkrfed1dj145178

Miles: 78,966
Color: Silver
Engine: V6, 3.6
Automatic transmission, grey cloth interior, AM/FM radio CD, backup camera, steering wheel monitor controls, cruise control, automatic headlight, power windows power lock, third row rear climate control



Condition report: hood has multiple small scrapes,scratches throughout; small scratch on bottom of Bumper; side front fender has small paint imperfections at bottom w/small scratches; Driver door has small scratches around door handle; multiple scratches at bottom of door; side rear door has medium size scratch in middle of door; rear quarter panel has small scratches with small dents; side rear bumper has small scuff marks; rear bumper has small paint chips; trunk has small scratches; side rear quarter panel has small rock chips at bottom ; small paint imperfections on the edge; small paint chips on middle of door; small dent passenger side front door; scratches around door handle; passenger side front fender has small scratches; front bumper has small scratches and scuff marks

Do Not Bid From The Pictures
You Must Inspect The Vehicle In Person On Saturday,
May 9th, 2026. Beginning At 8am Est. This Unit Is
Being Sold At Auction,
Auction Units Can Offer The Best Value,
However They Can Bear The Greatest Risk!
An Auction Vehicle Often May Have Condition Or Mechanical Issues.
There Are No Warranties Or Guarantees.
You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You.
This Vehicle Is Sold "as-is..... You Buy It You Own It! You Made A Mistake You Own It! Let The Buyer Beware..... There Is No Return Policy. Good Luck! And Remember An Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL PUBLIC****

May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending todays auction, please visit our website for the most up to date conversation!

LOT #

7235 REPO 2010 Toyota RAV4 2T3ZF4DV8AW047373

Miles: 138,823
Color: Silver
Engine: I4, 2.5

Automatic transmission, Front - wheel -drive, gray cloth interior, AM/FM radio with CD, cruise control, power Windows, roof rack



Condition report: multiple small paint chips and paint imperfections through out; small dents; driver side front fender has heavy scratches and scrapes; broken plastic held on with duct tape; driver side front fender has large dent with paint peeling and rusting driver side front door has small scrape scratches paint imperfections bottom driver side rear door has heavy scratches scuff marks paint and perfections throughout driver side rear quarter panel has scratches around field cap rear bumper has heavy scuff marks scratches broken plastic we are trunk that has heavy scratches throughout passenger side rear trunk has large dent with pink cracking passenger side rear bumper has small scratches passenger side quarter panel has heavy scratches and imperfections throughout passenger side door has large scuff marks small vents throughout passenger side front door large net door handle is door handle is broken and missing multiple small vents and passenger door small rack chips at bottom passenger side front fender has small dense with paint perfection paint peeling front bumper is destroyed hold on by rope and duct tape with hopes and dreams

DO NOT BID ON THIS VECHICLE FROM THE PICTURES

YOU MUST INSPECT THE VEHICLE IN PERSON ON Saturday, MAY 9TH, 2026.

Beginning at 8am Eastern Time

This Unit Is A Repossessed Vehicle!

Repossessed Vehicles can offer a Best Value, however they can bear The Greatest Risk!

Each reposessed vehicle will have New York State REPO papers you can ONLY register this unit in New York State, You Can "NOT???"

Register It Out Of New York State

A Repossessed Vehicle often has condition or mechanical issues. There are NO WARRANTIES or GUARANTEES. This vehicle came from someone who couldn't pay for it, so maintenance and upkeep was not the prior owner priority

LOT #

YOU MUST INSPECT THE VEHICLE in person and determine if this is the right vehicle for you.

THIS VEHICLE IS SOLD "AS-IS.....YOU BUY IT YOU OWN IT!YOU MADE A MISTAKE YOU OWN IT! LET THE BUYER BEWARE..... THERE IS NO RETURN POLICY.

GOOD LUCK! AND REMEMBER AN EDUCATED CONSUMER IS OUR BEST CUSTOMER.

****BIDDING IS OPEN TO THE GENERAL PUBLIC****

7201 Used 2016 Kia Sedona Kndmb5e11g6188323

Miles: 193,207
Color: White
Engine: V6, 3.3

Automatic transmission, grey cloth interior, dual climate control, rear climate control, AM/FM radio CD; climate control, steering wheel mount controls, cruise control, automatic headlight, power driver seat, power windows; third row seating, full Back seat; rear stow n go seating, power sliding doors, aluminum rims



Condition report: small chips, scratches and scrapes on front bumper; holes in front bumper; small scratches and scrapes throughout ; Driver door heavy scratches around door handle; multiple small paint chip/rock chips; side rear slider has paint work, bodywork and cracking; spray paint over problems; quarter panel that large paint chips and cracking paint; rear quarter panel is a different color; rear bumper has heavy scratches throughout; trunk has small paint chips throughout ; quarter panel large scuff marks, scratches throughout passenger side; rear quarter panel small rock chips& small paint chips; passenger side slider door has heavy scratches around door handle & small scuff marks; front door has heavy scratches throughout ; side front fender has small paint imperfection with rock chips, small paint chips; passenger side slider door has heavy scratches around door handle; small scuff marks ; front door has heavy scratches throughout; side front fender small paint imperfection.

May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending todays auction, please visit our website for the most up to date conversation!

LOT #

****3 OPEN RECALLS**** IF THE DOOR CLOSES ON AN OCCUPANT, THERE IS AN INCREASED RISK OF AN INJURY. 2) A TURN SIGNAL ACTIVATING IN THE OPPOSITE DIRECTION OF WHAT WAS INTENDED BY THE DRIVER INCREASES THE RISK OF A CRASH. 3) IF A CHILD IS IN A CHILD SEAT IN THE FRONT SEAT, A BROKEN ODS WIRING HARNESS WILL NOT PREVENT THE FRONT PASSENGER AIR BAG FROM DEPLOYING IN THE EVENT OF A CRASH, INCREASING THE RISK OF INJURY TO THE CHILD.

Do Not Bid From The Pictures
You Must Inspect The Vehicle In Person On Saturday,
May 9th, 2026. Beginning At 8am Est. This Unit Is

Being Sold At Auction,
Auction Units Can Offer The Best Value,
However They Can Bear The Greatest Risk!
An Auction Vehicle Often May Have Condition Or Mechanical Issues.

There Are No Warranties Or Guarantees.
You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You.
This Vehicle Is Sold "as-is..... You Buy It You Own It! You Made A Mistake You Own It! Let The Buyer Beware..... There Is No Return Policy. Good Luck! And Remember An Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL PUBLIC****

LOT #

DISPLAY A BLANK OR DISTORTED IMAGE ON THE CENTER DISPLAY SCREEN WHEN THE VEHICLE IS IN REVERSE

Condition report: put as large rust spot on hood rack Tipton paint tips Bumper has scratch it scrapes driver side front fender has paint and protections on edge Driver door has rough starting to form scratches throughout driver side rear door has multiple scratches paint and perfection driver side rear quarter panel is paint imperfections and clearcoat scratches and scrapes your trunk has heavy scratches paint and perfection rear bumper cover is this colored tighter quarter panel has stuffed marks scratches out pee cap passenger door has scratches on door handle scratches throughout the front door dent with paint and perfections passenger side front Binder has scrapes and scratches

Do Not Bid From The Pictures
You Must Inspect The Vehicle In Person On Saturday,
May 9th, 2026. Beginning At 8am Est. This Unit Is

Being Sold At Auction,
Auction Units Can Offer The Best Value,
However They Can Bear The Greatest Risk!
An Auction Vehicle Often May Have Condition Or Mechanical Issues.

There Are No Warranties Or Guarantees.
You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You.
This Vehicle Is Sold "as-is..... You Buy It You Own It! You Made A Mistake You Own It! Let The Buyer Beware..... There Is No Return Policy. Good Luck! And Remember An Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL PUBLIC****

7251 USED 2015 Ford Escape 1FMCU9GX8FUA97325

Miles: 74,547
Color: Gray
Engine: I4, 1.6 T



Automatic transmission, gray and black off interior, radio speed, wheel monitor controls, cruise control, automatic lights, power windows locked, aluminum rims

****OPEN RECALL**** ON YOUR VEHICLE, THE REAR VIEW CAMERA COULD

May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending todays auction, please visit our website for the most up to date conversation!

LOT #

7219 USED 2014 Jeep Wrangler Unlim 1C4BJWDG6EL232480

Miles: 183,343

Color: Orange

Engine: V6, 3.6

Automatic transmission, four-wheel-drive, black cloth interior, AM/FM radio with CD, steering wheel monitor control, cruise control, power windows power locks; 4 door with hard top and soft top; aluminum rims



Condition report: small paint chips and scratches throughout ; front Bumper has scrapes; small scratches on guard small rock chips throughout; small corrosion on door handles; heavy scratches and scrapes throughout ; small scratches over rear fender; bumper small scuff marks; trunk small scratches; back quarter panel small scratches above and on plastic; small scratches passenger side rear door; small chips and paint on passenger side; front door has small scratches throughout; passenger side front fender has small paint imperfections.

Do Not Bid From The Pictures

You Must Inspect The Vehicle In Person On

Saturday,

May 9th, 2026. Beginning At 8am Est. This Unit

Is

Being Sold At Auction,

Auction Units Can Offer The Best Value,

However They Can Bear The Greatest Risk!

An Auction Vehicle Often May Have Condition

Or Mechanical Issues.

There Are No Warranties Or Guarantees.

You Must Inspect The Vehicle In Person And

Determine If This Is The Right Vehicle For You.

This Vehicle Is Sold "as-is..... You Buy It

You Own It! You Made A Mistake You

Own It! Let The Buyer Beware..... There Is No

Return Policy. Good Luck! And Remember An

Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL**

PUBLIC**

LOT #


7216 Takeuchi Tb180 Fr

Takeuchi Tb180 Two Speed, Rubber Track's

Diesel Zero Tail Swing Heat Cab, External

Valve Push Blade Hydraulic Boom Swing

Construction Grating Over Windows



7221 USED 2009 Mazda CX-9 JM3TB38V790174547

Miles: 210,825

Color: Black

Engine: V6, 3.7

Automatic transmission, AWD,black leather interior, dual climate control, heated seats, AM/FM radio with CD, moonroof, steering wheel monitor controls, cruise control, power driver seat power windows power locks, third row seating, rear climate control, hitch receiver



Condition report: multiple small paint bubbles and scratches throughout; scratched chrome; driver side front fender has small scratches and scrapes; Driver door has small scratches, scrapes large dents; heavy scratches around door handles; large paint chip on door; multiple small paint chips & heavy scratch through door; rear quarter panel has heavy scratches around fuel cap; large paint imperfection throughout; rear bumper cover has heavy scratches; large scratches and scrapes passenger side; front fender small scratches by head light

Do Not Bid From The Pictures

You Must Inspect The Vehicle In Person On

Saturday,

May 9th, 2026. Beginning At 8am Est. This Unit

Is

Being Sold At Auction,

Auction Units Can Offer The Best Value,

However They Can Bear The Greatest Risk!

An Auction Vehicle Often May Have Condition

Or Mechanical Issues.

There Are No Warranties Or Guarantees.

You Must Inspect The Vehicle In Person And

Determine If This Is The Right Vehicle For You.

This Vehicle Is Sold "as-is..... You Buy It

You Own It! You Made A Mistake You

Own It! Let The Buyer Beware..... There Is No

Return Policy. Good Luck! And Remember An

Educated Consumer Is Our Best Customer.

May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending todays auction, please visit our website for the most up to date conversation!

LOT #

BIDDING OPEN TO THE GENERAL PUBLIC

7245 Used 2008 Toyota Highlander Jtees43a882020438

Miles: 148,465
Color: Gray
Engine: V6, 3.5

Automatic transmission, four-wheel-drive, gray leather interior, key seats, AM FM radio CD, moonroof, steering wheel monitor controls, cruise ; automatic headlights, power driver seat, power windows power lock, rear climate control; third row seating, aluminum rims, roof rack, hitch receiver



Condition report: front bumper has large scrapes, scratches large scuff marks with scratches throughout; paint imperfections; front fender has scratches and scrapes throughout; Driver door has large rock chips; Driver side rear door large dents, heavy large door dings with scratches; quarter panel has large scratches over wheel well; large scratches by tail light; trunk has rust starting to form, paint starting to bubble; rear bumper has scrapes; & scratches; small dents ; driver side rear quarter panel has scratches; wheel wells passenger side rear door has scratches throughout; paint chips throughout; passenger front door has scratches in the middle of the door; small chips passenger side; front has a dent with scuff mark marks and scratch

Do Not Bid From The Pictures
You Must Inspect The Vehicle In Person On Saturday,
May 9th, 2026. Beginning At 8am Est. This Unit Is
Being Sold At Auction,
Auction Units Can Offer The Best Value,
However They Can Bear The Greatest Risk!
An Auction Vehicle Often May Have Condition Or Mechanical Issues.
There Are No Warranties Or Guarantees.
You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You.
This Vehicle Is Sold "as-is..... You Buy It You Own It! You Made A Mistake You Own It! Let The Buyer Beware..... There Is No

LOT #

Return Policy. Good Luck! And Remember An Educated Consumer Is Our Best Customer.

BIDDING OPEN TO THE GENERAL PUBLIC

7210 USED 2015 Dodge Dart 1C3CDFB2FD237145

Miles: 95,632
Color: Red
Engine: I4, 2.4

Automatic transmission, black cloth interior, AM/FM radio with CD, steering wheel monitor controls, cruise control, power windows power locks, aluminum rims



Condition Report: multiple small heavy scratches; front bumper heavy scuff and scrapes; front small scratches; rust starting to form at bottom driver door; scratches around door handle; driver side door has small scratches and paint chips throughout; scratches around door handle; small rock chip at bottom; small dent w/large paint imperfections and scratches; large dent above rear tail light; rear bumper has heavy scuff mark & scratches; large scratches under Bumper and scrapes on fuel cap; small scratches throughout; side door has heavy scratches in the middle; multiple scratches around door handle; heavy scratches in the middle of door; passenger side front door heavy scratches; small scratches and scrapes

2 OPEN RECALLS Replace the transmission shift cable bushing on the transmission end of the shifter cable. & shift cable failure

Do Not Bid From The Pictures
You Must Inspect The Vehicle In Person On Saturday,
May 9th, 2026. Beginning At 8am Est. This Unit Is
Being Sold At Auction,
Auction Units Can Offer The Best Value,
However They Can Bear The Greatest Risk!
An Auction Vehicle Often May Have Condition Or Mechanical Issues.
There Are No Warranties Or Guarantees.
You Must Inspect The Vehicle In Person And

May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending todays auction, please visit our website for the most up to date conversation!

LOT #

Determine If This Is The Right Vehicle For You.
This Vehicle Is Sold "as-is..... You Buy It
You Own It! You Made A Mistake You
Own It! Let The Buyer Beware..... There Is No
Return Policy. Good Luck! And Remember An
Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL
PUBLIC****

7236 Repo 2016 Jeep Compass 1c4njcba3gd615431

Miles: 134,010

Color: Black

Engine: I4, 2

Automatic transmission, black cloth interior,
AM/FM radio with CD, monitor controls, cruise
control, tilt wheel, automatic headlights, roof
rack,



Condition report: hood has large scratches
throughout smaller rack tips on edge from
Bumper has small rack chips missing on driver
side front fender has scratches throughout small
dent driver door has small scratches dent on
edge door dent around door handle driver side
rear door has done on body line scratches
throughout rack tips throughout side for quarter
panel and scratches around fuel cap racks on
fuel cap air Bumper has scuff marks and
scratches your Bumper a small mix and scrapes
for your trunk that has heavy scratches dense
throughout but side rear bumper has large
scratches on their tail light messing ref and rear
bumper side rear quarter panel has multiple
scratches paint starting the bubble small bent
passenger side rear door scratches small bun and
rack chips throughout size front door small dent
by mirror scratches and racks passenger side
front fender large and small scratch scratches
throughout front bumper large scratches.

**DO NOT BID ON THIS VECHICLE FROM
THE PICTURES**

**YOU MUST INSPECT THE VEHICLE IN
PERSON ON Saturday, MAY 9TH, 2026.**

Beginning at 8am Eastern Time

This Unit Is A Repossessed Vehicle!

Repossessed Vehicles can offer a Best Value,
however they can bear The Greatest Risk!

LOT #

Each repossessed vehicle will have New York
State REPO papers you can ONLY register this
unit in New York State, You Can "NOT???"
Register It Out Of New York State
A Repossessed Vehicle often has condition or
mechanical issues. There are NO
WARRANTIES or GUARANTEES. This
vehicle came from someone who couldn't pay
for it, so maintenance and upkeep was not the
prior owner priority
YOU MUST INSPECT THE VEHICLE in
person and determine if this is the right vehicle
for you.

THIS VEHICLE IS SOLD "AS-IS.....YOU
BUY IT YOU OWN IT!YOU MADE A
MISTAKE YOU OWN IT! LET THE BUYER
BEWARE..... THERE IS NO RETURN
POLICY.
GOOD LUCK! AND REMEMBER AN
EDUCATED CONSUMER IS OUR BEST
CUSTOMER.

****BIDDING IS OPEN TO THE GENERAL
PUBLIC****

7207 Used 2016 Jeep Compass 1c4njdeb9gd542396

Miles: 99,785

Color: Red

Engine: I4, 2.4

Automatic transmission, four-wheel-drive, black
leather and cloth seats, heated seats, MFM radio
with CD, steering wheel monitor controls, cruise
control, automatic headlights, power windows
power lock aluminum rims, roof rack,



Condition report: Multiple small scratches and
scrapes throughout; side front fender has large
scratches throughout ; aluminum rims are pitting
and peeling; passenger side door heavy scratch
under door handle; small rock chips at bottom;
side door small scratches rock chips at bottom;
front starting to crack; Driver quarter panel has
heavy scratches; rear bumper has heavy scuff
marks and scrapes; multiple small chips;
Bumper scrapes; marks rear quarter panel; rust
forming; front door small scratches and paint
imperfection ; front fender large dent; scratches
on front hood starting to bubble; Rear quarter
panel rust forming; Rust active front door;

May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending todays auction, please visit our website for the most up to date conversation!

LOT #

small scratches and paint imperfections, scratches on front Fender, large dent by antenna pier; front bumper headlights scratched; the front hood is starting to bubble.

Do Not Bid From The Pictures
 You Must Inspect The Vehicle In Person On Saturday, May 9th, 2026. Beginning At 8am Est. This Unit Is Being Sold At Auction, Auction Units Can Offer The Best Value, However They Can Bear The Greatest Risk! An Auction Vehicle Often May Have Condition Or Mechanical Issues. There Are No Warranties Or Guarantees. You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You. This Vehicle Is Sold "as-is..... You Buy It You Own It! You Made A Mistake You Own It! Let The Buyer Beware..... There Is No Return Policy. Good Luck! And Remember An Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL PUBLIC****

LOT #

side front has small dent with paint imperfections

Do Not Bid From The Pictures
 You Must Inspect The Vehicle In Person On Saturday, May 9th, 2026. Beginning At 8am Est. This Unit Is Being Sold At Auction, Auction Units Can Offer The Best Value, However They Can Bear The Greatest Risk! An Auction Vehicle Often May Have Condition Or Mechanical Issues. There Are No Warranties Or Guarantees. You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You. This Vehicle Is Sold "as-is..... You Buy It You Own It! You Made A Mistake You Own It! Let The Buyer Beware..... There Is No Return Policy. Good Luck! And Remember An Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL PUBLIC****

7239 USED 2015 Ford C-MAX Hybrid 1FADP5AU7FL117955

Miles: 68,556
 Color: Red
 Engine: I4, 2
 Auto transmission, hybrid, grey cloth interior, heated seats, dual climate control, AM/FM radio with Sirius, steering wheel monitor control controls, cruise control, headlights, power windows power lock, aluminum rims,



Condition report: paint chips, small scratches; Bumper has scrapes and scratches throughout ; small paint chips & rock chip at the bottom; Driver door has rock chips at the bottom dent in middle of door; driver side rear quarter panel has scuffed marks and scratches with chipping; rear quarter panel has scratches and scrapes; rear bumper scratches, scrapes, and nicks; paint starting to peel and bubble; side rear quarter panel scratched; and scratched fuel cap; rear door has active rust; front door has chips on bottom of door & small scratches; passenger

7205 Used 2014 Kia Soul Kndjp3a5xe7714258

Miles: 115,863
 Color: Silver
 Engine: I4, 2
 Automatic transmission, black cloth interior, AM/FM radio SiriusXM, Bluetooth capabilities, steering wheel monitor controls, cruise control, tilt wheel, power windows power locks aluminum rims,



Condition report: multiple small paint chips and scratches through out; small rust spots forming; Bumper has small scrapes and scratches throughout; driver side front fender has smaller paint chips, scratches; driver door has small rock chips at bottom; small scratches; driver side rear door has paint peeling on edge; multiple small scratches and scrapes; rear bumper has small scuff marks; trunk has rust starting to form; rust is bubbling; overspray on plastic rear quarter panel; scratches under headlight; multiple small dents scratches through out ; passenger side front door has multiple small scratches and scrapes

May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending todays auction, please visit our website for the most up to date conversation!

LOT #


****3 OPEN RECALLS** FRONT AIR BAGS THAT DO NOT DEPLOY AS INTENDED CAN INCREASE THE RISK OF INJURY IN A CRASH, 2) IF THE PINION GEAR SEPARATES, STEERING WILL BE LOST, INCREASING THE RISK OF A CRASH. 3) AN ENGINE COMPARTMENT FIRE INCREASES THE RISK OF INJURY.**

Do Not Bid From The Pictures
 You Must Inspect The Vehicle In Person On Saturday,
 May 9th, 2026. Beginning At 8am Est. This Unit Is Being Sold At Auction,
 Auction Units Can Offer The Best Value, However They Can Bear The Greatest Risk!
 An Auction Vehicle Often May Have Condition Or Mechanical Issues.
 There Are No Warranties Or Guarantees.
 You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You.
 This Vehicle Is Sold "as-is..... You Buy It You Own It! You Made A Mistake You Own It! Let The Buyer Beware..... There Is No Return Policy. Good Luck! And Remember An Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL PUBLIC****

7266 USED 2016 Ford F-150 1FTEX1EP8GFA52075

Miles: 186,861
 Color: Green
 Engine: V6, 2.7 TT
 Automatic transmission, four-wheel-drive, automatic headlights, power mirrors, power locks, power windows, tilt steering wheel, steering wheel monitor controls, cruise control, AM/ FM radio with CD player, Blue tooth available, traction control, grey cloth interior, work floor mats, aluminum rims, fog lights.



****OPEN RECALL ** THIS MAY RESULT IN A LOSS OF VEHICLE CONTROL, INCREASING THE RISK OF A CRASH.**

****OPEN RECALL ** THIS MAY RESULT IN**

LOT #

A LOSS OF VEHICLE CONTROL, INCREASING THE RISK OF A CRASH.

Condition report: hood is heavily scratched, minor scratches, and paint imperfections on front bumper, multiple light scratches on driver side front fender, multiple minor scratches, and paint imperfections on driver side doors, minor scratching on driver side of bed, large dent on rear bumper, multiple scuffs and minor scratches on tailgate, multiple minor scratches on passenger side of bed, small dent on passenger side cab corner, multiple dents on passenger side doors, and minor scratches, minor scratches on passenger front fender, driver seat, cushion is heavily worn, multiple burn holes in driver front seat

Do Not Bid From The Pictures
 You Must Inspect The Vehicle In Person On Saturday,
 May 9th, 2026. Beginning At 8am Est. This Unit Is Being Sold At Auction,
 Auction Units Can Offer The Best Value, However They Can Bear The Greatest Risk!
 An Auction Vehicle Often May Have Condition Or Mechanical Issues.
 There Are No Warranties Or Guarantees.
 You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You.
 This Vehicle Is Sold "as-is..... You Buy It You Own It! You Made A Mistake You Own It! Let The Buyer Beware..... There Is No Return Policy. Good Luck! And Remember An Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL PUBLIC****

7206 Used 2016 Kia Forte Knafx4a86g5448996

Miles: 158,532
 Color: White
 Engine: I4, 2
 Automatic transmission, black and gray cloth interior, AM/FM radio CD, steering wheel monitor controls, cruise control, adaptive cruise control, automatic headlights, power windows power lock aluminum rims



May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending todays auction, please visit our website for the most up to date conversation!

LOT #


Condition report: paint scratches through out; Bumper small rock chips; front bumper /front fender small paint chips; Driver door has multiple small scratches and scrapes around door handle & black piece in between windows; driver side rear door has door handle missing; side rear quarter panel has small rust marks; quarter panel has heavy scratches and scrapes; side rear bumper has small scrapes scratches and dents; trunk has scratches; passenger side rear bumper small rock and paint chips throughout; side rear door handle is broken & missing; passenger door has small paint chips and rock chips; rust starting to form on bottom of rocker; Bumper paint chips

Do Not Bid From The Pictures
 You Must Inspect The Vehicle In Person On Saturday,
 May 9th, 2026. Beginning At 8am Est. This Unit Is
 Being Sold At Auction,
 Auction Units Can Offer The Best Value,
 However They Can Bear The Greatest Risk!
 An Auction Vehicle Often May Have Condition Or Mechanical Issues.
 There Are No Warranties Or Guarantees.
 You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You.
 This Vehicle Is Sold "as-is..... You Buy It You Own It! You Made A Mistake You Own It! Let The Buyer Beware..... There Is No Return Policy. Good Luck! And Remember An Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL PUBLIC****

7217 Komatsu Pc88mr-8 S/n5588

Komatsu Pc88mr-8 S/n5588, Diesel Engine, 7050 Hrs Cabinet Unit Radio Panel Ac, Heat, Hydraulic Thumb, Quick Attached, External Ports, Push Plate, Rubber Tracks, Zero Swing,



LOT #

7208 Used 2015 Chevrolet Traverse 1gnkvfd7fj354360

Miles: 142,041
 Color: Grey
 Engine: V6, 3.6
 Automatic transmission, all-wheel-drive gray cloth interior, radio CD, backup camera, XM capabilities, steering wheel monitor controls, cruise control, automatic headlights, power windows & locks, third row seating, aluminum rims, roof rack,



Condition report:
 chips in front of hood; bumper small scrapes & scratches; heavy scratches under headlight; driver side front fender has small rock chips and paint chips throughout with small paint imperfections; Driver door has multiple small scratches; small scuff marks; door with rock chips at bottom; passenger side door has heavy scratches around door handle; multiple small paint chips; paint on quarter panel starting to wear off; multiple scratches over fuel cap; rear bumper has heavy scuff marks and small cracking ; heavy scratches and scrapes throughout; quarter panel is heavily scratched; large paint chipped on the driver side; door has small scrapes and scratches throughout passenger side door; small dent under plastic trim; multiple smaller scratches along passenger side; fender small paint chips and scratches

****OPEN RECALL**** Dealers will replace the front-driver airbag module.

Do Not Bid From The Pictures
 You Must Inspect The Vehicle In Person On Saturday,
 May 9th, 2026. Beginning At 8am Est. This Unit Is
 Being Sold At Auction,
 Auction Units Can Offer The Best Value,
 However They Can Bear The Greatest Risk!
 An Auction Vehicle Often May Have Condition Or Mechanical Issues.
 There Are No Warranties Or Guarantees.
 You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You.
 This Vehicle Is Sold "as-is..... You Buy It You Own It! You Made A Mistake You Own It! Let The Buyer Beware..... There Is No Return Policy. Good Luck! And Remember An Educated Consumer Is Our Best Customer.

May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending todays auction, please visit our website for the most up to date conversation!

LOT #

BIDDING OPEN TO THE GENERAL PUBLIC

7248 USED 2015 Kia Sedona KNDMB5C17F6076141

Miles: 108,210
Color: Silver
Engine: V6, 3.3

Automatic transmission, grey cloth interior, heated seats, AM/FM radio with CD, rear power sliding doors, steering wheel monitor controls, cruise control, tilt wheel, power windows power lock, rear climate control, third row seating, aluminum rims,



Condition report :paint chips and scratches throughout; front grill has scratches scrapes and dents;front bumper/grill has duct tape; front fender has rock chips, bottom scrapes and scratches; Driver door scratched through door; scratches around door handle; rock chips at bottom, paint imperfections; rear door has scratches on door handle; small paint scratches at bottom; rear quarter panel rock chips; scratches around fuel cap; rear bumper scuff marks, scrape, scratches; trunk scratched; rear bumper cover has scratches and scrapes; side panel has scratches and scrapes through out; scratches to metal; door small rock chip at bottom; front door has large scratches throughout ; front wheel well has small scratch; front bumper has large crack with blue paint stripes.

Do Not Bid From The Pictures
You Must Inspect The Vehicle In Person On Saturday,
May 9th, 2026. Beginning At 8am Est. This Unit Is
Being Sold At Auction,
Auction Units Can Offer The Best Value,
However They Can Bear The Greatest Risk!
An Auction Vehicle Often May Have Condition Or Mechanical Issues.
There Are No Warranties Or Guarantees.
You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You.
This Vehicle Is Sold "as-is..... You Buy It You Own It! You Made A Mistake You

LOT #

Own It! Let The Buyer Beware..... There Is No Return Policy. Good Luck! And Remember An Educated Consumer Is Our Best Customer.

BIDDING OPEN TO THE GENERAL PUBLIC

7209 Used 2011 Subaru Impreza Jf1ge6a62bh514559

Miles: 140,884
Color: Red
Engine: H4, 2.5

Automatic transmission, all-wheel-drive, black cloth interior, AM/FM radio with CD, cruise control, power windows power lax, roof rack, Condition report multiple small imperfections throughout small Bumper small scratches small stretches small scratches pink imperfections on his perfection edge small Driver center recorder Bumper Sketch and scrapes. Stock marks throughout side rear bumper has small stock mark small large stance quarter panel heavy scratches large tape throughout multiple large rock chips heavy scratches and quarter panel passenger side rear door heavy scratches and scrapes the front door small above door handle multiple small racks paint tips passenger side front fender and small scrapes bumper and slide scratches small small paint imperfections



Do Not Bid From The Pictures
You Must Inspect The Vehicle In Person On Saturday,
May 9th, 2026. Beginning At 8am Est. This Unit Is
Being Sold At Auction,
Auction Units Can Offer The Best Value,
However They Can Bear The Greatest Risk!
An Auction Vehicle Often May Have Condition Or Mechanical Issues.
There Are No Warranties Or Guarantees.
You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You.
This Vehicle Is Sold "as-is..... You Buy It You Own It! You Made A Mistake You Own It! Let The Buyer Beware..... There Is No Return Policy. Good Luck! And Remember An Educated Consumer Is Our Best Customer.

**BIDDING OPEN TO THE GENERAL

May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending todays auction, please visit our website for the most up to date conversation!

LOT #

 PUBLIC**

LOT #

 Educated Consumer Is Our Best Customer.

 BIDDING OPEN TO THE GENERAL PUBLIC

7265 USED 2010 Acura TL 19UUA8F25AA019758

Miles: 155,529
 Color: Silver
 Engine: V6, 3.5



Automatic transmission, power mirrors, power locks, power windows, power front seats, driver seat memory system, tilt steering wheel, steering wheel monitor controls, cruise control, traction control, dual climate control, heated front seats, AM/FM radio with CD player, Blue tooth and Sirius XM available, sunroof, black leather interior, aluminum rims, fog lights

Condition report: multiple minor scratches and imperfections on hood, multiple heavy scratches, minor chips, and large, heavy scuffs on front bumper, large dent with paint damage with multiple paint chips on drivers side, front fender, multiple minor scratches on driver side doors, heavy corrosion with a hole on driver side quarter panel, multiple minor paint chips on rear bumper, small dent on passenger quarter panel, minor paint, imperfections, multiple minor, scuffs, and minor scratches on passenger side door doors, minor scratches, and chips on passenger front fender, front windshield weatherstripping is loose,, driver side door panel is slightly worn, center console is severely torn with previous substandard repair, small dent on driver side A pillar.

Do Not Bid From The Pictures
 You Must Inspect The Vehicle In Person On Saturday,
 May 9th, 2026. Beginning At 8am Est. This Unit Is Being Sold At Auction,
 Auction Units Can Offer The Best Value,
 However They Can Bear The Greatest Risk!
 An Auction Vehicle Often May Have Condition Or Mechanical Issues.
 There Are No Warranties Or Guarantees.
 You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You.
 This Vehicle Is Sold "as-is..... You Buy It You Own It! You Made A Mistake You Own It! Let The Buyer Beware..... There Is No Return Policy. Good Luck! And Remember An

7238 USED 2016 Cadillac CTS 1G6AP5SX0G0196543

Miles: 89,821
 Color: Grey
 Engine: I4, 2 T



Automatic transmission, gray cloth interior, dual climate control, AM radio, panoramic sunroof, three door garage memory, capabilities, paddle shifters, push to start, steering wheel monitor controls, automatic headlights, two seat memory, aluminum rims

Condition report: hood has scratches and scrapes throughout ; front edge of hood has small scratches; scratches, scrapes, large paint imperfections; driver side front fender has large dent with paint scratches on edge; Driver door has large dent large scratches throughout; driver rear door has tape like substance; edge door paint chips at bottom; rock chips at bottom; Driver quarter panel multiple dents on body line; heavy scratches throughout; rear bumper has large scrapes, scratches throughout; trunk has heavy scratches; passenger side quarter panel multiple small dings; scratches around fuel cap; passenger side rear door has small scratches and scrapes; marks scratches and paint imperfections; passenger side front fender has small imperfections, large scratches.

Do Not Bid From The Pictures
 You Must Inspect The Vehicle In Person On Saturday,
 May 9th, 2026. Beginning At 8am Est. This Unit Is
 Being Sold At Auction,
 Auction Units Can Offer The Best Value,
 However They Can Bear The Greatest Risk!
 An Auction Vehicle Often May Have Condition Or Mechanical Issues.
 There Are No Warranties Or Guarantees.
 You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You.
 This Vehicle Is Sold "as-is..... You Buy It You Own It! You Made A Mistake You

May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending todays auction, please visit our website for the most up to date conversation!

LOT #

Own It! Let The Buyer Beware..... There Is No Return Policy. Good Luck! And Remember An Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL PUBLIC****

LOT #

Own It! Let The Buyer Beware..... There Is No Return Policy. Good Luck! And Remember An Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL PUBLIC****

7240 USED 2011 Ford Escape 1FMCU0EG6BKA34616

Miles: 128,641
Color: Red
Engine: V6, 3



Automatic transmission, black leather interior, heated seat, radio CD, steering wheel monitor controls, cruise control, power driver seat, automatic headlights, power windows power locks, aluminum rims, roof rack,

Condition report: hood has multiple small paint chips and imperfection through out; front Bumper has small scrapes and scratches; front fender has small scratches and rock chips at the bottom; driver door has small scratches scrapes through out side; rear door paint chips, scratches & scrapes throughout; rear quarter panel has rust forming bubbles; fuel cap scratched; rear bumper has large nick, paint imperfections & scratches throughout; trunk lid has heavy scratches and glue like substance; passenger side rear has paint bubble on rear wheel well; passenger door has clear coat starting to peel; passenger side front door has clearcoat peeling small rock chip on bottom ; passenger side front fender has scratches scrapes and dings

Do Not Bid From The Pictures
You Must Inspect The Vehicle In Person On Saturday,
May 9th, 2026. Beginning At 8am Est. This Unit Is
Being Sold At Auction,
Auction Units Can Offer The Best Value,
However They Can Bear The Greatest Risk!
An Auction Vehicle Often May Have Condition Or Mechanical Issues.
There Are No Warranties Or Guarantees.
You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You.
This Vehicle Is Sold "as-is..... You Buy It You Own It! You Made A Mistake You

7222 USED 2017 Chevrolet Traverse 1gnkrgkdxhj298559

Miles: 147,333
Color: Black
Engine: V6, 3.6



Automatic transmission, black cloth interior, AM/FM radio with CD, three door garage memory, on star capabilities, steering wheel monitor controls, cruise control, automatic headlights, fog lights, power windows power locks, captain chairs, 3rd row seating; rear climate control, aluminum rims,hitch receiver

Condition report: small scratches throughout; small rocks chips on front; Bumper has small scratches; front fender small scratches throughout; small paint imperfections along edge; Driver door small scratches around door handle; small dent in the middle of the door; scratches around door handle; scratched door; quarter panel has scratches ; wheel well scratched; rear bumper has heavy imperfections and scratches; small scratches in the middle of door; scratches around door handle; front door small rock chips; door edge heavily scratched

Do Not Bid From The Pictures
You Must Inspect The Vehicle In Person On Saturday,
May 9th, 2026. Beginning At 8am Est. This Unit Is
Being Sold At Auction,
Auction Units Can Offer The Best Value,
However They Can Bear The Greatest Risk!
An Auction Vehicle Often May Have Condition Or Mechanical Issues.
There Are No Warranties Or Guarantees.
You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You.
This Vehicle Is Sold "as-is..... You Buy It You Own It! You Made A Mistake You Own It! Let The Buyer Beware..... There Is No Return Policy. Good Luck! And Remember An

May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending todays auction, please visit our website for the most up to date conversation!

LOT #

Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL PUBLIC****

7212 Repo 2020 Cadillac Xt4 1gyfzdr46lf032315

Miles: 68,219

Color: Gray

Engine: I4, 2 T

Auto, four-wheel-drive, black leather interior, dual climate control, AM/FM radio CD, backup camera, garage door memory, XM capability, paddle shifters, push to start, steering wheel monitor control, automatic headlights, power driver seat, power windows and locks, 2 seat memory, aluminum rims,



Condition Report: multiple small paint imperfections ; front fender has smaller paint chips ; Driver door has door protective guard on edge; small scratches around door handle; small scratches on driver side quarter panel; small scratches on edge; driver side bumper has a rust mark with paint missing; rear bumper has small paint imperfections and chips; quarter panel has small extra heavy scratches; passenger side front door has small scratches; passenger side front fender has small dent. scratches, and scrapes.

DO NOT BID ON THIS VEHICLE FROM THE PICTURES

YOU MUST INSPECT THE VEHICLE IN PERSON ON Saturday, MAY 9TH, 2026.

Beginning at 8am Eastern Time

This Unit Is A Repossessed Vehicle!

Repossessed Vehicles can offer a Best Value, however they can bear The Greatest Risk!

Each reposessed vehicle will have New York State REPO papers you can ONLY register this unit in New York State, You Can "NOT???"

Register It Out Of New York State

A Repossessed Vehicle often has condition or mechanical issues. There are NO

WARRANTIES or GUARANTEES. This vehicle came from someone who couldn't pay for it, so maintenance and upkeep was not the prior owner priority

YOU MUST INSPECT THE VEHICLE in

LOT #

person and determine if this is the right vehicle for you.

THIS VEHICLE IS SOLD "AS-IS.....YOU BUY IT YOU OWN IT!YOU MADE A MISTAKE YOU OWN IT! LET THE BUYER BEWARE..... THERE IS NO RETURN POLICY.

GOOD LUCK! AND REMEMBER AN EDUCATED CONSUMER IS OUR BEST CUSTOMER.

****BIDDING IS OPEN TO THE GENERAL PUBLIC****

7237 USED 2013 Kia Forte KNAFU4A25D5659171

Miles: 86,954

Color: White

Engine: I4, 2

Automatic transmission, black cloth interior, AM/FM radio with CD, SiriusXM capabilities, Bluetooth capabilities, steering wheel monitor controls, cruise control, tilt wheel, power locks



****OPEN RECALL** AN ENGINE COMPARTMENT FIRE WHILE PARKED OR DRIVING CAN INCREASE THE RISK OF INJURY.**

Condition report: small paint imperfections & small rust spots throughout; front bumper has small scrapes; front fender has rock chips and paint chipped on edge; driver door has scratches, scrapes throughout; small rock chips on bottom; driver rear door has small paint chips; Driver rear quarter panel has a rust mark rear bumper, and small scrapes and scratches; trunk has small scratches; rear quarter panel scratched and scraped throughout; passenger side rear door has scratches scrapes, small dent; passenger side front door has scratches; around door handle small scratches; bottom passenger side front fender has small scratches and scrapes

Do Not Bid From The Pictures

You Must Inspect The Vehicle In Person On Saturday,

May 9th, 2026. Beginning At 8am Est. This Unit Is

Being Sold At Auction,

May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending todays auction, please visit our website for the most up to date conversation!

LOT #

Auction Units Can Offer The Best Value,
 However They Can Bear The Greatest Risk!
 An Auction Vehicle Often May Have Condition
 Or Mechanical Issues.
 There Are No Warranties Or Guarantees.
 You Must Inspect The Vehicle In Person And
 Determine If This Is The Right Vehicle For You.
 This Vehicle Is Sold "as-is..... You Buy It
 You Own It! You Made A Mistake You
 Own It! Let The Buyer Beware..... There Is No
 Return Policy. Good Luck! And Remember An
 Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL
 PUBLIC****

LOT #

Is Being Sold At Auction,
 Auction Units Can Offer The Best Value,
 However They Can Bear The Greatest Risk!
 An Auction Vehicle Often May Have Condition
 Or Mechanical Issues.
 There Are No Warranties Or Guarantees.
 You Must Inspect The Vehicle In Person And
 Determine If This Is The Right Vehicle For You.
 This Vehicle Is Sold "as-is..... You Buy It
 You Own It! You Made A Mistake You
 Own It! Let The Buyer Beware..... There Is No
 Return Policy. Good Luck! And Remember An
 Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL
 PUBLIC****

7263 USED 2010 Nissan Murano JN8AZ1MW2AW122537

Miles: 148,731
 Color: Black
 Engine: V6, 3.5

Automatic transmission, all-wheel-drive, power
 mirrors, power locks, power windows, powered
 front seats, tilt steering wheel, steering wheel
 monitor controls, cruise control, a.m. FM radio
 with CD player, dual climate control, heated
 front seats, dual sunroof, black leather interior.
 Aluminum rims, fog lights.

Condition report: multiple chips and paint
 imperfections on hood, multiple scrapes, heavy
 scratches, scuffs, and paint imperfections on
 front bumper, multiple scratches on driver side,
 front fender, multiple scratches on driver side,
 front door, and rear door, multiple dings on
 driver side quarter panel, large area of cracked
 paint and rear bumper, rear bumper is fading,
 multiple paint imperfections on liftgate, multiple
 scratches on rear bumper, paint peeling on
 passenger quarter panel, multiple scuffs, and
 scratches on passenger rear door, multiple scuffs
 and paint and perfections and passenger front
 door, multiple minor scratches on passenger
 front fender, paint, peeling, and multiple areas
 on roof, large tear on driver seat.

Do Not Bid From The Pictures
 You Must Inspect The Vehicle In Person On
 Saturday,
 May 9th, 2026. Beginning At 8am Est. This Unit



7242 Used 2016 Nissan Altima 1n4al3ap3gc276432

Miles: 161,448
 Color: Black
 Engine: I4, 2.5

Automatic transmission, black leather interior,
 AM/FM radio with CD, push to start, paddle
 shifters, steering wheel monitor controls, cruise
 control, Tilt Wheel, Auto power windows power
 locks; aluminum rims

Condition report : rust bubble; front bumper has
 heavy scratches and small paint chips; chips on
 front bumper; driver side front fender has small
 scratches and scrapes; driver door has heavy
 scratches around door handle small scratches
 around door latch heavy scratches at bottom
 door ; driver side rear door has scratches around
 door handles ; large scratches through middle
 door; heavy scratches & paint chips on edge;
 paint starting to chip on edge; rear quarter panel
 has heavy scratches; fuel cap large scratches;
 paint rear bumper has small scratches and
 scrapes; small scuff marks on bumper w/ heavy
 scratches; trunk scratched throughout; heavy
 large scratch in the middle of Bumper; quarter
 panel has multiple light scratches, paint issues;
 edge has small rock chips; small dents on edge;
 body line passenger side rear door has dent in
 the middle of trim piece with paint missing;
 large scratches on door; passenger side front
 door large scratches throughout ; heavy
 scratches in the middle of the door; multiple



May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending todays auction, please visit our website for the most up to date conversation!

LOT #

small rock chips ; passenger side front fender has small chips,scrapes, scratches paint imperfection throughout; passenger side front bumper has scratches

Do Not Bid From The Pictures
 You Must Inspect The Vehicle In Person On Saturday,
 May 9th, 2026. Beginning At 8am Est. This Unit Is
 Being Sold At Auction,
 Auction Units Can Offer The Best Value,
 However They Can Bear The Greatest Risk!
 An Auction Vehicle Often May Have Condition Or Mechanical Issues.
 There Are No Warranties Or Guarantees.
 You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You.
 This Vehicle Is Sold "as-is..... You Buy It You Own It! You Made A Mistake You Own It! Let The Buyer Beware..... There Is No Return Policy. Good Luck! And Remember An Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL PUBLIC****

7241 Used 2011 Toyota Highlander 5tdbk3eh8bs083910

Miles: 18,316
 Color: Gray
 Engine: V6, 3.5
 Automatic transmission, four-wheel-drive, black leather interior, heated seats, radio CD, moonroof, three door garage memory, steering wheel monitor controls, cruise control, tilt wheel, automatic headlights, power mirrors, power windows power lock, third row seating, rear climate control, aluminum rims, roof rack



Condition report: multiple scratches, small paint chips and rock chips; Bumper has scratches; scrapes; large scratches on edge of front fender; driver doors have scratches throughout both; small rock chips; Driver door has scratches on through door horizontally and vertically with paint chipped on edge door side door scratches around door handle large scratches throughout middle of door with doors edge door has large scratches driver side quarter panel hits heavy

LOT #


scratch it they run through the quarter panel with heavy scratches fuel cap bumper heads large scratches scrapes heavy scratch it painter starting to form where your trunk paint starting to bubble tire rear quarter panel has scratches and scrapes through and small scratches they run horizontally small paint and perfections passenger side rear door has small dent at bottom of door scratches and paint chips throughout passenger side front door has large door scoops heavy scratches paint chips through our passenger side front fender has scratches scrapes paint and perfection and clearcoat

Do Not Bid From The Pictures
 You Must Inspect The Vehicle In Person On Saturday,
 May 9th, 2026. Beginning At 8am Est. This Unit Is
 Being Sold At Auction,
 Auction Units Can Offer The Best Value,
 However They Can Bear The Greatest Risk!
 An Auction Vehicle Often May Have Condition Or Mechanical Issues.
 There Are No Warranties Or Guarantees.
 You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You.
 This Vehicle Is Sold "as-is..... You Buy It You Own It! You Made A Mistake You Own It! Let The Buyer Beware..... There Is No Return Policy. Good Luck! And Remember An Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL PUBLIC****

7215 2018 Bobcat E85 S/n B4811407

2018 Bobcat E85 S/n B4811407 3856 Hrs Cab Air Heat, Bobcat Radio, Rubber Track , Front Bush Light,front Push Blade, Dual Lift Cylinders, Bobcat Quick Attached, Hydraulic Thumb, 24 Inch Digging Bucket, Zero Tail Swing Diesel Motor



May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending today's auction, please visit our website for the most up to date conversation!

LOT #

7269 REPO 2018 Honda Pilot 5FNYP6H58JB073494

Miles: 131,742
Color: White
Engine: V6, 3.5



Automatic transmission, automatic headlights, power mirrors, power windows, power locks, tilt steering wheel, steering wheel monitor controls, cruise control, touchscreen stereo with AM/FM radio, Bluetooth and SiriusXM available, sunroof, dual climate control, heated front seats, USB auxiliary ports, black leather interior, third row seating, aluminum rims, hitch receiver, fog lights,

Condition report: minor imperfections on hood, minor scratches on front bumper, minor scratches on driver side, front and rear door, minor scratch on driver side quarter panel, minor scratches on liftgate, heavy scratches, and multiple paint chips on rear bumper, minor scratches and imperfections on passenger quarter panel rear door, and front door, small scrape, and passenger mirror.

DO NOT BID ON THIS VEHICLE FROM THE PICTURES

YOU MUST INSPECT THE VEHICLE IN PERSON ON Saturday, MAY 9TH, 2026.

Beginning at 8am Eastern Time

This Unit Is A Repossessed Vehicle!

Repossessed Vehicles can offer a Best Value, however they can bear The Greatest Risk!

Each reposessed vehicle will have New York State REPO papers you can ONLY register this unit in New York State, You Can "NOT???"

Register It Out Of New York State

A Repossessed Vehicle often has condition or mechanical issues. There are NO

WARRANTIES or GUARANTEES. This vehicle came from someone who couldn't pay for it, so maintenance and upkeep was not the prior owner priority

YOU MUST INSPECT THE VEHICLE in person and determine if this is the right vehicle for you.

THIS VEHICLE IS SOLD "AS-IS.....YOU BUY IT YOU OWN IT!YOU MADE A MISTAKE YOU OWN IT! LET THE BUYER BEWARE..... THERE IS NO RETURN POLICY.

GOOD LUCK! AND REMEMBER AN EDUCATED CONSUMER IS OUR BEST

LOT #

CUSTOMER.

BIDDING IS OPEN TO THE GENERAL PUBLIC

7268 REPO 2019 Mitsubishi Outlander Spor JA4AR3AU2KU0028

Miles: 106,501
Color: Black
Engine: I4, 2



Automatic transmission, four-wheel-drive, black cloth interior, AM/FM radio, steering wheel controls, cruise control, automatic headlights, power windows power lights aluminum rims

Condition report for scratches and rakes throughout from Bumper scratch large cracks falling out there is a thunder paint perfection have scratches around door handle rock chips paint chips on edge driver rear door scratches around door handle rock chips chips heavy scratches your door heavy scratches or bumper heavy scratches and scrapes and scratches scrapes passenger cyber chips at edge heavy scratches on a quarter panel passenger side rear door has small dense large scratches front door and paint a small damage with that bumper and driver passenger side not connected

DO NOT BID ON THIS VEHICLE FROM THE PICTURES

YOU MUST INSPECT THE VEHICLE IN PERSON ON Saturday, MAY 9TH, 2026.

Beginning at 8am Eastern Time

This Unit Is A Repossessed Vehicle!

Repossessed Vehicles can offer a Best Value, however they can bear The Greatest Risk!

Each reposessed vehicle will have New York State REPO papers you can ONLY register this unit in New York State, You Can "NOT???"

Register It Out Of New York State

A Repossessed Vehicle often has condition or mechanical issues. There are NO

WARRANTIES or GUARANTEES. This vehicle came from someone who couldn't pay for it, so maintenance and upkeep was not the prior owner priority

YOU MUST INSPECT THE VEHICLE in person and determine if this is the right vehicle for you.

May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending todays auction, please visit our website for the most up to date conversation!

LOT #

THIS VEHICLE IS SOLD "AS-IS.....YOU BUY IT YOU OWN IT!YOU MADE A MISTAKE YOU OWN IT! LET THE BUYER BEWARE..... THERE IS NO RETURN POLICY.
GOOD LUCK! AND REMEMBER AN EDUCATED CONSUMER IS OUR BEST CUSTOMER.

****BIDDING IS OPEN TO THE GENERAL PUBLIC****

7270 REPO 2017 Hyundai SANTA FE Sport 5NMZT3LB0HH041091

Miles: 162,555
Color: Black
Engine: I4, 2.4

Automatic transmission, automatic headlights, power mirrors, power locks, power windows, tilt steering wheel, steering wheel monitor controls, cruise control, touchscreen stereo with AM/FM radio, and CD player, Bluetooth and SiriusXM available, USB auxiliary ports, great cloth interior, aluminum rims,



Condition report: multiple large dents with paint damage on hood, multiple paint chips on hood, multiple large, scuffs, scrapes, and paint imperfections and front bumper, multiple minor scratches on driver side front door, multiple small dents with paint damage on driver side front door, driver side mirror is cracked, paint peeling multiple scuffs, and minor scratches on driver side rear door, multiple small dents on driver side quarter panel, large, heavy, scratching, and peeling of paint on rear bumper, minor scratches on liftgate, minor scratches, and multiple dings on passenger quarter panel, minor scratches on passenger rear door, and front door, passenger side mirror is broken needs to be replaced, large scuffs, and multiple minor scratches on passenger front fender, multiple paint chips and corrosion on roof, small burn hole on driver seat

DO NOT BID ON THIS VEHICLE FROM THE PICTURES
YOU MUST INSPECT THE VEHICLE IN PERSON ON Saturday, MAY 9TH, 2026.

LOT #

Beginning at 8am Eastern Time
This Unit Is A Repossessed Vehicle!
Repossessed Vehicles can offer a Best Value, however they can bear The Greatest Risk!
Each repossessed vehicle will have New York State REPO papers you can ONLY register this unit in New York State, You Can "NOT???" Register It Out Of New York State
A Repossessed Vehicle often has condition or mechanical issues. There are NO WARRANTIES or GUARANTEES. This vehicle came from someone who couldn't pay for it, so maintenance and upkeep was not the prior owner priority
YOU MUST INSPECT THE VEHICLE in person and determine if this is the right vehicle for you.

THIS VEHICLE IS SOLD "AS-IS.....YOU BUY IT YOU OWN IT!YOU MADE A MISTAKE YOU OWN IT! LET THE BUYER BEWARE..... THERE IS NO RETURN POLICY.
GOOD LUCK! AND REMEMBER AN EDUCATED CONSUMER IS OUR BEST CUSTOMER.

****BIDDING IS OPEN TO THE GENERAL PUBLIC****

7271 USED 2019 Nissan Kicks 3N1CP5CU8KL527331

Miles: 131,166
Color: Black
Engine: I4, 1.6

Automatic transmission, automatic headlights, power mirror, power windows, power locks, tilt steering wheel, steering wheel monitor controls, cruise control, touchscreen stereo with AM/FM radio, Bluetooth and SiriusXM available, three USB ports, traction control, black cloth interior, aluminum rims,



Condition report: multiple paint chips and minor scratches on hood, heavy, scratching, and fading on front bumper, minor scratches on driver side, front door, and rear door, minor scratches on driver side quarter panel, multiple scratches on liftgate, minor scratches on passenger rear door, and front door, multiple small paint ships on passenger front fender, corrosion, and multiple

May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending todays auction, please visit our website for the most up to date conversation!

LOT #

paint chips on roof.

Do Not Bid From The Pictures

You Must Inspect The Vehicle In Person On

Saturday,

May 9th, 2026. Beginning At 8am Est. This Unit

Is Being Sold At Auction,

Auction Units Can Offer The Best Value,

However They Can Bear The Greatest Risk!

An Auction Vehicle Often May Have Condition

Or Mechanical Issues.

There Are No Warranties Or Guarantees.

You Must Inspect The Vehicle In Person And

Determine If This Is The Right Vehicle For You.

This Vehicle Is Sold "as-is..... You Buy It

You Own It! You Made A Mistake You

Own It! Let The Buyer Beware..... There Is No

Return Policy. Good Luck! And Remember An

Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL**

PUBLIC**

LOT #

imperfections; passenger side front door paint

chipped; passenger side front fender has paint

Imperfections.

Do Not Bid From The Pictures

You Must Inspect The Vehicle In Person On

Saturday,

May 9th, 2026. Beginning At 8am Est. This Unit

Is

Being Sold At Auction,

Auction Units Can Offer The Best Value,

However They Can Bear The Greatest Risk!

An Auction Vehicle Often May Have Condition

Or Mechanical Issues.

There Are No Warranties Or Guarantees.

You Must Inspect The Vehicle In Person And

Determine If This Is The Right Vehicle For You.

This Vehicle Is Sold "as-is..... You Buy It

You Own It! You Made A Mistake You

Own It! Let The Buyer Beware..... There Is No

Return Policy. Good Luck! And Remember An

Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL**

PUBLIC**

7249 Used 2010 Buick Enclave 5galvced9aj237398

Miles: 144,5076

Color: White

Engine: V6, 3.6

Automatic transmission, tan leather interior, heated and cold seats, dual climate control, Sirius capabilities, three door garage memory, panoramic sunroof, steering wheel monitor controls, cruise control, tilt wheel, automatic headlights, fog lights, power driver seat, two seat memory, power windows power lock; Rear captain chairs, third row seating, rear sunroof, DVD player and headrest, rear climate control; aluminum rims,

Condition report: throughout front bumper small scrapes, scratches, dents; driver side front fender has small scratches and scrapes; Driver door has scratches around door handle& rock chips at bottom; small scratches on top of door; rock chips at bottom; Driver side quarter panel- dent around fuel cap scratches around fuel cap; rear bumper has small scratches; trunk has scratches; passenger side quarter panel has rocks chips on edge ,scratches throughout; side rear door rock chipped around door handle; small paint



7220 USED 2014 Kia Sorento 5XYKTCA63EG473803

Miles: 100,099

Color: Silver

Engine: I4, 2.4

Automatic transmission, four-wheel-drive, black cloth interior, AM/FM radio with CD, steering wheel monitor controls, cruise control, power window power lock, aluminum rims, roof rack, hitch receiver,

Condition report: scuff marksand small scratches throughout ; front bumper has small scrape; scratches around headlight; driver side front fender small scuff marks above plastic trim piece; Driver door has small scratches; scrapes around door handle; small dent in the middle of door ; driver side rear door scratched throughout; small rock chips throughout driver side rear quarter panel; and scuffed marks throughout down through the paint; scratches around fuel cap; rear bumper has small rock chips; trunk has scratches throughout; quarter panel has scratches; door with paint



May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending todays auction, please visit our website for the most up to date conversation!

LOT #

imperfection ; small rust active at the bottom;
small scuff marks on front fender

Do Not Bid From The Pictures
You Must Inspect The Vehicle In Person On Saturday,
May 9th, 2026. Beginning At 8am Est. This Unit Is
Being Sold At Auction,
Auction Units Can Offer The Best Value,
However They Can Bear The Greatest Risk!
An Auction Vehicle Often May Have Condition Or Mechanical Issues.
There Are No Warranties Or Guarantees.
You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You. This Vehicle Is Sold "as-is..... You Buy It You Own It! You Made A Mistake You Own It! Let The Buyer Beware..... There Is No Return Policy. Good Luck! And Remember An Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL PUBLIC****

LOT #

Do Not Bid From The Pictures
You Must Inspect The Vehicle In Person On Saturday,
May 9th, 2026. Beginning At 8am Est. This Unit Is
Being Sold At Auction,
Auction Units Can Offer The Best Value,
However They Can Bear The Greatest Risk!
An Auction Vehicle Often May Have Condition Or Mechanical Issues.
There Are No Warranties Or Guarantees.
You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You. This Vehicle Is Sold "as-is..... You Buy It You Own It! You Made A Mistake You Own It! Let The Buyer Beware..... There Is No Return Policy. Good Luck! And Remember An Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL PUBLIC****

7211 USED 2016 Volkswage Jetta 3VWL17AJ1GM204921

Miles: 186,677
Color: Grey
Engine: I4, 1.8 T
Automatic transmission, gray cloth interior, heated seats, AM/FM radio with CD, steering wheel monitor controls, cruise control, push start, automatic headlights, fog lights, power windows power locks, aluminum rims



Condition report:

Chips & scuffs; throughout bumper small scratches small scratches; small chips, scratches and paint imperfection; aluminum rims have scratches; driver side door has small scratches around door handle; multiple small paint chips and rock chips; small dent in driver door; multiple small dents by door handle; small scratches at bottom; quarter panel has small scratches, rock chip; side quarter panel large scratches and scuff marks throughout; scratches on door edge; side front door has heavy scratches and scrapes; side front fender has small scratches.

7262 USED 2013 Chevrolet Tahoe 1GNSKBE09DR333569

Miles: 145,795
Color: Black
Engine: V8, 5.3
Automatic transmission, 4wD, black leather interior, dual climber control., our capabilities, steering wheel monitors, cruise control, tilt wheel, automatic headlights, Peter windows power locked, power driver seat, third row seat seating, rear bench seat, rear entertainment, rear climate aluminum rims, roof rack, pitch receiver



Report scratch a small rock bubble swarming from Bumper has scrapes scratches and protections they're both healing driver side front finder has rock chipped and paint chip soup out Driver door has characters around door handle small dent on edge scratches out starting to peel paint on bottom side rear door scratches and scraped with a small rack tip side quarter panels throughout where Bumper has heavy scratches and scrapes the trunk it has heavy scratches scrapes and nips under a quarter panel as rough starting to form paint is peeling rust Heavy stretch scrapes paint imperfections that the front door has heavy scratches cracks in front has to

May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending todays auction, please visit our website for the most up to date conversation!

LOT #

be scratches and small dents

Do Not Bid From The Pictures
 You Must Inspect The Vehicle In Person On Saturday,
 May 9th, 2026. Beginning At 8am Est. This Unit Is Being Sold At Auction,
 Auction Units Can Offer The Best Value, However They Can Bear The Greatest Risk!
 An Auction Vehicle Often May Have Condition Or Mechanical Issues.
 There Are No Warranties Or Guarantees.
 You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You.
 This Vehicle Is Sold "as-is..... You Buy It You Own It! You Made A Mistake You Own It! Let The Buyer Beware..... There Is No Return Policy. Good Luck! And Remember An Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL PUBLIC****

7243 Used 2011 Gmc Yukon Xl 1gks2ke34br113096

Miles: 178,652
 Color: Black
 Engine: V8, 5.3



Automatic transmission, four-wheel-drive, tan leather interior, dual climate control, AM/FM radio with CD, OnStar capabilities, three door memory, steering wheel monitor controls, cruise control, heated and cooled seats, automatic two seat memory, power windows power locks, rear captain chairs, rear climate controls, rear heated seats, DVD player headrest, third row seating, aluminum rims, roof rack, hitch receiver

Condition report: multiple scratches rock chips and paint chips on front edge; front bumper has small scratches through out; driver side front fender has small scratches by headlight; rock chips at bottom; Driver door has scratches around door handle; scratches in the middle of door; scratches and defects on plastic trim piece; rock chips at bottom of door; rear door has scratches around door handle; small scratches and rust starting to form at bottom; driver side rear quarter panel starting to form rust at bottom with large scratches, scrapes, small dents

LOT #


throughout side; rear bumper has small nicks scratches paint imperfections; trunk has large scratches below glass; passenger side rear bumper has large scuff marks under tail light; heavy rusting and paint chips at edge ; driver passenger side metal door has large scratches paint and perfect and heavy stretches around door handle small rack tipped and paint chipped that bottom door recite front door large scratches scrapes door dings heavy scratches and active side front finder small paint marks throughout large paint stuff light on front bumper

Do Not Bid From The Pictures
 You Must Inspect The Vehicle In Person On Saturday,
 May 9th, 2026. Beginning At 8am Est. This Unit Is Being Sold At Auction,
 Auction Units Can Offer The Best Value, However They Can Bear The Greatest Risk!
 An Auction Vehicle Often May Have Condition Or Mechanical Issues.
 There Are No Warranties Or Guarantees.
 You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You.
 This Vehicle Is Sold "as-is..... You Buy It You Own It! You Made A Mistake You Own It! Let The Buyer Beware..... There Is No Return Policy. Good Luck! And Remember An Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL PUBLIC****

7213 Repo 2016 Chevrolet Cruze Limited 1g1pc5sh7g712807

Miles: 112,176
 Color: White
 Engine: I4, 1.8



Automatic transmission, black and gray cloth interior, AM/FM Radio with CD, steering wheel controls, cruise control, automatic headlights, power windows , power locks

condition report : side front fender has small scratches and bottom rocker starting to rust; large scratches with paint missing; door has heavy scratches around door handle; large rock chips and paint tips on edge door; driver side

May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending todays auction, please visit our website for the most up to date conversation!

LOT #

quarter panel has multiple small dents; heavy scratches, bumper heavily scraped ; trunk lid has small rust particles and scratches on edge; side rear quarter panel has small rock chips throughout ; small dents throughout driver side; passenger side rear door has rust, small rust particles in the middle of door; large scratches; passenger side front door has larger heavy scratches around door handle; multiple small dents scrapes and scratches; passenger side front fender has multiple dents on bottom of fender; multiple large scratches throughout.

DO NOT BID ON THIS VECHICLE FROM THE PICTURES

YOU MUST INSPECT THE VEHICLE IN PERSON ON Saturday, MAY 9TH, 2026.

Beginning at 8am Eastern Time

This Unit Is A Repossessed Vehicle!

Repossessed Vehicles can offer a Best Value, however they can bear The Greatest Risk!

Each repossessed vehicle will have New York State REPO papers you can ONLY register this unit in New York State, You Can "NOT???

Register It Out Of New York State

A Repossessed Vehicle often has condition or mechanical issues. There are NO

WARRANTIES or GUARANTEES. This vehicle came from someone who couldn't pay for it, so maintenance and upkeep was not the prior owner priority

YOU MUST INSPECT THE VEHICLE in person and determine if this is the right vehicle for you.

THIS VEHICLE IS SOLD "AS-IS.....YOU BUY IT YOU OWN IT!YOU MADE A MISTAKE YOU OWN IT! LET THE BUYER BEWARE..... THERE IS NO RETURN POLICY.

GOOD LUCK! AND REMEMBER AN EDUCATED CONSUMER IS OUR BEST CUSTOMER.

BIDDING IS OPEN TO THE GENERAL PUBLIC

LOT #

7234 USED 2017 Subaru Outback 4S4BSACC1H3203225

Miles: 199,936

Color: Blue

Engine: H4, 2.5

Automatic transmission, four-wheel-drive, black cloth interior, dual climate control, heated seat, AM/FM radio CD, backup camera, steering wheel controls, paddle shifters, automatic headlights, control, power windows, power locks; aluminum rims, roof rack,



Condition report decimal scratches and scrapes out small racks on front front bumper driver side small vent with paint perfection rack chips at bottom Driver door has rack chipped at bottom scratches around door handle paint chips on a door driver side rear door has multiple dent scratches around door handle tighter quarter panel has dents on body line scratches around at the door Tirer Bumper has stuff marks rubbing marks paint missing rear bumper has scratches and straight stripes with your trunk that that rack tipped scratches where a license plate goes past your side rear quarter panel has scratches around fuel cap small scratches passenger side door scratches around door handle small scratches in the middle of door passenger side front door has dent with paint and perfections active at bottom passenger side front Binder has multiple dents on body line from Bumper has scratches

Do Not Bid From The Pictures

You Must Inspect The Vehicle In Person On Saturday,

May 9th, 2026. Beginning At 8am Est. This Unit Is

Being Sold At Auction,

Auction Units Can Offer The Best Value,

However They Can Bear The Greatest Risk!

An Auction Vehicle Often May Have Condition Or Mechanical Issues.

There Are No Warranties Or Guarantees.

You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You.

This Vehicle Is Sold "as-is..... You Buy It You Own It! You Made A Mistake You Own It! Let The Buyer Beware..... There Is No Return Policy. Good Luck! And Remember An Educated Consumer Is Our Best Customer.

BIDDING OPEN TO THE GENERAL PUBLIC

May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending todays auction, please visit our website for the most up to date conversation!

LOT #

7250 USED 2015 Ford Escape 1FMCU9J9XFUC00254

Miles: 140,526

Color: Red

Engine: I4, 2 T

Automatic transmission, AWD, black leather interior, heated seats, dual climate control, AMFM radio with CD; backup camera, three door memory, push the start, steering wheel monitor controls, cruise control, tilt wheel, automatic head lights, power driver seat, seat memory, power windows power lock, aluminum rims, roof rack,



****OPEN RECALL** ON YOUR VEHICLE, THE REAR VIEW CAMERA COULD DISPLAY A BLANK OR DISTORTED IMAGE ON THE CENTER DISPLAY SCREEN WHEN THE VEHICLE IS IN REVERSE**

Condition report : scratches, scrapes & paint starting to bubble; small scratches on front bumper; small scrapes, scratches and rock chips; driver side front fender has imperfections; bottom driver door scratched in middle of door; scratches around door handle; door has paint chips; driver side rear door has paint chips on edge w/ small dents throughout; scratches & paint imperfections; driver side rear quarter panel paint imperfection scratches and scrapes; trunk paint starting to bubble; small scratches and scrapes on rear bumper cover; passenger quarter panel scratched; small paint chips passenger side rear door; paint chips rock chips scratched; passenger side; front door handle scratched; front fender scraped

Do Not Bid From The Pictures
 You Must Inspect The Vehicle In Person On Saturday,
 May 9th, 2026. Beginning At 8am Est. This Unit Is
 Being Sold At Auction,
 Auction Units Can Offer The Best Value,
 However They Can Bear The Greatest Risk!
 An Auction Vehicle Often May Have Condition Or Mechanical Issues.
 There Are No Warranties Or Guarantees.
 You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You.
 This Vehicle Is Sold "as-is..... You Buy It You Own It! You Made A Mistake You

LOT #

Own It! Let The Buyer Beware..... There Is No Return Policy. Good Luck! And Remember An Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL PUBLIC****

7247 USED 2005 Kia Sportage KNDJE723757123573

Miles: 121,396

Color: Brown

Engine: V6, 2.7

Automatic Transmission, four-wheel Drive. AM/FM radio CD, moon roof, cruise control, power window power lock ;aluminum rims, roof rack,



Condition report: paint chips throughout ; front Bumper has scratches & scuff marks; driver side front fender has rock chips and paint chips through out; Driver door has scratches around door handle; paint chipped w/ large scratches at bottom; driver side rear door has large scuff w/ metal scratched and scrapes throughout; driver side rear quarter panel has small rock chips and paint chips; trunk lid has rust forming; scratches with scrapes on rear bumper; quarter panel has dents throughout; scratches throughout passenger side; issue with plastic trim; passenger side front door has dent around door handle; passenger side fender has scrapes, scratches and dents

Do Not Bid From The Pictures
 You Must Inspect The Vehicle In Person On Saturday,
 May 9th, 2026. Beginning At 8am Est. This Unit Is Being Sold At Auction,
 Auction Units Can Offer The Best Value,
 However They Can Bear The Greatest Risk!
 An Auction Vehicle Often May Have Condition Or Mechanical Issues.
 There Are No Warranties Or Guarantees.
 You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You.
 This Vehicle Is Sold "as-is..... You Buy It You Own It! You Made A Mistake You Own It! Let The Buyer Beware..... There Is No Return Policy. Good Luck! And Remember An Educated Consumer Is Our Best Customer.

May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending todays auction, please visit our website for the most up to date conversation!

LOT #

****BIDDING OPEN TO THE GENERAL PUBLIC****

7252 USED 2012 Buick Enclave 5GAKRCED8CJ122763

Miles: 119,941
Color: Gold
Engine: V6, 3.6

Automatic transmission, tan leather interior, heated seats, dual climate, lane assist, AM- FM radio with CD, Onstar capabilities, three door garage memory, steering wheel monitor controls, Automatic lights, fog lights, two seat memory, power seat, power window power lock, rear captain chairs, third row seating, climate control, aluminum rims, roof rack,



Condition report: multiple small dents through out hood and on roof; vehicle front bumper has small scrape, scratches and dents; fender has paint imperfections; scratches over Wheel well; Driver door scratched throughout; rock chips driver side rear door; paint imperfections and clearcoat scratches; quarter panel has paint imperfections around fuel cap scratches and scrapes throughout; rear bumper has small scratches small nicks; trunk has small dent rust particles throughout; passenger side rear quarter panel multiple small dents, scratches, and scrapes; multiple small dent on quarter panel; paint imperfections at bottom door ;passenger side front fender has multiple small dents

Do Not Bid From The Pictures
You Must Inspect The Vehicle In Person On Saturday,
May 9th, 2026. Beginning At 8am Est. This Unit Is
Being Sold At Auction,
Auction Units Can Offer The Best Value,
However They Can Bear The Greatest Risk!
An Auction Vehicle Often May Have Condition Or Mechanical Issues.
There Are No Warranties Or Guarantees.
You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You.
This Vehicle Is Sold "as-is..... You Buy It You Own It! You Made A Mistake You Own It! Let The Buyer Beware..... There Is No

LOT #

Return Policy. Good Luck! And Remember An Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL PUBLIC****

7261 USED 2016 Ford Flex 2FMHK6C88GBA11835

Miles: 133,051
Color: White
Engine: V6, 3.5

Automatic transmission, AWD, tan leather interior, dual climate control, heated seats, FM radio CD, steering wheel monitor controls, push automatic Adlich, fog lights, power driver seat, two seat memory, power and nose power lock, third row seating, metal bench seat, aluminum rims, hitch.



***OPEN RECALLS** A FRACTURE OF A REAR TOE LINK SIGNIFICANTLY DIMINISHES STEERING CONTROL, INCREASING THE RISK OF A CRASH. && A REAR VIEW CAMERA THAT DISPLAYS A BLANK OR DISTORTED IMAGE WHILE IN REVERSE CAN REDUCE OR DISTORT THE DRIVERS VIEW OF WHAT IS BEHIND THE VEHICLE, INCREASING THE RISK OF A CRASH.**

Condition report: has scrape scratches rocks paint chips and Bumper cracks racks of pink chips driver side front fender bracket tip paint tip paint and perfection Driver door imperfections scratches out Driver Beer door and scratched indoor heat indoor pink chips and body chips and quarter panel quarter panel has small rust spots with imperfection rear bumper and Mark scrapes scratches for trunk scratches scrapes and imperfection special side rear quarter panel has small rust spots over well well scratches around field cap side rear door scratch scratches scrapes throughout with imperfections side front door large scratches rack tips tight scratches for passenger side front bumper small neck and scrapes

Do Not Bid From The Pictures
You Must Inspect The Vehicle In Person On Saturday,

May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending todays auction, please visit our website for the most up to date conversation!

LOT #

May 9th, 2026. Beginning At 8am Est. This Unit Is Being Sold At Auction, Auction Units Can Offer The Best Value, However They Can Bear The Greatest Risk! An Auction Vehicle Often May Have Condition Or Mechanical Issues. There Are No Warranties Or Guarantees. You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You. This Vehicle Is Sold "as-is..... You Buy It You Own It! You Made A Mistake You Own It! Let The Buyer Beware..... There Is No Return Policy. Good Luck! And Remember An Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL PUBLIC****

LOT #

Being Sold At Auction, Auction Units Can Offer The Best Value, However They Can Bear The Greatest Risk! An Auction Vehicle Often May Have Condition Or Mechanical Issues. There Are No Warranties Or Guarantees. You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You. This Vehicle Is Sold "as-is..... You Buy It You Own It! You Made A Mistake You Own It! Let The Buyer Beware..... There Is No Return Policy. Good Luck! And Remember An Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL PUBLIC****

7253 USED 2014 Mazda Mazda6 JM1GJ1W64E1121368

Miles: 120,876
Color: Red
Engine: I4, 2.5
Automatic transmission, black leather interior, heated seats, dual climate control, AM/FM radio CD, push the start, steering wheel monitor controls, cruise control, adaptive cruise control, paddle shifters, automatic headlights, power driver seat, power window power lock, aluminum rims



Condition report: small scratches throughout w/ paint imperfection; front Bumper scrapes and scratches; driver side rock chips and paint chips; Driver side door has dents and scratches; scratches around door handle; rear door scratches and scrapes; rock chips at bottom; passenger side rear quarter panel scratched around fuel cap; rear bumper dented; scratches on trunk; passenger side rear quarter panel; plastic side on rear door; chips at bottom passenger side ; front door rock chipped under mirror w/scratches on mirror; side front has large hole with paint bubbling and rust forming

Do Not Bid From The Pictures

You Must Inspect The Vehicle In Person On Saturday,

May 9th, 2026. Beginning At 8am Est. This Unit Is

7260 USED 2013 Kia Sorento 5XYKT4A6XDG335048

Miles: 139,592
Color: Black
Engine: I4, 2.4L

Automatic transmission, power mirrors, power windows, power locks, tilt steering wheel, steering wheel monitor controls, cruise control, AM/FM radio with CD player, Bluetooth and SiriusXM available, heated front seat, gray cloth interior, third row, seating, aluminum rims, fog lights



****OPEN RECALL** AN ENGINE**

COMPARTMENT FIRE WHILE PARKED OR DRIVING CAN INCREASE THE RISK OF INJURY.

Condition report: multiple paint chips, heavy scratches, and paint imperfections on hood, multiple paint imperfections, scrapes, and scratches on front bumper, minor scratches on driver side, front fender, minor scratches, scuffs on driver side front door, small dent with no paint damage on front door, minor scratches in minor paint imperfections on driver side rear door, dent with paint damage on driver side quarter panel, large scrapes, and scuffs on driver side, quarter panel and driver side of rear bumper, minor scratches on liftgate and bumper, minor scratches on passenger quarter panel, multiple scuffs, and scratches on passenger rear door, large area of sticky residue on passenger

May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending todays auction, please visit our website for the most up to date conversation!

LOT #

front door, multiple minor scratches on passenger front door, passenger side marker lamp on mirror is cracked and broken, minor scratches on passenger front fender, minor paint imperfections on roof.

Do Not Bid From The Pictures

You Must Inspect The Vehicle In Person On Saturday,

May 9th, 2026. Beginning At 8am Est. This Unit Is

Being Sold At Auction,

Auction Units Can Offer The Best Value,

However They Can Bear The Greatest Risk!

An Auction Vehicle Often May Have Condition Or Mechanical Issues.

There Are No Warranties Or Guarantees.

You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You.

This Vehicle Is Sold "as-is..... You Buy It

You Own It! You Made A Mistake You

Own It! Let The Buyer Beware..... There Is No

Return Policy. Good Luck! And Remember An

Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL**

PUBLIC**

LOT #

door, multiple gouges and heavy scratches on rear bumper, minor scratches on passenger quarter panel, minor paint imperfections on passenger rear door, minor scratches on passenger front door, and front fender, light corrosion on passenger front fender.

Do Not Bid From The Pictures

You Must Inspect The Vehicle In Person On Saturday,

May 9th, 2026. Beginning At 8am Est. This Unit Is Being Sold At Auction,

Auction Units Can Offer The Best Value,

However They Can Bear The Greatest Risk!

An Auction Vehicle Often May Have Condition Or Mechanical Issues.

There Are No Warranties Or Guarantees.

You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You.

This Vehicle Is Sold "as-is..... You Buy It

You Own It! You Made A Mistake You

Own It! Let The Buyer Beware..... There Is No

Return Policy. Good Luck! And Remember An

Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL**

PUBLIC**

7264 USED 2016 Buick Encore KL4CJCSB1GB632735

Miles: 100,004

Color: Black

Engine: I4, 1.4 T

Automatic transmission, automatic headlights, power mirrors, power windows, power locks, power front seats, tilt steering wheel, steering wheel monitor controls, cruise control, AM/FM radio with CD player, Bluetooth available, on star capabilities, do a climate control, heated front seats, heated steering wheel, sunroof, black leather interior, aluminum rims, fog lights

Condition report: dent with paint damage on hood, multiple minor scratches on hood, multiple paint chips, scuffs, scrapes, and paint imperfections on front bumper, multiple scratches on driver side, front fender, multiple dents multiple scratches on driver side front door, multiple dense with paint damage and minor paint imperfections on driver side rear



7254 USED 2014 Nissan Rogue 5N1AT2MV4EC847795

Miles: 136,503

Color: White

Engine: I4, 2.5

Automatic transmission, all-wheel-drive, black leather interior, heated seats, dual climate control, AM/FM radio with CD, steering wheel monitor controls, push to start, power lock power window, aluminum rims, roof rack,

Condition report multiple paint and rack tip paint tip throughout front Bumper has scratches and grapes driver side front fender particles brackets performing at bottom small paint and perfection throughout driver rear door scratches around door handle at bottom driver side rear quarter panel has multiple rocks paint chips paint and perfection rear bumper has heavy scratches and scrapes rear trunk lift has scratches scrapes and rust marks pressure tight quarter panel has small chips scratches scrapes heavy



May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending todays auction, please visit our website for the most up to date conversation!

LOT #

scratches around the rear fuel cap passenger side
 rear door paint tips by door handle small rack
 tips heavy scratches passenger side front door
 has small rough mark marked passenger side
 front fender has small scratches and scrape
 passenger side front fender

Do Not Bid From The Pictures
 You Must Inspect The Vehicle In Person On
 Saturday,
 May 9th, 2026. Beginning At 8am Est. This Unit
 Is
 Being Sold At Auction,
 Auction Units Can Offer The Best Value,
 However They Can Bear The Greatest Risk!
 An Auction Vehicle Often May Have Condition
 Or Mechanical Issues.
 There Are No Warranties Or Guarantees.
 You Must Inspect The Vehicle In Person And
 Determine If This Is The Right Vehicle For You.
 This Vehicle Is Sold "as-is..... You Buy It
 You Own It! You Made A Mistake You
 Own It! Let The Buyer Beware..... There Is No
 Return Policy. Good Luck! And Remember An
 Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL
 PUBLIC****

LOT #

passenger doors, corrosion on roof

Do Not Bid From The Pictures
 You Must Inspect The Vehicle In Person On
 Saturday,
 May 9th, 2026. Beginning At 8am Est. This Unit
 Is Being Sold At Auction,
 Auction Units Can Offer The Best Value,
 However They Can Bear The Greatest Risk!
 An Auction Vehicle Often May Have Condition
 Or Mechanical Issues.
 There Are No Warranties Or Guarantees.
 You Must Inspect The Vehicle In Person And
 Determine If This Is The Right Vehicle For You.
 This Vehicle Is Sold "as-is..... You Buy It
 You Own It! You Made A Mistake You
 Own It! Let The Buyer Beware..... There Is No
 Return Policy. Good Luck! And Remember An
 Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL
 PUBLIC****

7255 USED 2014 Subaru XV Crosstrek JF2GPACC7E8224771

Miles: 184,657
 Color: Silver
 Engine: H4, 2
 Automatic transmission, all-wheel-drive, power
 mirrors, power windows, power locks, tilt
 steering wheel, steering wheel monitor controls,
 cruise control, AMFM radio with CD player,
 heated front seats, black cloth interior,
 aluminum rims, roof rack, fog lights



Condition report: multiple paint chips, scratches,
 scuffs, paint imperfections on hood, multiple
 scuffs and scratches and paint chips on front
 bumper, small dent on driver side front door,
 minor scratches on driver side doors, multiple
 paint chips, scratches, and imperfections on
 liftgate and rear bumper, dent with paint damage
 on passenger rear door, multiple small dent and
 passenger front door; Minor scratches on

7258 USED 2017 Nissan Pathfinder 5N1DR2MM2HC672213

Miles: 154,862
 Color: Blue
 Engine: V6, 3.5



Automatic transmission, four-wheel-drive,
 power mirrors, power windows, power locks, tilt
 steering wheel, steering wheel monitor controls,
 cruise control, touchscreen stereo with AM/FM
 radio, and CD player, Bluetooth available,
 SiriusXM available, dual climate control, third
 row seating, black cloth interior, aluminum rims,

Condition report: multiple paint chips on hood,
 multiple minor scratches on hood, multiple
 minor scratches and imperfections on front
 bumper, minor scratches on driver side, front
 fender, driver side front door has been repainted,
 with minor chips and minor scratches, multiple
 scratches with touchups on driver side rear door,
 dent with no paint damage on driver side rear
 door, large heavy scratches on driver side
 quarter panel, minor scratches on liftgate and
 rear bumper, small passenger quarter panel,
 multiple minor scratches, and paint and
 imperfections on passenger rear door, minor ding
 with paint damage, minor scratches on passenger

May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending todays auction, please visit our website for the most up to date conversation!

LOT #

front door, multiple heavy scratches on passenger side mirror, multiple small chips and minor scratches on roof. Small burn hole on driver front seat.

Do Not Bid From The Pictures
 You Must Inspect The Vehicle In Person On Saturday,
 May 9th, 2026. Beginning At 8am Est. This Unit Is
 Being Sold At Auction,
 Auction Units Can Offer The Best Value,
 However They Can Bear The Greatest Risk!
 An Auction Vehicle Often May Have Condition Or Mechanical Issues.
 There Are No Warranties Or Guarantees.
 You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You.
 This Vehicle Is Sold "as-is..... You Buy It You Own It! You Made A Mistake You Own It! Let The Buyer Beware..... There Is No Return Policy. Good Luck! And Remember An Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL PUBLIC****

7256 USED 2011 Ford Explorer 1FMHK8D81BGA44350

Miles: 135,377
 Color: Black
 Engine: V6, 3.5
 Automatic transmission, four-wheel-drive, automatic headlights, power mirrors, power windows, power locks, powered front seats, tilt steering wheel, steering wheel monitor controls, cruise control, touchscreen stereo with AM/FM radio CD player, Bluetooth and SiriusXM available, dual climate control, heated front seats, third row seating, black leather interior, aluminum rims, fog lights



****2 OPEN RECALLS** VEHICLES EXPOSED TO A CORROSIVE ENVIRONMENT WHERE ROAD SALT IS USED EXTENSIVELY DURING WINTER MONTHS && AN EXTERIOR A-PILLAR TRIM PART THAT DETACHES WHILE DRIVING CAN CREATE A ROAD HAZARD FOR OTHER ROAD USERS, INCREASING**

LOT #

THE RISK OF A CRASH.

Condition report: multiple paint chips, heavy scratches, and imperfections on hood, driver side fog light is broken, multiple minor scratches, and imperfections on front bumper, small dent with paint damage on driver side, front fender, minor scratches on driver side, fender, multiple scratches on driver side front door, multiple dings, one large dent with no paint damage on driver side front door, heavy, scratch, and small dent with paint damage on driver side rear door, minor scratches on driver side quarter panel, multiple scrapes, scuffs, and paint imperfections on rear bumper, large chip with peeling and corrosion on liftgate, minor scratches on passenger quarter panel, multiple dents with no paint damage and paint damage on passenger rear door, small dings and paint imperfections on passenger front door, minor scratches on passenger front fender, interior driver side door panel has large tear in it, driver seat has large tear.

Do Not Bid From The Pictures
 You Must Inspect The Vehicle In Person On Saturday,
 May 9th, 2026. Beginning At 8am Est. This Unit Is
 Being Sold At Auction,
 Auction Units Can Offer The Best Value,
 However They Can Bear The Greatest Risk!
 An Auction Vehicle Often May Have Condition Or Mechanical Issues.
 There Are No Warranties Or Guarantees.
 You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You.
 This Vehicle Is Sold "as-is..... You Buy It You Own It! You Made A Mistake You Own It! Let The Buyer Beware..... There Is No Return Policy. Good Luck! And Remember An Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL PUBLIC****

May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending todays auction, please visit our website for the most up to date conversation!

LOT #

7259 USED 2007 Toyota RAV4 JTMBD31V375115889

Miles: 182,320

Color: Green

Engine: I4, 2.4

Automatic transmission, four-wheel-drive, power mirrors, power locks, power windows, tilt steering wheel, steering wheel monitor control, cruise control, AM/FM radio with CD player, dual climate control, beige cloth interior, aluminum rims, hitch receiver, spare tire on hatch, fog lights,



****OPEN RECALL**** If this occurs, the seat belt may not properly restrain the occupant, which could increase the risk of injury.

Condition report: multiple paint chips, scratches, and paint imperfections on hood, multiple scuffs, scrapes, heavy scratches, and paint imperfections on front bumper, paint is cracking on front bumper, multiple paint chips and small heavy scratches on driver side front fender, dent with paint damage, in multiple minor scratches on driver side front door, heavy, scratch, and small dent with no paint damage on driver side rear door, multiple dents on driver side quarter panel, multiple heavy scratches, scrapes, scuffs, paint chips, and paint imperfections on rear bumper and hatch, multiple scratches on passenger quarter panel, multiple paint chips, and multiple scratches on passenger rear door, multiple scratches on passenger front door and passenger front fender, small paint chips on roof, front windshield is pitting at the top.

Do Not Bid From The Pictures

You Must Inspect The Vehicle In Person On

Saturday,

May 9th, 2026. Beginning At 8am Est. This Unit Is

Being Sold At Auction,

Auction Units Can Offer The Best Value,

However They Can Bear The Greatest Risk!

An Auction Vehicle Often May Have Condition Or Mechanical Issues.

There Are No Warranties Or Guarantees.

You Must Inspect The Vehicle In Person And

Determine If This Is The Right Vehicle For You.

This Vehicle Is Sold "as-is..... You Buy It

You Own It! You Made A Mistake You

Own It! Let The Buyer Beware..... There Is No

LOT #

Return Policy. Good Luck! And Remember An Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL PUBLIC****

7257 USED 2017 Subaru Outback 4S4BSENCXH3257353

Miles: 183,616

Color: Gray

Engine: H6, 3.6

Automatic transmission, black leather interior, all-wheel-drive, dual climate control, heated seat, AM/FM radio with CD, moonroof, steering wheel monitor controls, paddle shifters, push the start, power driver seat, power windows power locks, rear heated seats, Subaru floor mats, roof rack, aluminum rims



Condition report : hood has multiple scratches & scrapes; front bumper has scratches, scrapes throughout; driver side front dent scratches scrapes small rocks chips; Driver door has large scuff mark, scratches small dents, paint imperfections; driver side rear door small dent; large paint imperfection & scratches, scrape,scuff markes on bumper; heavy scratches paint imperfection; trunk large scratches and scrapes; passenger side quarter panel dent with scratches paint imperfections throughout; fuel cap has glue like substance; side rear door large scuff marks; multiple dents dings heavy scuff marks; scratches under door handle; large doors passenger side scratches & scrapes throughout.

Do Not Bid From The Pictures

You Must Inspect The Vehicle In Person On

Saturday,

May 9th, 2026. Beginning At 8am Est. This Unit Is

Being Sold At Auction,

Auction Units Can Offer The Best Value,

However They Can Bear The Greatest Risk!

An Auction Vehicle Often May Have Condition Or Mechanical Issues.

There Are No Warranties Or Guarantees.

You Must Inspect The Vehicle In Person And

Determine If This Is The Right Vehicle For You.

This Vehicle Is Sold "as-is..... You Buy It

You Own It! You Made A Mistake You

May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending today's auction, please visit our website for the most up to date conversation!

LOT #

Own It! Let The Buyer Beware..... There Is No Return Policy. Good Luck! And Remember An Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL PUBLIC****

7267 USED 2018 Chevrolet Express 1GCZGGFG5J1321768

Miles: 220,838
Color: White
Engine: V8, 6

Automatic transmission, gray vinyl interior, AM/FM radio with CD steering wheel monitor controls, cruise control, automatic headlights, power windows power locks



Condition report: both seats are ripped hood has small rock chips though out driver side has small paint imperfections driver door has large scratch though out drive side of van has multiple large dents that are from the in side out with multiple large paint chips and scratches dents and paint touch up work rear van doors has rust around plastic paint chips and small dents passenger side has small chips on rear with multiple dents double doors has small rust marks passenger side door has had paint touch up work and front fender has paint chips

Do Not Bid From The Pictures
You Must Inspect The Vehicle In Person On Saturday,
May 9th, 2026. Beginning At 8am Est. This Unit Is Being Sold At Auction,
Auction Units Can Offer The Best Value,
However They Can Bear The Greatest Risk!
An Auction Vehicle Often May Have Condition Or Mechanical Issues.
There Are No Warranties Or Guarantees.
You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You.
This Vehicle Is Sold "as-is..... You Buy It You Own It! You Made A Mistake You Own It! Let The Buyer Beware..... There Is No Return Policy. Good Luck! And Remember An Educated Consumer Is Our Best Customer.

****bidding Open To The General Public****

LOT #

7214 Used 2014 Chevrolet Cruze 1g1pc5sb4e7369226

Miles: 106,962
Color: Red
Engine: I4, 1.4 T
Automatic transmission, black cloth interior, AM/FM radio CD, on star capabilities, steering wheel mounted controls, cruise control, tilt Wheel, Power windows power locks



Condition report: small paint chips, scratches and imperfections throughout, front Bumper has small gouges, front fender has large paint chips and rock chips w/scratches at bottom, door has rust and rust holes throughout; large chips on edge door; rear door has large scratches and rock chips; small rust spots starting to form on quarter panel; small straight scratches; Bumper has small scratches; trunk has paint imperfections through out; Driver passenger side quarter panel has rust starting to bubble; fuel cap scratched; rocker panels have large rust forming; paint flaking ; door has multiple small scratches; front door has large paint chip and rock chips throughout ; passenger side front fender has small paint scratch with rock chips and rust starting to form,

Do Not Bid From The Pictures
You Must Inspect The Vehicle In Person On Saturday,
May 9th, 2026. Beginning At 8am Est. This Unit Is
Being Sold At Auction,
Auction Units Can Offer The Best Value,
However They Can Bear The Greatest Risk!
An Auction Vehicle Often May Have Condition Or Mechanical Issues.
There Are No Warranties Or Guarantees.
You Must Inspect The Vehicle In Person And Determine If This Is The Right Vehicle For You.
This Vehicle Is Sold "as-is..... You Buy It You Own It! You Made A Mistake You Own It! Let The Buyer Beware..... There Is No Return Policy. Good Luck! And Remember An Educated Consumer Is Our Best Customer.

****BIDDING OPEN TO THE GENERAL PUBLIC****

May 9th Secured Creditor & Repo Auction 4/21/2026-5/9/2026

Thank you for attending todays auction, please visit our website for the most up to date conversation!

LOT #
