

SALE NO. AU20220914001

LOT NO.		DESCRIPTION	ID	UNKN
1	QTY - 1	09 Chevrolet C7E Stake Body YW 6 cyl (Diesel) VIN: 1GBM7E1B99F411518; Defects: Body Damage, Body Rust, Engine, Fuel Tank, Suspension	OD 117567	
2	QTY - 1	08 Chevrolet Impala 4DSD GY 6 cyl VIN: 2G1WB58K481263415; Defects: Body Damage, Lights, Oil Leak, Tires/Wheels, Transmission	OD 103631	
3	QTY - 1	07 Chevrolet Impala 4DSD BL 6 cyl (Flex Fuel) VIN: 2G1WB58K379350528; Defects: Axle, Body Damage, Fuel Lines, Oil Leak, Tie Rod Ends, Transmission	OD 162016	
4	QTY - 1	07 Chevrolet Impala 4DSD BL 6 cyl (Flex Fuel) VIN: 2G1WB58K179353315; Defects: Body Damage, Lights, Oil Leak, Rust	OD 177189	
5	QTY - 1	07 Chevrolet Impala 4DSD GY 6 cyl (Flex Fuel) VIN: 2G1WB58K879355594; Defects: Body Damage, Oil Leak, Rust	OD 131034	
6	QTY - 1	06 Chevrolet Impala 4DSD GY 6 cyl VIN: 2G1WB58K669347749; Defects: Oil Leak, Rust	OD 134109	
7	QTY - 1	06 Chevrolet Impala 4DSD BR 6 cyl VIN: 2G1WB58K369344341; Defects: Body Damage, Brakes, Oil Leak, Power Steering, Rust	OD 190748	
8	QTY - 1	06 Chevrolet Impala 4DSD GY 6 cyl VIN: 2G1WB58K569344857; Defects: Body Damage, Exhaust, Rust, Transmission	OD 161009	
9	QTY - 1	08 Ford E350 Van YW 8 cyl VIN: 1FTSE34L88DB55139; Defects: Body Damage, Converter, Rust	OD 171289	
10	QTY - 1	06 Ford F250 Pickup GR 8 cyl VIN: 1FDSX20536ED96170; Defects: Frame Rusted, Rust	OD 101202	065525
11	QTY - 1	08 Chevrolet C7C Dump YW 6 cyl (Diesel/Biodiesel) 2 Ton VIN: 1GBM7C1B08F401267; Defects: Rust	OD 82869	
12	QTY - 1	99 Ford F350 Pickup YW 8 cyl 1 Ton 4x2 Crew Cab VIN: 1FTSW30L7XED71091; Defects: Rust	OD 201688	

SALE NO. AU20220914001

LOT NO.		DESCRIPTION	
13	QTY - 1	13 Ford F150 Pickup YW 8 cyl (Flex Fuel) VIN: 1FTFX1EF9DKE30242; Defects: Body Damage, Brakes, Rocker Panels, Rust Holes in Floor, Undercarriage Rust	ID UNKN OD 213450
14	QTY - 1	11 Ford F15 Pickup YW 8 cyl (Flex Fuel) VIN: 1FTFX1EF8BKD62741; Defects: **OD DISCREPANCY**, Frame, Rust	ID UNKN OD UNKN
15	QTY - 1	08 Ford F450 Pickup YW 10 cyl 1.5 Ton Service Body VIN: 1FDXF46Y98EB72913; Defects: Rust	ID UNKN OD 163276
16	QTY - 1	06 Ford F350 Pickup YW 8 cyl (Diesel) Stake Body VIN: 1FDWF37P06EB57953; Defects: Body Rust, Brakes, Transmission	ID 065198 OD 86865
17	QTY - 1	07 Ford F650 Dump YW 6 cyl (Diesel) VIN: 3FRWW65A47V488709; Defects: Body Rust, Brakes, Engine, Hole Cut in Engine Block, MV907A TO BE GIVEN	ID 075215 OD 187632
18	QTY - 1	07 Ford F650 Dump YW 6 cyl (Diesel) VIN: 3FRWW65A57V488699; Defects: Body Damage, Body Rust, Brakes, Engine, Exhaust, Fuel Tank, Hole Cut in Engine Block, Interior Damage, MV907A TO BE GIVEN, Rust, Suspension, Windshield	ID 075214 OD 140391
19	QTY - 1	07 Ford F650 Dump YW 6 cyl (Diesel) VIN: 3FRWW65A27V488711; Defects: Body Damage, Body Rust, Brakes, Engine, Hole Cut in Engine Block, MV907A TO BE GIVEN, Steering	ID 075212 OD 123133
20	QTY - 1	07 Ford F650 Dump YW 6 cyl (Diesel) VIN: 3FRWW65A47V488712; Defects: Body Damage, Body Rust, Brakes, Engine, Hole Cut in Engine Block, MV907A TO BE GIVEN	ID 075209 OD 151442
21	QTY - 1	07 Ford F650 Dump YW 6 cyl (Diesel) VIN: 3FRWW65A87V488681; Defects: Body Damage, Body Rust, Brakes, Engine, Hole Cut in Engine Block, MV907A TO BE GIVEN, Suspension	ID 075206 OD 140982
22	QTY - 1	07 Ford F650 Dump YW 6 cyl (Diesel) VIN: 3FRWW65A17V488697; Defects: Body Rust, Brakes, Engine, Frame, Hole Cut in Engine Block, MV907A TO BE GIVEN	ID 075218 OD 139211

SALE NO. AU20220914001

LOT NO.		DESCRIPTION		
23	QTY - 1	07 Ford F650 Stake Body YW 6 cyl (Diesel) VIN: 3FRXW65A77V488739; Defects: Body Damage, Body Rust, Brakes, Engine, Hole Cut in Engine Block, MV907A TO BE GIVEN, Transmission	ID 075265 OD 181741	
24	QTY - 1	04 Ford F450 Stake Body YW 8 cyl (Diesel) VIN: 1FDXF46P54ED34733; Defects: Body Rust, Brakes, Emissions	ID 045364 OD 82127	
25	QTY - 1	09 Ford F550 Utility YW 8 cyl (Diesel) VIN: 1FDAF56R09EA32271; Defects: Body Rust, Missing Parts, Oil Leak, Power Steering, Suspension	ID 095159 OD 189517	
26	QTY - 1	08 Ford F450 Utility YW 8 cyl (Diesel) VIN: 1FDXX46R48EB72954; Defects: Body Rust, Brakes, Hydraulics, Interior Damage, Oil Leak, Power Take Off, Steering, Windshield	ID 085412 OD 296859	
27	QTY - 1	08 Ford F450 Utility YW 10 cyl 1.5T Service Body VIN: 1FDXF46Y78EB72912; Defects: Rust	ID UNKN OD 192639	
28	QTY - 1	07 Ford F650 Flatbed YW 6 cyl (Diesel) VIN: 3FRWW66A77V486838; Defects: Body Rust, Brakes, Engine, Hole Cut in Engine Block, MV907A TO BE GIVEN	ID 075285 OD 214518	
29	QTY - 1	07 Ford F650 Flatbed YW 6 cyl (Diesel) Cab w/o Bed VIN: 3FRWW66A77V486841; Defects: Batteries, Body Rust, Brakes, Engine, Hole Cut in Engine Block, Lights, Missing Parts, MV907A TO BE GIVEN	ID 075272 OD 74729	
30	QTY - 1	12 Dodge Ram 3500 Utility YW 8 cyl VIN: 3C7WDSAT5CG242756; Defects: Body Damage, Exhaust, Rust	ID UNKN OD 188840	
31	QTY - 1	06 Sterling LT9 Tandem Dump YW 6 cyl (Diesel) 6x4 7 Ton VIN: 2FZHAZCV16AW91437; Defects: FOR PARTS VALUE ONLY, Hole Cut in Engine Block, Hood, Missing Parts, MV907A TO BE GIVEN, Rust	ID UNKN OD 203166	
32	QTY - 1	05 Sterling L90 Dump YW 6 cyl (Diesel) w/ 2 Wheels + Tires VIN: 2FZAAZDLX5AN73481; Defects: Computer, FOR PARTS VALUE ONLY, Hole Cut in Engine Block, MV907A TO BE GIVEN, Rust	ID 22400118V OD 66795	
33	QTY - 1	12 International 740 Dump YW 6 cyl (Diesel) Engine Apart Parts in Cab VIN: 1HTWDAAN6CJ615524; Defects: Engine, Rust	ID UNKN OD 87053	

SALE NO. AU20220914001

LOT NO.		DESCRIPTION	
34	QTY - 1	08 International 760 Dump YW 6 cyl (Diesel) w/ lots 84 & 85 VIN: 1HTWXAHT18J645985; Defects: ABS Light, Body Rust, Engine, Engine Light	ID 22400487V OD 188685
35	QTY - 1	08 International 760 Dump YW 6 cyl (Diesel) w/ lots 86 & 87 VIN: 1HTWXAHT88J645983; Defects: Rust, Suspension, Turbo	ID 22400454V OD 185284
36	QTY - 1	04 International 4200 Dump YW 8 cyl (Diesel) VIN: 1HTMPAFM84H664909; Defects: Body Rust, Brakes, Engine, FOR PARTS VALUE ONLY, Hole Cut in Engine Block, MV907A TO BE GIVEN	ID 045056 OD 95028
37	QTY - 1	02 International 470 Dump YW 8 cyl (Diesel) OD replaced VIN: 1HTSCABM32H557143; Defects: **OD DISCREPANCY**, Body Rust, Cluster, Clutch, FOR PARTS VALUE ONLY, Hole Cut in Engine Block, MV907A TO BE GIVEN, Oil Leak	ID 025476 OD 62016
38	QTY - 1	02 International 470 Dump YW 8 cyl (Diesel) VIN: 1HTSCABM02H557147; Defects: Body Rust, Driveshaft, FOR PARTS VALUE ONLY, Hole Cut in Engine Block, Interior Damage, MV907A TO BE GIVEN, Oil Leak, Power Take Off, Suspension, Turbo	ID 025491 OD 183585
39	QTY - 1	01 International 470 Stake Body YW 8 cyl (Diesel) VIN: 1HTSCABM61H332892; Defects: Body Damage, Body Rust, Brakes, Clutch, Driveshaft, Engine, Exhaust, Exterior and Interior DMG, FOR PARTS VALUE ONLY, Hole Cut in Engine Block, MV907A TO BE GIVEN, Oil	ID 005645 OD 115777
40	QTY - 1	00 International 470 Utility YW 6 cyl (Diesel) VIN: 1HTSLAAM3YH313941; Defects: FOR PARTS VALUE ONLY, Hole Cut in Engine Block, MV907A TO BE GIVEN, Rust	ID UNKN OD 209990
41	QTY - 1	05 Everest 12BLA39 12 ft. LH Wing Defects: Worn Pins and Bushings, Rust (with 22-40-0074-E, 22-40-0119-E and Truck)	ID 22400120E
42	QTY - 1	Lot of Energy Absorption System Hardware	ID 21401090R
43	QTY - 1	90 Alamo SHD88 88 in. Flail Mower Defects: Rust, Worn Bearings and Bushings	ID 20400331E

SALE NO. AU20220914001

LOT NO.		DESCRIPTION	
44	QTY - 1	90 Alamo SHD88 88 in. Flail Mower Defects: Rust, Dented Belt Cover, Worn Bearings and Bushings	ID 20400332E
45	QTY - 1	86 Jari C36 36 in. Sickle Bar Mower Defects: Levers, Tires and Loose Parts	ID 20401289E
46	QTY - 1	04 Snapper MRP216517B 21 in. Mower Defects: Cracked Deck	ID 21400516E
47	QTY - 1	85 Snapper 214XL 21 in. Push Mower Defects: Engine Brake and Flywheel	ID 21400347E
48	QTY - 1	94 Sarlo M522 21 in. Push Mower Defects: Engine Burning Oil	ID 21400346E
49	QTY - 1	89 Ing-Rand P250 WD Air Compressor (Hrs: 3375) Defects: Rust, Fender Hole, Compressor Oil Leak	ID 21400433E
50	QTY - 1	97 Ing-Rand 9250WJD Air Compressor (Hrs: 1596) Defects: Undercarriage Rust, Bent Frame, Roof Panel Rust, Oil Leaks and Doors	ID 21400929E
51	QTY - 1	Champion Air Compressor Model: VR5-8 (Parts Only) S/N R158189	
52	QTY - 1	Lot of Misc.Tires (Parts Only)	
53	QTY - 1	Lot of Misc. Tires	ID 19400970R
54	QTY - 1	Lot of (1) 07 Stihl MS260 16 in. Chain Saw and (1) 04 Stihl TS400 14 in. Cut Off Saw 07 Defects: Engine Crankcase Cracked and Egg Shaped Where Bolt That Holds Chain Brake Goes	ID 21400292E
55	QTY - 1	87 Lincoln K1292CV Welder (Hrs: 3954) Defects: Rust	ID 21401069E
56	QTY - 1	Lot of (2) Penn State Industries - DC 1HP Dust Collectors	ID 20400629X
57	QTY - 1	Lot of (3) Power Actuated Nail Guns Uniset-HG 100	ID 20400117X

SALE NO. AU20220914001

LOT NO.	DESCRIPTION		
58	QTY - 1	Air Products Welder (Parts Only)	
59	QTY - 1	Lot of Broken Tools (Parts Only)	
60	QTY - 1	Delta Table Saw (Parts Only)	
61	QTY - 1	Lot of (2) Tire Cages (Parts Only)	
62	QTY - 1	Lincoln Air Bumper Jack (Parts Only)	
63	QTY - 1	Hyd Power Unit (Parts Only)	
64	QTY - 1	Lot of Micellaneous Pallets (Parts Only)	
65	QTY - 1	John Dow Fuel Caddy (Parts Only)	
66	QTY - 1	Lot of (5) Fuel Tanks (Parts Only)	
67	QTY - 1	Lot of Misc. Implement Parts (Parts Only)	
68	QTY - 1	Lot of Misc. Parts (Parts Only)	
69	QTY - 1	Lot of Driveline Parts (Parts Only)	
70	QTY - 1	Lot of Miscellaneous Pest Control Products (20-40-0689-R, 20-40-0690-R)	
71	QTY - 1	Pelco EH2400 Enclosure Indoor Corner CCamera	ID 20401304X
72	QTY - 1	Lot of Snow Plow Parts (19-40-0935-R and 19-40-0966-R)	

SALE NO. AU20220914001

LOT NO.		DESCRIPTION	
73	QTY - 1	Lot of Mower Parts (19-40-0912-R and 19-40-0968-R)	
74	QTY - 1	Lot of Parts for Excavator	ID 19400910R
75	QTY - 1	96 Mercury 9.9ml 10 hp OB Motor Defects: Cracked Engine Case	ID 21401213E
76	QTY - 1	Dayton Floor Scrubber	ID 22400407D
77	QTY - 1	Lot of Miscellaneous Auto Filters (19-40-0971-R, 21-40-1141-R, 22-40-0075-R, 22-40-0264-R, 22-40-0511-R, 22-40-0569-R)	
78	QTY - 1	04 Viking PRRL1148FE 11 ft. Rev. Plow Defects: Lower Edge Bent, Rust, Worn Pins and Bushings	ID 22400207E
79	QTY - 1	04 Viking PRRL1148FE 11 ft. Rev. Plow Defects: Rust, Worn Pins and Bushings	ID 21400519E
80	QTY - 1	95 Frink 640SCK RH One Way Plow Defects: Worn Plow Shoes, Worn Pins and Bushings	ID 21400518E
81	QTY - 1	94 Viking 120HSE9 RH One Way Plow Defects: Worn Shoes, Hole in Plow, Worn Pins and Bushings	ID 21400517E
82	QTY - 1	06 Viking PRRL1036FE 10 ft. Rev. Defects: Worn Pins and Bushings, Rust	ID 21400457E
83	QTY - 1	95 Viking PRRL1036 10 ft. Rev. Plow Defects: Rust, Worn Pins and Bushings	ID 21400437E
84	QTY - 1	08 Viking 144WHD 12 ft. RH Wing Defects: Worn Pin and Bushings, Rear Wing Bent (with 22-40-0513-E and 22-40-0487-V)	ID 22400488E
85	QTY - 1	08 Viking 144WHD 12 ft. LH Wing Defects: Rear Wing Bent, Worn Pins and Bushings (with 22-40-0488-E and 22-40-0487-V)	ID 22400513E

SALE NO. AU20220914001

LOT NO.		DESCRIPTION	ID
86	QTY - 1	08 Viking 144WHD 12 ft. RH Wing Defects: Rear Corner Repaired, Bent Rear Wing, Worn Pins and Bushings (with 22-40-0456-E and 22-40-0454-V)	22400455E
87	QTY - 1	08 Viking 144WHD 12 ft. LH Wing Defects: Worn Pins and Bushings (with 22-40-0455-E and 22-40-0454-V)	22400456E
88	QTY - 1	04 Viking PRRL1148FE 11 ft. Rev Defects: Worn Pins and Bushings, Plow Lock	21400203E
89	QTY - 1	94 Viking P1036FE 10 ft. Rev Plow Defects: Worn Pins and Bushings, Rust, Right Top Corner Dented and Torn	20400487E
90	QTY - 1	95 Viking 144WHD 12 ft. RH Wing Defects: Four Patched Areas, Dented Top Rail	20400493E
91	QTY - 1	95 Hendelson 144WHD 12 ft. RH Wing Defects: Worn Pins and Bushings, Rust, Wing Corner Repaired	21400614E
92	QTY - 1	08 Viking 144WHD 12 ft. RH Wing Defects: Worn Pins and Bushings, Rust	21400564E
93	QTY - 1	04 Viking PRRL1148FE 11 ft. Rev. Plow Defects: Worn Pins and Bushings, Bow in Blade	21400545E
94	QTY - 1	10 Viking 144WHD 12 ft. Right Hand Wing Plow Defects: Worn Pin and Bushings, Right Corner of Wing Torn and Bent, Rust	20400524E
95	QTY - 1	Lot of Misc. Truck Parts (Parts Only)	
96	QTY - 1	Lot of Auto Parts	19400945R
97	QTY - 1	Lot of (12) Rims Steel Wheels on a Pallet	20400064X
98	QTY - 1	91 Sommers GA402M1C 3.5k Generator Defects: Tires and Chipped Paint	22400206E

SALE NO. AU20220914001

LOT NO.		DESCRIPTION	
99	QTY - 1	10 Traffix Truck Mounted Scorpion Attenuator TL3TMAB Defects: Broken and Bent Hinge Bracket and Cracked Cartridge Tube	ID 22400144E
100	QTY - 1	91 JD 770BH Grader YW Diesel/Biodiesel (Hrs: 6143) with Tire Chains on Pallet Defects: Chassis Rust, Tires, Worn Pins and Bushings, Plow Blade Cylinder Leaking S/N DW770BH533930	
101	QTY - 1	Lot of (1) 03 Gradall 48 in. Pavement Removal Bucket 0390-E, (1) 03 Gradall 28 in Excavating Bucket 0390-E, (1) 06 Gradall Ripper Tooth 0392-E, (1) 06 Gradall 15 in. Trenching Bucket 0393-E and (1) 06 Gradall 48 in. Excavating Bucket 0394-E	
102	QTY - 1	11 S 30335 4 kw Portable Generator B & S Defects: Engine runs, but generator is internally shorting out.	ID 21401037E
103	QTY - 1	98 Display Sol Sunray 345 VMS Defects: Rust and Undercarriage	ID 21401212E
104	QTY - 1	07 Vernac PCMS1500 Variable Message Board Defects: Frame Rust and Chassis	ID 21401211E
105	QTY - 1	07 Vernac PCMS1500 Variable Message Board Defects: Frame Rust and Chassis	ID 21401210E
106	QTY - 1	92 Troy-Bilt 8H Rototiller	ID 21401192E
107	QTY - 1	07 Vernac PCMS1500 Variable Message Board Defects: Rust, Screen Crack	ID 22400288E
108	QTY - 1	85 Onan 257D 25 kw Emerg. Generator (Hrs: 449)	ID 22400287E
109	QTY - 1	85 Onan 257D 25 kw Emerg. Generator (Hrs: 711)	ID 21400544E
110	QTY - 1	96 Hobart ARC5040D 400 amp Weld (Hours: 3337) Defects: Oil Leak	ID 20400784E
111	QTY - 1	07 Vernac PCMS1500 Variable Message Board Defects: Exterior Rust, Frame Rust, Rusted Battery Boxes	ID 21401140E

SALE NO. AU20220914001

LOT NO.		DESCRIPTION	ID
112	QTY - 1	86 Vermeer T600D Rock Cutter (Hrs: 3072) with (3) Skids of Parts Defects: Chassis Rust, Worn Pin and Bushings, Missing Pads on Track	21401071E
113	QTY - 1	11 Arrow Master WAAW15SB Arrow Board Defects: Undercarriage Rust, Solar Panel Frame	21400301E
114	QTY - 1	00 Arrow Master Arrow Board Defects: Solar Panel Frame Rust, Undercarriage and Under Battery Box	21400298E
115	QTY - 1	11 Arrow Master WAAW15SB Arrow Board Defects: Frame Rust, Undercarriage	21400297E
116	QTY - 1	11 Arrow Master WAAW15SB Arrow Board Defects: Frame Rust, Undercarriage	21400296E
117	QTY - 1	Attachment -06 Hydraulic Pump and Tank Go with Broom Defects: Worn Pins and Bushings, Rust Holes and Patches on Broom Shroud, Worn Side Dust Shields, Oil Leak at Hydraulic Tank Filter Housings	20400491E
118	QTY - 1	94 CH&E 4142 2 in. Port Pump Defects: Motor Seized	21400191E
119	QTY - 1	Bobcat 24 HYD Planer Attachment for Bob Cat Skid Steer Defects: Seized Up Teeth, Worn Pins and Bushings, Losing Power	19401506E
120	QTY - 1	08 EAS 8291 Impact Attenuator Defects: Compromised Segment, Frame Rust	20400477E
121	QTY - 1	03 Viking PRRL1036FE 10 ft. Rev Defects: Worn Pins, Bushings, Bent Plow Frame, Rust	20400478E
122	QTY - 1	06 Miller Big 40 Welder/Gen Defects: Paint Flaking Off Enclosure	20400100E
123	QTY - 1	02 Smith SSV10HC14 9y Spreader Defects: Rust, Brackets, Hyd. Pipes	22400074E
124	QTY - 1	05 Everest Brai 12 ft. RH Wing Defects: Rust, Worn Pins and Bushings (with 22-40-0074-E, 22-40-0120-E and 22-40-0118-V)	22400119E

SALE NO. AU20220914001

LOT NO.		DESCRIPTION	
125	QTY - 1	09 Case 621E Loader YW 4 cyl. (Hours: 4652) (No Reg. Doc.) Defects: Rust, Tires, A/C, Steering, Oil and Coolant Leaks, NO REG DOCS S/N N9F206964	ID 097045
126	QTY - 1	Gregory TTMA-100 S/N 4S93A2418DM089619	ID 139261
127	QTY - 1	Gregory TTMA-100 S/N 4S93A2410FH089108	ID 159087
128	QTY - 1	Vermac 1500C Message Machine S/N 2S9US4139CS132261	ID 128623
129	QTY - 1	Gregory TTMA-100 S/N 4S93A2413CM089509	ID 139217
130	QTY - 1	VERMACPCMS1500C Mesg Brd (Parts Only) S/N 2S9US41287S132006	ID 078513
131	QTY - 1	Safestop ATTN TMA9000 (Poor Condition) S/N 1E9TC19145A362312	ID 079043
132	QTY - 1	Safestop ATTN TMA9000 (Poor Condition) S/N 1E9TC19155A362299	ID 079045
133	QTY - 1	Libby MEP004A Generator S/N RZ20776	ID 779384
134	QTY - 1	Safestop ATTN TMA9000 (Poor Condition) S/N 1E9TC191X5A362554	ID 079238
135	QTY - 1	Safestop ATTN TMA9000 (Poor Condition) S/N 1E9TC19165A362552	ID 079240
136	QTY - 1	Safestop ATTN TMA9000 (Poor Condition) S/N 1E9TC19145A362551	ID 079241
137	QTY - 1	Safestop ATTN TMA9000 (Poor Condition) S/N 1E9TC19129A362036	ID 099007
138	QTY - 1	Case 621E Loader 2yd (Hours: 5795) S/N NAF208591	ID 107052
139	QTY - 1	Kohler 40ROZ261 Generator (Poor Condition) S/N 233399	ID 889524

SALE NO. AU20220914001

LOT NO.		DESCRIPTION	
140	QTY - 1	Lot of approx. (13) Arrow Boards (Parts Only)	
141	QTY - 1	Bush Hog Post Hole Digger Mod# PHD2103 (Parts Only) S/N 1204494	
142	QTY - 1	Bush Hog Rototiller Mod# RTH72 (Parts Only) S/N 1210621	
143	QTY - 1	HTC Tailgate Spreader Model# 1800 (Parts Only) S/N BH04689106	
144	QTY - 1	Lot of (7) Hose Reels With Piping (Parts Only)	
145	QTY - 1	Gregory TTMA-100 (Parts Only) S/N 4S93A2410FH089111	ID 159090
146	QTY - 1	01 JD 6410 AG Tractor Diesel/Biodiesel (Hr: 3810) Defects: Worn Pin and Bushings, Detached Front Grill, Dented Hydraulic Tank, Weak Cylinder in Motor, Low Power, Hydraulic Leak (with 20-40-0506-E & 20-40-0507-E) S/N L06410P305326	ID 20400506E
147	QTY - 1	Right & Left Mowers Defects: Left Wing Hyd. Leak, Bent Foor Guard, Worn Pins & Bushings, Rust (with 20-40-0507-E & 20-40-0495-E)	ID 20400506E
148	QTY - 1	01 Tiger Rear Flail Mower (with 20-40-0506-E & 20-40-0495-E)	ID 20400507E
149	QTY - 1	02 JD 6410 AG Tractor Diesel/Biodiesel (Hr: 5417) Defects: Dented Hydraulic Tank, Rust, Chipped Paint, Low Power Engine, Worn Pins and Bushings (with 20-40-0504-E & 20-40-0505-E)	ID 20400494E
150	QTY - 1	Right and Left Mowers Defects: Bent Foot Guards, Worn Pins & Bushing, Rust (with 20-40-0505-E & 20-40-0494-E)	ID 20400504E

SALE NO. AU20220914001

LOT NO.		DESCRIPTION	
151	QTY - 1	Rear Flail Mower Defects: Bent Foot Guards, Worn Pins & Bushings, Rust (with 20-40-0504-E & 20-40-0494-E)	ID 20400505E
152	QTY - 1	95 JD 755 Utility Tractor 3 pt Model: 755/AT60 (Hr: 3750) Defects: Engine Worn, Bad Cylinders, Low Power	ID 20400601E
153	QTY - 1	Woods Finishing Mower Attachment to 20-40-0601-E Defects: Worn Pins & Bushings, Bent Wheel Spindle Arm	ID 20400600E
154	QTY - 1	06 JD 310G Backhoe/Loader YW Diesel/Biodiesel (Hr: 4541) with Attachments Defects: Cab Rust, Worn Pin & Bushings Front Axle Pivot and Backhoe, Hydraulic Oil Leak (with lots 155, 156 & 157) S/N T0310GX960825	ID 21401191E
155	QTY - 1	06 John Deere 24 in. Backhoe Bucket Defects: Worn Bushings (with 21-40-1191-E, 21-40-1190-E and 21-40-1251-E)	ID 21401189E
156	QTY - 1	06 John Deere 48 in. Backhoe Bucket Defects: Worn Blade (with 21-40-1191-E, 21-40-1189-E and 21-40-1251-E)	ID 21401190E
157	QTY - 1	06 John Deere 12 in. Backhoe Bucket Defects: Worn Pins and Bushings (with 21-40-1189-E, 21-40-1190-E and 21-40-1191-E)	ID 21401251E
158	QTY - 1	Solartech Matrix Message S/N 4GM2M1513H1413924	ID 178505
159	QTY - 1	Hollingsworth MEP005A Generator S/N KZ05768	ID 859359
160	QTY - 1	Gregory TTMA-100 S/N 4S93A2417LH089277	ID 208561
161	QTY - 1	Kohler 40ROZ261 Generator S/N 235980	ID 889519
162	QTY - 1	LEROICENT Q375DJE Compressor S/N 3172X342	ID 938011

SALE NO. AU20220914001

LOT NO.		DESCRIPTION	ID
163	QTY - 1	LANDA VHM42002 Steam Cleaner S/N P03983041	989496
164	QTY - 1	Lot of (4) Sets of MOHAWK MP18-4-680 Mobile Column Lifts S/N PSKA2022	009700
165	QTY - 1	Mohawk TR-25A Drive on Lift S/N A2D194	029704
166	QTY - 1	ENRGY ABSORB TMA180 TRK MTD ATTN S/N 599062306	069036
167	QTY - 1	04 MSA 165T Flatbed Trailer YW Defects: Rust, Brakes S/N 1G9FS162X4B136199	048987
168	QTY - 1	03 Snowbear 610 Trailer BL Defects: Frame S/N 2SWUW11A23G094020	038017
169	QTY - 1	09 Spaulding RMV Roadsaver Trailer YW Defects: Rust, Frame, Brakes S/N 4S9PD19259M097558	098009
170	QTY - 1	12 Load Trail TD0224072 Tilt Trailer YW Defects: Rust S/N 4ZETD2423C1011559	
171	QTY - 1	92 Tigerline F3H708 Trailevator YW Defects: Hole in Frame, Broken Jack Handle, Rusted Box, Worn Pins and Bushings S/N 1T9ME1214NM199157	
172	QTY - 1	80 Magline F3-708 Trailevator YW Defects: Rusted Rear Side Bed, Floor Deck Holes, Rust, Cracked Fender S/N 14245N	

LEGEND

AT = AUTOMATIC TRANSMISSION
ST = STANDARD TRANSMISSION
PB = POWER BRAKES
PS = POWER STEERING
TMU = TRUE MILEAGE UNKNOWN

PW = POWER WINDOWS
AC = AIR CONDITIONING
CC = CRUISE CONTROL
R = RADIO

OD = MILEAGE INDICATED ON ODOMETER, INCLUDING EXCESS OF 100,000 IF KNOWN